

# How to Configure DP838xx for Ethernet Compliance Testing

David Ritter, Robert Rodrigues

#### **ABSTRACT**

This application report covers how to setup and configure the DP838xx PHY (using the customer EVM) for Ethernet Physical Layer Compliance (IEEE 802.3) testing as the device under test (DUT). This application note primarily uses DP83867 as an example, but any DP838xx can use these procedures for compliance testing.

Refer to *DP83822 IEEE 802.3u Compliance and Debug* (SNLA266) for a DP83822 specific Ethernet compliance procedure.

#### **Contents** 1 Standards and System Requirements ..... 1 1 1.2 Test Equipment Suppliers \_\_\_\_\_\_\_2 1.3 1.4 2 2.2 1000 BASE-T ...... 4 2.3 100 BASE-TX ..... 2.4 Appendix A Appendix B Appendix C List of Figures 1 2 3 4 DP83867 10 BASE-Te Configuration 9 5 6 7 8 10 11 12 13 **List of Tables** 1



## 1 Standards and System Requirements

#### 1.1 Standards

The following standards serve as references for the tests described in this document.

- Subclause 14.3.1 of IEEE standard 802.3-2002
- Subclause 40.6 IEEE standard 802.3-2002
- ANSI X3.263-1995

# 1.2 Test Equipment Suppliers

The different test equipment used to perform the various procedures described in this document can be procured from the following suppliers. Obtaining some of this equipment may require going through an agent.

- Tektronix
- Spirent
- Agilent (Keysight)
- · Rohde and Schwarz
- Teledyne LeCroy

# 1.3 Test System Requirements

For testing an Ethernet PHY for both MII and MDI transmission, the following hardware and software are required:

- Oscilloscope with Ethernet physical layer compliance software (for example, Tektronix TDSET3)
- Ethernet compliance test fixture
- Link partner or packet generator (for example, Spirent SmartBits/Test Center)\*
- TI USB-2-MDIO tool with PC (for alternative MDIO access)\*
- DC power supply
- Necessary cables and probes
- Thermal stream or oven\*
- \* [Not required for all tests or test setups.]

# 1.4 Software Setup and Installation

Consult the test equipment OEM's Ethernet compliance software manual for help with compliance software installation.

For alternative MDIO access through MSP430 Launchpad, see the USB-2-MDIO User's Guide. Link to USB-2-MDIO tool page: http://www.ti.com/tool/USB-2-MDIO



## 2 Ethernet Physical Layer Compliance Testing

#### 2.1 Standard Test Setup and Procedures

For Ethernet physical layer compliance testing, the PHY is managed through the serial management interface (SMI – also know as MDIO interface) to determine the test mode. The testing results are determined and recorded by the oscilloscope's Ethernet compliance software (for example, Tektronix's TDSET3).

The variation between Ethernet physical layer compliance tests is primarily the test mode of the PHY (configured by setting the internal PHY registers through SMI) and the connection on the test fixture (see Appendix A).

- Step 1. Connect the EVM to the 5-V DC jack (2.1-mm barrel plug) DC supply. For other external power supply options, see the *DP83867EVM User's Guide* (SNLU176) or *DP83867ERGZ EVM User's Guide* (SNLU190).
- Step 2. Connect the EVM to the test fixture according to setup outlined in the test fixture or software manual (see Figure 1). Identify if a link partner (packet generator) is needed for the test, and connect accordingly.
- Step 3. Set the thermal stream or oven to desired temperature (if applicable).
- Step 4. Configure the PHY's MDIO registers for the specific test. The SMI (MDIO interface) can be managed with TI's USB-2-MDIO tool through an MSP430 Launchpad (see the USB-2-MDIO tool for more info). The register configuration is outlined in Appendix B.
- Step 5. Start and configure the oscilloscope's Ethernet testing software (see the software user's manual).
- Step 6. Run the test and store the results (using the Ethernet compliance testing software).
- Step 7. Determine if the test has passed or failed according to IEEE standards.
- Step 8. Change test parameters or test channel and repeat.




Figure 1. DP83867 EVM Connected to Testing Fixture Through CAT5 Cable



#### 2.2 1000 BASE-T

Refer to Appendix B for 1000 BASE-T register writes.

Refer to Appendix C for Test Mode waveform oscilloscope captures.

#### 2.2.1 **Template (Test Mode 1)**

Purpose: To ensure that the PHY transmit waveforms fit into the IEEE-defined templates.

Pass Condition: Voltage output waveforms fit into IEEE-defined templates with PHY in Test Mode 1 after normalization.

Specific Test Setup: Verify the correct test fixture connections. Configure PHY to output Test Mode 1 by setting MDIO registers according to 1000 Base Test Mode 1 in Appendix B. Note that some Ethernet compliance software can run Template and Peak Voltage Tests simultaneously.

#### 2.2.2 Peak Voltage (Test Mode 1)

**Purpose:** To ensure correct PHY transmitter output voltage levels.

Pass Condition: Voltage Levels are to be within:

|Peak Voltage B| - |Peak Voltage A| < 1%

|Peak Voltage C| < 2% of 0.5 x ( |Peak Voltage B| + |Peak Voltage A| ) / 2

|Peak Voltage D| < 2% of 0.5 x ( |Peak Voltage B| + |Peak Voltage A| ) / 2

Specific Test Setup: Verify the correct test fixture connections. Configure PHY to output Test Mode 1 by setting MDIO registers according to 1000 Base Test Mode 1 in Appendix B. Note that some Ethernet compliance software can run Template and Peak Voltage Tests simultaneously.

#### 2.2.3 **Droop (Test Mode 1)**

Purpose: To ensure that the transmitter output voltage does not decay faster than specified in IEEE 802.3.

Pass Condition: The magnitude of the voltage at 500 ns after point F and H should greater than 73.1% of the magnitude of points F and H, respectively.

Specific Test Setup: Verify the correct test fixture connections. Configure PHY to output Test Mode 1 by setting MDIO registers according to 1000 Base Test Mode 1 in Appendix B.

#### 2.2.4 **Jitter Master Unfiltered (Test Mode 2)**

Purpose: To ensure that the PHY TX\_TCLK Jitter with respect to an unjittered reference is within the specified bounds.

Pass Condition: The peak-to-peak value of the jittered waveform with respect to the unjittered reference should be less than 1.4 ns.

Specific Test Setup: Verify the correct test fixture connections. Configure PHY to output Test Mode 2 by setting MDIO registers according to 1000 Base Test Mode 2 in Appendix B.

NOTE: For DP83867 TX\_TCLK access, connect to pins 29 and 30 (TX\_TCLK and GND) on the EVM as seen Figure 2, and use 1000 Base Test Mode 2 with TX\_TCLK in Appendix B (see Figure 11 for TX\_TCLK waveform).






Figure 2. DP83867 EVM With CLK\_OUT Pins Marked for TX\_TCLK Access

#### 2.2.5 Jitter Slave Unfiltered (Test Mode 2 and 3)

Purpose: To ensure that the PHY TX TCLK Jitter with respect to an unjittered reference is within the specified bounds.

Pass Condition: The peak-to-peak value of the jittered waveform with respect to the unjittered reference should be less than 1.4 ns.

Specific Test Setup: Verify the correct test fixture connections. Configure PHY to output Test Mode 2 and then Test Mode 3 by setting MDIO registers according to 1000 Base Test Mode 2 and then 1000 Base Test Mode 3 in Appendix B.

NOTE: For DP83867 TX\_TCLK access, connect to pins 29 and 30 (TX\_TCLK and GND) on the EVM as seen Figure 2, and use 1000 Base Test Mode 3 with TX\_TCLK in Appendix B (see Figure 11 for TX\_TCLK waveform).

#### 2.2.6 **Distortion (Test Mode 4)**

**Purpose:** To ensure that the peak distortion is within the specified bounds.

Pass Condition: The peak distortion of the output differential signal should be less than 10 mV when sampled with TX\_TCLK for at least 60% of the Unit Interval (UI) for 2047 consecutive samples at an arbitrary phase.

Specific Test Setup: Verify the correct test fixture connections. Configure PHY to output Test Mode 4 by setting MDIO registers according to 1000 Base Test Mode 4 in Appendix B.

A disturbing signal of 2.7 Vpp at 20.8 MHz is required to pass Distortion test (please see Ethernet Compliance Software's Manual for setup).

Also, verify that the Ethernet Compliance software is adhering to the "at least 60% of Unit Interval (UI) for 10 mV", not 100% (for example, TDSET uses 100% of UI, so failures are seen even with compliant parts).

#### 2.2.7 Common-Mode Voltage (Test Mode 4)

Purpose: To ensure that the Common-Mode Voltage is within the specified bounds.

Pass Condition: The magnitude of the Common-Mode Voltage should be within 50 mVpp.

Specific Test Setup: Verify the correct test fixture connections. Configure PHY to output Test Mode 4 by setting MDIO registers according to 1000 Base Test Mode 4 in Appendix B.

Connect the DUT ground to test fixture ground for proper measurements (as outlined in IEEE 802.3 in Figure 3).






Figure 3. IEEE-Defined CM Voltage Test Setup

#### 2.2.8 Return Loss (Test Mode 4)

**Purpose:** To ensure that the return loss is above the specified attenuation.

Pass Condition: The reflection of any incident signal to the PHY must be attenuated:

≥16 dB over the frequency range of 1.0 MHz to 40 MHz

≥10 – 20log 10 (f /80) dB over the frequency range 40 MHz to 100 MHz (f in MHz)

**Specific Test Setup:** Verify the correct test fixture connections. Configure PHY to output Test Mode 4 by setting MDIO registers according to 1000 Base Test Mode 4 in Appendix B.

NOTE: A spectrum analyzer may be needed depending on Ethernet Compliance Software.

# 2.2.9 Common-Mode Noise Rejection

**Purpose:** Verify that the PHY's common-mode rejection ratio is within the specified bounds.

Pass Condition: See IEEE 802.3 40.6.1.3.3

**Specific Test Setup:** Special Testing setup is required for high voltage injection. Refer to the high voltage injection testing procedures (not included in this application note).

## 2.3 100 BASE-TX

Refer to Appendix B for 100 BASE-TX register writes. Use both MDI and MDIX configurations for all tests.

#### 2.3.1 Template (Active Output Interface)

Purpose: To ensure that the output fits the transmit template.

Pass Condition: Fit into the specified ANSI Active Output Interface template.

**Specific Test Setup:** Verify the correct test fixture connections. Configure PHY to output Test Mode 5 by setting MDIO registers according to 100 Base Standard MDI and 100 Base Standard MDIX in Appendix B.

#### 2.3.2 Differential Output Voltage

**Purpose:** To ensure the differential output voltage is within the specified bounds.

Pass Condition: The differential output voltage should be within a positive or negative 950-1050 mV.

**Specific Test Setup:** Verify the correct test fixture connections. Configure PHY to output Test Mode 5 by setting MDIO registers according to 100 Base Standard MDI and 100 Base Standard MDIX in Appendix B.



#### 2.3.3 Signal Amplitude Symmetry

Purpose: To ensure the Signal Amplitude Symmetry is within the specified bounds.

**Pass Condition:** The ratio of the positive peak to negative peak amplitudes should be within 2% or  $0.98 \le |+V_{OUT}| / |-V_{OUT}| \le 1.02$ 

**Specific Test Setup:** Verify the correct test fixture connections. Configure PHY to output Test Mode 5 by setting MDIO registers according to 100 Base Standard MDI and 100 Base Standard MDIX in Appendix B.

#### 2.3.4 Rise and Fall Time

**Purpose:** To ensure that the device rise and fall time are within the specified bounds.

**Pass Condition:** The rise and fall time (between 10% and 90% voltage levels for both positive and negative) should be between 3 ns and 5 ns. The maximum and minimum rise and fall times should be within 0.5 ns.

**Specific Test Setup:** Verify the correct test fixture connections. Configure PHY to output Test Mode 5 by setting MDIO registers according to 100 Base Standard MDI and 100 Base Standard MDIX in Appendix B.

#### 2.3.5 Waveform Overshoot

Purpose: To ensure that the waveform overshoot is below the specified bound.

**Pass Condition:** The overshoot (both positive and negative maximum voltage level on transition) should not exceed 5% over the steady state voltage level ( $V_{OUT}$ ).

**Specific Test Setup:** Verify the correct test fixture connections. Configure PHY to output Test Mode 5 by setting MDIO registers according to 100 Base Standard MDI and 100 Base Standard MDIX in Appendix B.

#### 2.3.6 **Jitter**

**Purpose:** To ensure that the transmit output jitter is within the specified bounds.

Pass Condition: The transmit output jitter should be less than 1.4 ns.

**Specific Test Setup:** Verify the correct test fixture connections. Configure PHY to output Test Mode 5 by setting MDIO registers according to 100 Base Standard MDI and 100 Base Standard MDIX in Appendix B.

#### 2.3.7 Duty Cycle Distortion

Purpose: To ensure that the duty cycle distortion is below the specified bound.

**Pass Condition:** The duty cycle distortion (defined as above and below 50% of Vout) should not exceed ±0.25 ns.

**Specific Test Setup:** Verify the correct test fixture connections. Configure PHY to output Test Mode 5 by setting MDIO registers according to 100 Base Standard MDI and 100 Base Standard MDIX in Appendix B.

#### 2.3.8 Return Loss

**Purpose:** To ensure that the return loss is above the specified attenuation.

Pass Condition: The reflection of any incident signal to the PHY must be attenuated:

≥16 dB over the frequency range of 2 MHz to 30 MHz

≥10 - 20log 10 (f /30) dB over the frequency range 30 MHz to 60 MHz (f in MHz)

≥10 dB over the frequency range 60 MHz to 80 MHz

**Specific Test Setup:** Verify the correct test fixture connections. Configure PHY to output Test Mode 5 by setting MDIO registers according to *100 Base Standard MDI* and *100 Base Standard MDIX* in Appendix B. Note: A spectrum analyzer may be needed depending on Ethernet Compliance Software.



#### 2.3.9 Common-Mode Rejection

Purpose: Verify that the PHY's common mode rejection ratio is within the specified bounds.

Pass Condition: See ANSI X3-263-1995 9.2.3

**Specific Test Setup:** Verify the correct test fixture connections. Configure PHY to output Test Mode 5 by setting MDIO registers according to 100 Base Standard MDI and 100 Base Standard MDIX in Appendix B.

NOTE: Some Ethernet compliance software does not include Common-Mode Rejection testing.

#### 2.4 10 BASE-T/10 BASE-Te

Refer to Appendix B for 10 BASE-T/10 BASE-Te register writes.

The DP83867 supports only 10 BASE-Te mode of operation. Verify the DUT supports the standard, and is operating in the proper mode, when performing compliance testing.

#### 2.4.1 Link Pulse

**Purpose:** To ensure that the link pulse waveform is within the specified bounds.

Pass Condition: The link pulse must fit into the IEEE-defined template.

**Specific Test Setup:** Verify the test fixture connections. Set MDIO registers according to *10 Base Link Pulse* in Appendix B.

#### 2.4.2 TP IDL

Purpose: To ensure that the transmitter functions properly after transitioning to an idle state.

**Pass Condition:** The transmitter TP\_IDL pulse must fit within the template for Load 1, 2, and 3 with and without the twisted pair model (TPM).

**Specific Test Setup:** Verify the test fixture connections including the packet generator as a link partner (generating random packets). Configure the PHY to be in reverse loopback mode by setting MDIO registers according to *10 Base Standard* in Appendix B.


# 2.4.3 MAU, Internal

Purpose: To ensure that the transmitter output equalization is within the specified bounds.

**Pass Condition:** The transmitter waveform should fit within the IEEE-defined template for all data sequences when terminated with a  $100-\Omega$  resistor.

**Specific Test Setup:** Verify the test fixture connections including the packet generator as a link partner (generating random packets). Configure the PHY to be in reverse loopback mode by setting MDIO registers according to *10 Base Standard* in Appendix B. See Figure 4 for DP83867 10 BASE-Te test bench configuration.





Copyright © 2017, Texas Instruments Incorporated

Figure 4. DP83867 10 BASE-Te Configuration

#### 2.4.4 Jitter With TPM

**Purpose:** To ensure that the jitter is within the specified bounds.

**Pass Condition:** The transmitter output jitter should be less than ±5.5 ns. Note: Failure with TPM does not necessarily mean noncompliance.

**Specific Test Setup:** Verify the test fixture connections including the packet generator as a link partner (generating random packets). Configure the PHY to be in reverse loopback mode by setting MDIO registers according to *10 Base Standard* in Appendix B. See Figure 4 for DP83867 10 BASE-Te test bench configuration.

#### 2.4.5 Jitter Without TPM

**Purpose:** To ensure that the jitter is within the specified bounds.

**Pass Condition:** The transmitter output jitter should be less than ±8.0 ns.

**Specific Test Setup:** Verify the test fixture connections including the packet generator as a link partner (generating random packets). Configure the PHY to be in reverse loopback mode by setting MDIO registers according to *10 Base Standard* in Appendix B. See Figure 4 for DP83867 10 BASE-Te test bench configuration.

#### 2.4.6 Differential Voltage

**Purpose:** To ensure that the differential voltage is within the specified bounds.

**Pass Condition:** The peak differential voltage should be between 2.2 V and 2.8 V when terminated with  $100-\Omega$  resistor for 10BASE-T. The peak differential voltage should be between 1.54 V and 1.96 V when terminated with  $100-\Omega$  resistor for 10BASE-Te.



References www.ti.com

**Specific Test Setup:** Verify the test fixture connections including the packet generator as a link partner (generating random packets). Configure the PHY to be in reverse loopback mode by setting MDIO registers according to *10 Base Standard* in Appendix B. See Figure 4 for DP83867 10 BASE-Te test bench configuration.

#### 2.4.7 Harmonic Content

Purpose: To ensure the harmonic content of the PHY is within the specified bounds.

Pass Condition: The Data Out circuit must drive all ones. All subsequent harmonics must be 27-dB below the fundamental.

**Specific Test Setup:** Verify the test fixture connections including the packet generator as a link partner (generating random packets). Configure the PHY to be in reverse loopback mode by setting MDIO registers according to *10 Base Standard* in Appendix B. See Figure 4 for DP83867 10 BASE-Te test bench configuration.

#### 2.4.8 Common-Mode Voltage

**Purpose:** To ensure the common-mode voltage is within the specified bounds.

Pass Condition: The magnitude of the common-mode voltage should be less than 50-mV peak.

**Specific Test Setup:** Verify the test fixture connections including the packet generator as a link partner (generating random packets). Configure the PHY to be in reverse loopback mode by setting MDIO registers according to *10 Base Standard* in Appendix B. See Figure 4 for DP83867 10 BASE-Te test bench configuration.

#### 2.4.9 Return Loss

**Purpose:** To ensure that the return loss is above the specified attenuation.

Pass Condition: The reflection of any incident signal to the PHY must be attenuated:

≥ 15 dB over the frequency range of 5.0 MHz to 10 MHz

**Specific Test Setup:** Two waveform inputs may be necessary depending on testing setup. Verify the test fixture connections including the packet generator as a link partner (generating random packets). Configure the PHY to be in reverse loopback mode by setting MDIO registers according to *10 Base Standard* in Appendix B. See Figure 4 for DP83867 10 BASE-Te test bench configuration.

### 2.4.10 Common-Mode Rejection

Purpose: Verify that the PHY's common-mode rejection ratio is within the specified bounds.

Pass Condition: See IEEE 802.3 14.3.1.2.6

**Specific Test Setup:** Refer to the high voltage injection testing procedures (not included in this app note). Set MDIO registers according to *10 Base Standard* in Appendix B.

#### 3 References

**TDSET3 Manual** 

http://www.tek.com/manual/tdset3-ethernet-test-compliance-software-printed-help-document

IEEE 802.3

ANSI X3.263-1995

DP83867E/IS/CS Robust, High Immunity, Small Form Factor 10/100/1000 Ethernet Phy (SNLS504) DP83867IR/CR High Immunity 10/100/1000 Ethernet Physical Layer Transceiver (SNLS484)



# Outline of Ethernet Compliance Tests for DP83867

Table 1 lists the Ethernet compliance tests for DP83867.

Table 1. Outline of Ethernet Compliance Tests for DP83867

TEST	TEST MODE	REGISTER CONFIGURATION (IN Appendix B)
1000 BASE-T		
Template	Test Mode 1	1000 Base Test Mode 1
Peak Voltage	Test Mode 1	1000 Base Test Mode 1
Droop	Test Mode 1	1000 Base Test Mode 1
Jitter Master Unfiltered	Test Mode 2	1000 Base Test Mode 2
Jitter Slave Unfiltered	Test Mode 2 and 3	1000 Base Test Mode 2/3
Distortion	Test Mode 4	1000 Base Test Mode 4
Common Mode Voltage	Test Mode 4	1000 Base Test Mode 4
Return Loss	Test Mode 4	1000 Base Test Mode 4
Common Mode Rejection	(Test Mode 4)	1000 Base Test Mode 4
100 BASE-TX		
Template	Test Mode 5	100 Base Standard MDI/MDIX
Differential Output Voltage	Test Mode 5	100 Base Standard MDI/MDIX
Signal Amplitude Symmetry	Test Mode 5	100 Base Standard MDI/MDIX
Rise and Fall Time	Test Mode 5	100 Base Standard MDI/MDIX
Waveform Overshoot	Test Mode 5	100 Base Standard MDI/MDIX
Jitter	Test Mode 5	100 Base Standard MDI/MDIX
Duty Cycle Distortion	Test Mode 5	100 Base Standard MDI/MDIX
Return Loss	Test Mode 5	100 Base Standard MDI/MDIX
Common Mode Rejection	Test Mode 5	100 Base Standard MDI/MDIX
10 BASE-T		
Link Pulse	See register writes	10 Base Link Pulse
TP_IDL	See register writes	10 Base Standard
MAU, Internal	See register writes	10 Base Standard
Jitter with TPM	See register writes	10 Base Standard
Jitter without TPM	See register writes	10 Base Standard
Differential Voltage	See register writes	10 Base Standard
Harmonic Content	See register writes	10 Base Standard
Common Mode Voltage	See register writes	10 Base Standard
Return Loss	See register writes	10 Base Standard
Common Mode Rejection	See register writes	10 Base Standard
	· · · · · · · · · · · · · · · · · · ·	



# Ethernet Compliance Testing MDIO Register Writes for DP83867

#### 1000 Base Test Mode 1:

Reg 0x001F = 0x8000 //reset PHY

Reg 0x0000 = 0x0140 //1000 Base-T Mode Reg 0x0010 = 0x5008 //forced MDI Mode Reg 0x0009 = 0x3B00 //Test Mode 1

Reg 0x0025 = 0x0480 //output test mode to all channels

Reg 0x01D5 = 0xF508

#### 1000 Base Test Mode 2:

Reg 0x001F = 0x8000 //reset PHY

Reg 0x0000 = 0x0140 //1000 Base-T Mode Reg 0x0010 = 0x5008 //forced MDI Mode Reg 0x0009 = 0x5B00 //Test Mode 2

Reg 0x0025 = 0x0480 //output test mode to all channels

#### 1000 Base Test Mode 2 with TX TCLK:

Reg 0x001F = 0x8000 //reset PHY

Reg 0x0000 = 0x0140 //1000 Base-T Mode Reg 0x0010 = 0x5008 //forced MDI Mode Reg 0x0009 = 0x5B00 //Test Mode 2

Reg 0x0025 = 0x0480 //output test mode to all channels

Reg 0x0170 = 0x81F //output clk a Reg 0x00C6 = 0x0010 //proprietary

#### 1000 Base Test Mode 3:

Reg 0x001F = 0x8000 //reset PHY

Reg 0x0000 = 0x0140 //1000 Base-T Mode Reg 0x0010 = 0x5008 //forced MDI Mode Reg 0x0009 = 0x7B00 //Test Mode 3

Reg 0x0025 = 0x0480 //output test mode to all channels

#### 1000 Base Test Mode 3 with TX TCLK:

Reg 0x001F = 0x8000 //reset PHY

Reg 0x0000 = 0x0140 //1000 Base-T Mode Reg 0x0010 = 0x5008 //forced MDI Mode



www.ti.com Appendix B

Reg 0x0009 = 0x7B00 //Test Mode 3

Reg 0x0025 = 0x0480 //output test mode to all channels

Reg 0x0170 = 0x81F //output clk Reg 0x00C6 = 0x0010 //proprietary

#### 1000 Base Test Mode 4:

Reg 0x001F = 0x8000 //reset PHY

//0460: Channel D

#### 100 Base Standard MDI (Test Mode 5):

Reg 0x001F = 0x8000 //reset PHY

Reg 0x0000 = 0x2100 //programs DUT to 100Base-TX Mode Reg 0x0010 = 0x5008 //programs DUT to Forced MDI Mode

Reg 0x0009 = 0xBB00 //Test Mode 5

Reg 0x0025 = 0x0480 //output test mode to all channels

#### 100 Base Standard MDIX (Test Mode 5):

Reg 0x001F = 0x8000 //reset PHY

Reg 0x0000 = 0x2100 //programs DUT to 100Base-TX Mode Reg 0x0010 = 0x5028 //programs DUT to Forced MDIX Mode

Reg 0x0009 = 0xBB00 //Test Mode 5

Reg 0x0025 = 0x0480 //output test mode to all channels

### 10 Base Link Pulse:

Reg 0x001F = 0x8000 //reset PHY

Reg 0x0000 = 0x0100 //programs DUT to 10Base-T/Te Mode Reg 0x0010 = 0x5008 //programs DUT to Forced MDI Mode

#### 10 Base Standard:

Reg 0x001F = 0x8000 //reset PHY

Reg 0x0000 = 0x0100 //programs DUT to 10Base-T/Te Mode
Reg 0x0010 = 0x5008 //programs DUT to Forced MDI Mode
Reg 0x0016 = 0x0020 //programs DUT to Phy Loop-Back



# PHY Test Mode Waveforms

This appendix illustrates the PHY test mode waveforms.




Figure 5. IEEE Test Mode 1 per Standard




Figure 6. DP83867 Test Mode 1 Output Waveform



www.ti.com Appendix C




Figure 7. IEEE Test Mode 2 and 3 per Standard




Figure 8. DP83867 Test Mode 2 and 3 Output Waveform



Appendix C www.ti.com




Figure 9. IEEE Test Mode 4 per Standard




Figure 10. DP83867 Test Mode 4 Output Waveform



www.ti.com Appendix C




Figure 11. DP83867 TX\_TCLK Output Waveform (EVM Pin 29 to GND)




Figure 12. DP83867 Scrambled Idles Output Waveform 100M (Test Mode 5)



Appendix C www.ti.com




Figure 13. DP83867 Link Pulse Output Waveform 10M



www.ti.com Revision History

# **Revision History**

NOTE: Page numbers for previous revisions may differ from page numbers in the current version.

Changes from Original (November 2015) to A Revision		
•	Added data sheet links to References	10
•	Updated registers in Appendix B	12

#### IMPORTANT NOTICE FOR TI DESIGN INFORMATION AND RESOURCES

Texas Instruments Incorporated ("TI") technical, application or other design advice, services or information, including, but not limited to, reference designs and materials relating to evaluation modules, (collectively, "TI Resources") are intended to assist designers who are developing applications that incorporate TI products; by downloading, accessing or using any particular TI Resource in any way, you (individually or, if you are acting on behalf of a company, your company) agree to use it solely for this purpose and subject to the terms of this Notice.

TI's provision of TI Resources does not expand or otherwise alter TI's applicable published warranties or warranty disclaimers for TI products, and no additional obligations or liabilities arise from TI providing such TI Resources. TI reserves the right to make corrections, enhancements, improvements and other changes to its TI Resources.

You understand and agree that you remain responsible for using your independent analysis, evaluation and judgment in designing your applications and that you have full and exclusive responsibility to assure the safety of your applications and compliance of your applications (and of all TI products used in or for your applications) with all applicable regulations, laws and other applicable requirements. You represent that, with respect to your applications, you have all the necessary expertise to create and implement safeguards that (1) anticipate dangerous consequences of failures, (2) monitor failures and their consequences, and (3) lessen the likelihood of failures that might cause harm and take appropriate actions. You agree that prior to using or distributing any applications that include TI products, you will thoroughly test such applications and the functionality of such TI products as used in such applications. TI has not conducted any testing other than that specifically described in the published documentation for a particular TI Resource.

You are authorized to use, copy and modify any individual TI Resource only in connection with the development of applications that include the TI product(s) identified in such TI Resource. NO OTHER LICENSE, EXPRESS OR IMPLIED, BY ESTOPPEL OR OTHERWISE TO ANY OTHER TI INTELLECTUAL PROPERTY RIGHT, AND NO LICENSE TO ANY TECHNOLOGY OR INTELLECTUAL PROPERTY RIGHT OF TI OR ANY THIRD PARTY IS GRANTED HEREIN, including but not limited to any patent right, copyright, mask work right, or other intellectual property right relating to any combination, machine, or process in which TI products or services are used. Information regarding or referencing third-party products or services does not constitute a license to use such products or services, or a warranty or endorsement thereof. Use of TI Resources may require a license from a third party under the patents or other intellectual property of TI.

TI RESOURCES ARE PROVIDED "AS IS" AND WITH ALL FAULTS. TI DISCLAIMS ALL OTHER WARRANTIES OR REPRESENTATIONS, EXPRESS OR IMPLIED, REGARDING TI RESOURCES OR USE THEREOF, INCLUDING BUT NOT LIMITED TO ACCURACY OR COMPLETENESS, TITLE, ANY EPIDEMIC FAILURE WARRANTY AND ANY IMPLIED WARRANTIES OF MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE, AND NON-INFRINGEMENT OF ANY THIRD PARTY INTELLECTUAL PROPERTY RIGHTS.

TI SHALL NOT BE LIABLE FOR AND SHALL NOT DEFEND OR INDEMNIFY YOU AGAINST ANY CLAIM, INCLUDING BUT NOT LIMITED TO ANY INFRINGEMENT CLAIM THAT RELATES TO OR IS BASED ON ANY COMBINATION OF PRODUCTS EVEN IF DESCRIBED IN TI RESOURCES OR OTHERWISE. IN NO EVENT SHALL TI BE LIABLE FOR ANY ACTUAL, DIRECT, SPECIAL, COLLATERAL, INDIRECT, PUNITIVE, INCIDENTAL, CONSEQUENTIAL OR EXEMPLARY DAMAGES IN CONNECTION WITH OR ARISING OUT OF TI RESOURCES OR USE THEREOF, AND REGARDLESS OF WHETHER TI HAS BEEN ADVISED OF THE POSSIBILITY OF SUCH DAMAGES.

You agree to fully indemnify TI and its representatives against any damages, costs, losses, and/or liabilities arising out of your non-compliance with the terms and provisions of this Notice.

This Notice applies to TI Resources. Additional terms apply to the use and purchase of certain types of materials, TI products and services. These include; without limitation, TI's standard terms for semiconductor products <a href="http://www.ti.com/sc/docs/stdterms.htm">http://www.ti.com/sc/docs/stdterms.htm</a>), evaluation modules, and samples (<a href="http://www.ti.com/sc/docs/sampterms.htm">http://www.ti.com/sc/docs/sampterms.htm</a>).

Mailing Address: Texas Instruments, Post Office Box 655303, Dallas, Texas 75265 Copyright © 2017, Texas Instruments Incorporated