Amphenol Aerospace High Speed Protocol Guide

Γ		2M Series 2M Series High Speed Micro D 38999 HD38999 MRC							
		ZIVI Series	2M Series High Speed	Micro D		HD38999	MINO		
	Ethernet 10Base-T	¹ €∷₃² 6-4	1 ² 4 ² 6-4	15 pin	9-35	9-9	∰ 9 pin		
	Gigabit Ethernet (1000Base-T)	7-10 7-10 7-10	7-10	15 pin	11-35	9-9	∰ 9 pin		
	10 Gigabit Ethernet (10GBase-T)	Not Suitable	7-10	25 pin	Not Suitable	Not Suitable	∰ 9 pin		
	USB 2.0	¹ €€€3 6-4	1000°3 6-4	15 pin	9-35	Not Suitable	∰ 9 pin		
0	USB 3.0	Not Suitable	7-10	25 pin	Not Suitable	Not Suitable	∰ 9 pin		
High Speed Protocol	DVI	10-26	10-26	37 pin	15-35	Not Suitable	19 pin		
High Sp	Display Port 1.0	Not Suitable	10-26	51 pin	Not Suitable	Not Suitable	Not Suitable		
	Display Port 1.2	Not Suitable	Not Suitable	51 pin	Not Suitable	Not Suitable	Not Suitable		
	SATA 1.0	Not Suitable	6 - 7	15 pin	9-5	Not Suitable	∰ 9 pin		
	SATA 2.0	Not Suitable	6 - 7	15 pin	Not Suitable	Not Suitable	∰ 9 pin		
	SATA 3.0	Not Suitable	6 - 7	21 pin	Not Suitable	Not Suitable	Not Suitable		
	НОМІ	Not Suitable	10-26	51 pin	Not Suitable	Not Suitable	19 pin		



Amphenol Aerospace High Speed Protocol Guide

	Amprierio: Aerospace might Speed Protocol Guide								
	Quadrax	Split Pair Quad	OCS	HDB3/HSB3	R-SATA				
Ethernet 10Base-T	9-5	9-5	13-53	40 pin, all rows	7 pin				
Gigabit Ethernet (1000Base-T)	17-52	17-52	13-53	40 pin, all rows	22 pin				
10 Gigabit Ethernet (10GBase-T)	17-52	© ^A ■ 17-52	(°) (°) 13-53	40 pin, 4 pair, row 1 and 2	22 pin				
USB 2.0	9-5	9-5	13-53	40 pin, all rows	7 pin				
	Not Suitable	© ^A ■ 17-52	13-53	40 pin, 3 pair, row 1	22 pin				
USB 3.0 DVI Display Bort 10	PO OF	PO GA B C C C C C C C C C C C C C C C C C C	Consult AAO	80 pin, 6 pair, row 1	Not Suitable				
O C D D Display Port 1.0	P S B C S B	Recent Property of the propert	Consult AAO	40 pin, 3 pair, row 1	Not Suitable				
Display Port 1.2	Not Suitable	PO S O C O D O C O C O C O C O C O C O C O C	Consult AAO	40 pin, 3 pair, row 1	Not Suitable				
SATA 1.0	9-5	9-5	13-53	40 pin, 3 pair, row 1	7 pin				
SATA 2.0	Not Suitable	9-5	13-53	40 pin, 3 pair, row 1	7 pin				
SATA 3.0	Not Suitable	9-5	13-53	40 pin, 3 pair, row 1	7 pin				
НДМІ	Not Suitable	POSOB OF DE	Consult AAO	80 pin, 6 pair, row 1	Not Suitable				

