

LMS8117A

GND

PWR_FLAG

C11 100n

GND

GND


C12 1000u/25V

GND

SEKCJA ZASILANIA


GND GND


+ C9 C10
PWR_FLAG 10u 100n



F2 T3 F3 SW4
T500mA TEZ₁4,0/D 230/7.5V T100mA SW_DPST

J5 Conn_01x02_Male





C17 100n

 \rightarrow