





Segment 1
Gain [mV]
500
400
300
200
100
90
80
70
60
1500
1600
1700
1800
1900
HV [V]
1T: no data
1B: no data
Segment 2
Gain [mV]
500
400
300
200
100
90
80
70
60
1500
1600
1700
1800
1900
HV [V]
2T: no data
2B: no data
Segment 3
Gain [mV]
500
400
300
200
100
90
80
70
60
50
1500
1600
1700
1800
1900
HV [V]
3T: Gain = 1.53e-16 HV^5.60
3B: Gain = 1.95e-12 HV^4.36
Segment 4
Gain [mV]
500
400
300
200
100
90
80
1500
1600
1700
1800
1900
HV [V]
4T: Gain = 1.89e-14 HV^4.95
4B: Gain = 6.85e-14 HV^4.78



Segment 5
Gain [mV]
500
400
300
200
1500
1600
1700
1800
1900
HV [V]
5T: Gain = 1.66e-15 HV^5.35
5B: Gain = 1.06e-13 HV^4.78


Segment 6
Gain [mV]
500
400
300
200
100
80
70
60
50
1500
1600
1700
1800
1900
HV [V]
6T: Gain = 2.27e-12 HV^4.31
6B: Gain = 4.44e-16 HV^5.39



Segment 7
Gain [mV]
500
400
300
200
100
90
80
70
60
1500
1600
1700
1800
1900
HV [V]
7T: Gain = 2.39e-10 HV^3.69
7B: Gain = 8.61e-15 HV^5.03


Segment 8
Gain [mV]
500
400
300
200
100
90
80
70
60
1500
1600
1700
1800
1900
HV [V]
8T: no data
8B: no data


Segment 9




Segment 10




Segment 11




Segment 12




Segment 13




Segment 14





Segment 15





Segment 16





Segment 17
Gain [mV]
500
400
300
200
100
90
80
1500
1600
1700
1800
1900
HV [V]
17T: Gain = 4.67e-11 HV^3.90
17B: Gain = 4.13e-10 HV^3.64


Segment 18
Gain [mV]
500
400
300
200
100
90
80
70
60
1500
1600
1700
1800
1900
HV [V]
18T: Gain = 6.12e-11 HV^3.83
18B: Gain = 5.74e-14 HV^4.77



Segment 19
Gain [mV]
500
400
300
200
100
90
80
70
60
1500
1600
1700
1800
1900
HV [V]
19T: Gain = 3.91e-11 HV^3.96
19B: Gain = 1.38e-15 HV^5.29


Segment 20
Gain [mV]
500
400
300
200
100
90
80
70
60
50
1500
1600
1700
1800
1900
HV [V]
20T: Gain = 8.46e-14 HV^4.75
20B: Gain = 2.20e-16 HV^5.56


Segment 21




Segment 22




Segment 23




Segment 24




Segment 25




Segment 26




Segment 27




Segment 28




Segment 29




Segment 30




Segment 31




Segment 32




Segment 33




Segment 34




Segment 35




Segment 36




Segment 37




Segment 38




Segment 39




Segment 40




Segment 41




Segment 42




Segment 43




Segment 44




Segment 45




Segment 46




Segment 47




Segment 48




Segment 49




Segment 50





Segment 51





Segment 52





Segment 53
Gain [mV]
500
400
300
200
100
70
60
50
40
30
1500
1600
1700
1800
1900
HV [V]
53T: Gain = 1.39e-13 HV^4.70
53B: Gain = 1.08e-19 HV^6.46


Segment 54
Gain [mV]
500
400
300
200
100
90
80
70
60
1500
1600
1700
1800
1900
HV [V]
54T: no data
54B: no data


Segment 55
Gain [mV]
500
400
300
200
100
90
80
70
1500
1600
1700
1800
1900
HV [V]
55T: Gain = 1.91e-12 HV^4.35
55B: Gain = 3.94e-15 HV^5.15


Segment 56
Gain [mV]
500
400
300
200
100
90
80
70
60
1500
1600
1700
1800
1900
HV [V]
56T: no data
56B: no data

Segment 57



Segment 58

