AutoCare Workshop - Repair Estimate

Date: 15-Mar-2024
Customer: Rajesh Kumar
Policy Reference: INSW/VEH/2024/001234
Vehicle: 2022 Honda City (MH-01-AB-1234)
Incident: Front collision damage

S.No	Description	Amount (INR)
1	Front bumper replacement	12,500
2	Headlight assembly (left)	8,200
3	Hood repair and painting	15,000
4	Radiator grille	3,500
5	Labor charges	6,000
6	Painting/refinishing	8,000
	TOTAL	**53,200**

Authorized Signatory & Workshop Stamp

SYNTHETIC DOCUMENT