AD 2. AERODROMES

VAID AD 2.1 AERODROME LOCATION INDICATOR AND NAME

VAID - DEVI AHILYA BAI HOLKAR AIRPORT, INDORE

VAID AD 2.2 AERODROME GEOGRAPHICAL AND ADMINISTRATIVE DATA

1	Aerodrome reference point coordinates and its site	224324N 0754820E MAG. BRG. 241.80 DEG 668M From physical extremity of RWY 25	
2	Direction and distance of aerodrome reference point from the center of the city or town which the aerodrome serves	276 DEG/6.5KM from Indore Railway Station	
3	Aerodrome elevation and reference temperature	1854 FT / 40.6 DEG C	
4	Magnetic variation, date of information and annual change	0.37 DEG W (2010) /0.033 DEG E	
5	Name of aerodrome operator, address, telephone, telefax, e-mail address, AFS address, website (if available)	Airport Director Airports Authority of India Devi Ahilyabai Holkar Airport, Indore -452005,	
		Telephone:	917312629455 919893289455
		Fax:	(91) 7312620278
		AFS:	VAIDYHYX
		Email:	apdindore@AAI.AERO
6	Types of traffic permitted (IFR/VFR)	IFR/VFR	
7	Remarks	1. Seasonal bird activity in Aerodrome and Approach path. Pilots to exercise caution. 2. Jackal activity in operational area. 3. Elevation in EGM08	

VAID AD 2.3 OPERATIONAL HOURS

1	Aerodrome Operator	MON-FRI 0400-1230 UTC (0930-1800 IST) Sat, Sun + Hol: NIL
2	Custom and immigration	As per Requirement
3	Health and sanitation	As ATS
4	AIS briefing office	As ATS
5	ATS reporting office (ARO)	As ATS
6	MET Briefing office	As ATS
7	Air Traffic Service	H24
8	Fuelling	As ATS
9	Handling	As ATS
10	Security	As ATS
11	De-icing	NIL
12	Remarks	1. The ATS approved hourly RWY TFC handling capacity is as follows: Max number of ARR and DEP -12 (the minimum spacing between two successive arrivals shall be more than five min) Max number of arrivals only - 06 Max number of departures only - 10 2. No non sked ops for VAID without positive CLR for LDG/PRKG due shortage of PRKG bays. FLT will be accepted only with 48 hrs prior coordination.

VAID AD 2.4 HANDLING SERVICES AND FACILITIES

1	Cargo-handling facilities	NIL
2	Fuel and Oil types	IOC: Jet A-1(ATF K50) AVGAS 100LL, Oil: Nil RIL: Jet A-1(ATF K50), Oil: Nil BPCL: Jet A-1(ATF K50), Oil: Nil
3	Fuelling facilities and capacity	IOC: 02 Bowsers 1) AR544 - 16,000 Litre, 11.6 Litre/Sec. 2) AR545 - 16,000 Litre, 11.6 Litre/Sec. RIL: 05 Bowsers – 04 (R012 & R013 & R039 & R046) - 11000 Litre, 13.3 Litre/Sec 01 (R095) - 16000 Litre, 16.6 Litre/Sec BPCL: 02 Bowsers 1) R84-15000 Litre, 25 Litre/Sec 2) R156-15000 Litre, 25 Litre/Sec
4	De-icing facilities	NIL
5	Hangar space for visiting aircraft	NIL
6	Repair facilities for visiting aircraft	NIL
7	Remarks	Mooring facility: NIL

VAID AD 2.5 PASSENGER FACILITIES

1	Hotel(s) at or in the vicinity of aerodrome	In the city
2	Restaurant(s) at or in the vicinity of aerodrome	At AD and in the city
3	Transportation possibilities	Buses, Taxis and Car hire from AD..
4	Medical Facilities	First AID at AD. Hospitals in the city.
5	Bank and post office at or in the vicinity of aerodrome	Banks: At AD. 1000-1600 IST Post office: 1 Km
6	Tourist office	MP Tourist counter Avbl. in arrival lounge
7	Remarks	NIL

VAID AD 2.6 RESCUE AND FIRE FIGHTING SERVICES

1	Aerodrome category for fire fighting	Within ATS HR: CAT-7
2	Rescue equipment	Available as per category
3	Capability for removal of disabled aircraft	1. The critical aircraft for the airport is A320. 2. Primary responsibility for removal of disabled aircraft rests with the concerned airline. 3. The airlines may contact 'Aerodrome Coordinator for Disabled Aircraft Removal Operations' for coordinating with the agencies having Disabled Aircraft Recovery Kit. 4. Contact Details of Aerodrome Coordinator for Disabled Aircraft Removal Operations: Airport Director Contact number: +91-731-2629455, +91-9893289455 Email-apdindore@aai.aero
4	Remarks	NIL

VAID AD 2.7 SEASONAL AVAILABILITY CLEARING

1	Type(s) of clearing equipment	NIL
2	Clearance priorities	NIL
3	Remarks	AD operational during all seasons. Jackal activity / seasonal bird activity.

VAID AD 2.8 APRONS, TAXIWAYS AND CHECK LOCATIONS/POSITIONS DATA

1	Designation, surface and strength of aprons	Refer Aircraft Parking/Docking Chart
2	Designation, width, surface and strength of taxiways	Refer Aircraft Parking/Docking Chart
3	Location and elevation of altimeter checkpoints	TWY B: 1839 FT TWY C: 1841 FT TWY D: 1846 FT
4	Location of VOR checkpoints	TWY B: 224333.46 N 0754831.27E/ELEV 1839 FT TWY C: 224331.93 N 0754827.66E /ELEV 1841FT TWY D: 224328.32 N 0754819.14E /ELEV 1846FT
5	Position of INS checkpoints	NIL

6	Remarks	**1. DIMENSION OF APRON:** i. **APRON A** a) Stand No. 1 to 7: 290 X 150 M b) Stand No. 12 to 16: 214 X 37 M ii. **APRON B** a) Stand No. 8 to 11: 183 X 110 M iii. **APRON C** a) Stand No. 17 to 19: 122 X 53.5 M b) Stand No. 20 to 26: 298 X 53.5 M **2.** The only TWY connected to flying club is designated as TWY E and is suitable only for Flying club ACFT. **3.** Taxilane H- It is intermediate part between Taxiway H1 and H3. **4. TAXI PROCEDURE** i. Lead in taxi lane D-D1 to stand number 1 to 7 or via C-D1 (to stand number 1 to 6) and via C (to stand number 7). ii. Lead in taxi lane B/C-A for stand number 8 to 11. iii. Lead out taxi lane D1 from stand number 1 to 5 to TWY C, lead out taxi lane C1 from stand number 6 to 7 to TWY C. iv. Lead out taxi lane B1 from stand number 8 to 11 to TWY B/A. v. Lead in Taxi Lane D1 to stand No. 12 to 16. vi. Lead out taxi lane D1 from stand number 12 to 16 to TWY C/D. vii. Taxi in/Out Taxi Lane H1/H/H3 to stand No.17 to 26. **5. ISOLATION BAY:** i. Dimension: 110 M X 120 M ii. Location: South west of aerodrome iii. Surface: Concrete, PCN: 62/R/B/W/T iv. Elevation: 1848 FT v. Coordinates: 224307.28130N 0754757.28748E vi. Lighting: Edge lights & Isolation bay flood lights vii. Critical aircraft: Boeing 767-400 (POWER IN POWER OUT) viii. Connecting taxiway: TWY F **6. COORDINATES OF RWY HOLDING POINT:** i. **TWY B:** 224333.16907N 0754831.33021E, ELEV: 1839 FT ii. **TWY C:** 224331.66068N 0754827.79343E ELEV:1841 FT iii. **TWY D:** 224327.98612N 0754819.30239E ELEV:1845FT iv. **TWY E:** 224332.63724N 0754845.50311E ELEV:1837 FT v. **TWY F:** 224310.13401N 0754753.05539E ELEV:1850 FT vi. **TWY G:** 224315.46873N 0754750.38184E ELEV:1853 FT **7. COORDINATES OF RWY & TWY INTERSECTION:** i. **TWY B:** 224330.41800N 0754832.51908E ELEV:1842 FT ii. **TWY C:** 224328.96655N 0754829.15382E ELEV:1844 FT iii. **TWY D:** 224325.29840N 0754820.64931E ELEV:1849 FT iv. **TWY E:** 224333.87659N 0754840.53827E ELEV:1839 FT v. **TWY F:** 224312.81534N 0754751.71086E ELEV:1849 FT vi. **TWY G:** 224312.61359N 0754751.70921E ELEV:1852 FT **8.** Apron C and Part Parallel Taxiway G are available for all weather operations. **9.** Vertical Reference System: EGM-08” **10. VVIP B777-300ER Bay 8A Details:** i. Dimension: 79.8 M X 89.0 M ii. Location: Northeast of aerodrome iii. Surface: Concrete, PCN: 62/R/B/W/T iv. Elevation: 1843.501FT v. Coord: 224339.72N 0754825.58E vi. Lighting: flood lights vii. Critical aircraft: Boeing-777-300ER (Power-in Power Out) viii. Connecting taxiway: TWY B AND C

VAID AD 2.9 SURFACE MOVEMENT GUIDANCE AND CONTROL SYSTEM AND MARKINGS

1	Use of aircraft stand identification signs, taxiway guidelines and visual docking/parking guidance system at aircraft stands	Taxiing guidance provided on RTF. Guidelines at Apron. Visual docking/parking guidance system available for parking stand no. 1 to 5. PBB is available for parking stand no. 1 to 5.
2	Runway and taxiway markings and lights	RWY Markings Designation, THR, TDZ, Centreline, Edge Lights Edge, End, THR TWY Marking Centreline, Holding Position, Edge. Lights Edge.
3	Stop bars (if any)	NIL
4	Remarks	Apron Marking: Apron Edge, Vehicular Lane, Wing Tip Clearance Marking Equipment Limit Line /Safety Clearance Line and Parking Stand Marking. Apron Lighting: All aprons (A, B, C) provided with apron flood lights (AFL), apron edge lights. Guard Lights have been provided at Runway-Taxiway Intersections at Taxiway B, C, D and G.

VAID AD 2.10 AERODROME OBSTACLES

In Approach/Take-off/Circling Area and at AD					
1	**2**	**3**	**4**	**5**	**6**
RWY/Area affected	Obstacle type	Coordinates	Elevation (EGM-08)	Marking/LGT	Remarks
25/TKOF 07/APCH	TREE	224255.2N 0754657.3E	1863 FT	NO	Tree
25/APCH 07/TKOF	OTHER	224339.5N 0754841.5E	1859 FT	NO	Mobile Road Traffic (Road Elev. 561.7 M + Traffic Ht. 5M)
25/APCH 07/TKOF	FENCE	224339.6N 0754841.6E	1848 FT	NO	Airport Boundary Wall with Fencing on Top
25/APCH 07/TKOF	POLE	224339.3N 0754841.5E	1848 FT	NO	Light Post
25/APCH 07/TKOF	FENCE	224338.7N 0754844.3E	1851 FT	NO	Airport Boundary Wall with Fencing on Top
25/APCH 07/TKOF	OTHER	224337.5N 0754848.9E	1860 FT	NO	Mobile Road Traffic (Road Elev. 562.0 M + Traffic Ht. 5M)
25/APCH 07/TKOF	OTHER	224334.4N 0754850.0E	1857 FT	NO	Mobile Road Traffic (Road Elev. 561.1 M + Traffic Ht. 5.0 M)
25/APCH 07/TKOF	BUILDING	224332.6N 0754848.4E	1868 FT	NO	MPFC Hangar

In Approach/Take-off/Circling Area and at AD					
1	**2**	**3**	**4**	**5**	**6**
RWY/Area affected	Obstacle type	Coordinates	Elevation (EGM-08)	Marking/LGT	Remarks
25/APCH 07/TKOF	BUILDING	224331.7N 0754848.0E	1863 FT	NO	Hangar
25/APCH 07/TKOF	TREE	224335.1N 0754859.7E	1903 FT	NO	Group of Tree
25/APCH 07/TKOF	TREE	224336.5N 0754853.4E	1866 FT	NO	Group of Tree
25/APCH 07/TKOF	OTHER	224344.9N 0754850.3E	1863 FT	NO	Mobile Road Traffic (Road Elev. 563.8 M + Traffic Ht. 5M)
25/APCH 07/TKOF	TREE	224338.8N 0754856.9E	1883 FT	NO	Group of Tree
25/APCH 07/TKOF	OTHER	224338.0N 0754856.2E	1865 FT	NO	Hoarding
25/APCH 07/TKOF	TREE	224337.1N 0754858.1E	1904 FT	NO	Group of Tree
25/APCH 07/TKOF	TREE	224339.9N 0754900.6E	1882 FT	NO	Group of Tree
25/APCH 07/TKOF	TREE	224343.6N 0754859.0E	1881 FT	NO	Group of Tree
25/APCH 07/TKOF	POLE	224346.0N 0754853.7E	1875 FT	NO	Electric Pole
25/APCH 07/TKOF	POLE	224346.4N 0754855.3E	1877 FT	NO	Electric Pole
25/APCH 07/TKOF	TREE	224347.7N 0754856.7E	1901 FT	NO	Group of Tree
25/APCH 07/TKOF	TREE	224340.1N 0754905.1E	1891 FT	NO	Group of Tree
25/APCH 07/TKOF	FENCE	224339.5N 0754841.8E	1851 FT	NO	Airport Boundary Wall with Fencing on Top
25/APCH 07/TKOF	POLE	224339.1N 0754842.2E	1848 FT	NO	Light Post
25/APCH 07/TKOF	POLE	224338.8N 0754842.9E	1848 FT	NO	Light Post
25/APCH 07/TKOF	FENCE	224339.1N 0754843.3E	1850 FT	NO	Airport Boundary Wall
25/APCH 07/TKOF	FENCE	224338.4N 0754845.4E	1851 FT	NO	Airport Boundary Wall with Fencing on Top
25/APCH 07/TKOF	POLE	224338.0N 0754845.6E	1848 FT	NO	Light Post
25/APCH 07/TKOF	FENCE	224338.2N 0754846.6E	1852 FT	NO	Airport Boundary Wall with Fencing on Top
25/APCH 07/TKOF	BUILDING	224332.9N 0754849.5E	1863 FT	NO	Security Hut
25/APCH 07/TKOF	TREE	224333.3N 0754849.7E	1875 FT	NO	Group of Tree
25/APCH 07/TKOF	OTHER	224336.5N 0754849.8E	1855 FT	NO	Mobile Road Traffic (Road Elev. 560.5 M + Traffic Ht. 5.0 M)

In Approach/Take-off/Circling Area and at AD					
1	**2**	**3**	**4**	**5**	**6**
RWY/Area affected	Obstacle type	Coordinates	Elevation (EGM-08)	Marking/LGT	Remarks
25/APCH 07/TKOF	TREE	224335.6N 0754851.0E	1871 FT	NO	Group of Tree
25/APCH 07/TKOF	TREE	224332.9N 0754851.3E	1883 FT	NO	Group of Tree
25/APCH 07/TKOF	OTHER	224332.6N 0754848.6E	1870 FT	LGTD	Obstacle Light on MPFC Hangar
25/APCH 07/TKOF	BUILDING	224336.4N 0754859.8E	1875 FT	NO	Building
25/APCH 07/TKOF	POLE	224344.4N 0754853.3E	1876 FT	NO	Light Post
25/APCH 07/TKOF	OTHER	224344.8N 0754853.9E	1879 FT	NO	Flag on Hording
25/APCH 07/TKOF	OTHER	224346.6N 0754857.8E	1882 FT	NO	Hoarding
25/APCH 07/TKOF	OTHER	224338.7N 0754844.2E	1859 FT	NO	Mobile Road Traffic (Road Elev. 561.7 M + Traffic Ht. 5M)
In circling area and at AD	OTHER	224308.7N 0754732.8E	1875 FT	NO	WDI
In circling area and at AD	ANTENNA	224303.9N 0754720.4E	1875 FT	NO	MET Antenna (Arrester on MET Antenna Top 573.3m)
In circling area and at AD	BUILDING	224259.1N 0754710.4E	1848 FT	NO	Bird Chaser Hut
In circling area and at AD	OTHER	224326.8N 0754834.2E	1850 FT	NO	Arrester on GP Monitor Antenna
In circling area and at AD	BUILDING	224325.7N 0754831.5E	1847 FT	NO	GP Hut Corner
In circling area and at AD	OTHER	224325.7N 0754831.7E	1888 FT	NO	GP Main Antenna
In circling area and at AD	OTHER	224325.6N 0754831.7E	1850 FT	NO	GP DME Antenna
In circling area and at AD	OTHER	224334.7N 0754842.4E	1840 FT	NO	Approach Light
In circling area and at AD	TREE	224308.6N 0754724.5E	1889 FT	NO	Group of Tree
In circling area and at AD	BUILDING	224302.3N 0754711.8E	1864 FT	NO	Security Hut
In circling area and at AD	TREE	224257.6N 0754657.2E	1883 FT	NO	Group of Tree
In circling area and at AD	TREE	224247.6N 0754711.9E	1882 FT	NO	Group of Tree
In circling area and at AD	TREE	224256.2N 0754654.8E	1877 FT	NO	Group of Tree
In circling area and at AD	TREE	224256.6N 0754656.9E	1878 FT	NO	Group of Tree
In circling area and at AD	TREE	224259.9N 0754703.9E	1882 FT	NO	Group of Tree
In circling area and at AD	TREE	224301.1N 0754707.6E	1868 FT	NO	Group of Tree

In Approach/Take-off/Circling Area and at AD					
1	**2**	**3**	**4**	**5**	**6**
RWY/Area affected	Obstacle type	Coordinates	Elevation (EGM-08)	Marking/LGT	Remarks
In circling area and at AD	OTHER	224302.8N 0754716.1E	1852 FT	NO	Electric Panel
In circling area and at AD	BUILDING	224340.0N 0754833.6E	1897 FT	NO	Old ATC
In circling area and at AD	ANTENNA	224340.0N 0754833.6E	1916 FT	NO	Antenna on Old ATC
In circling area and at AD	ANTENNA	224340.0N 0754833.7E	1906 FT	NO	Antenna on Old ATC
In circling area and at AD	BUILDING	224339.0N 0754834.9E	1882 FT	NO	OLD Terminal Building
In circling area and at AD	BUILDING	224339.2N 0754837.3E	1862 FT	NO	Shed
In circling area and at AD	TREE	224339.5N 0754837.6E	1888 FT	NO	Group of Tree
In circling area and at AD	TREE	224339.3N 0754838.6E	1876 FT	NO	Group of Tree
In circling area and at AD	BUILDING	224339.7N 0754839.3E	1861 FT	NO	Security Hut
In circling area and at AD	TREE	224331.2N 0754847.8E	1887 FT	NO	Group of Tree
In circling area and at AD	TREE	224330.8N 0754848.3E	1869 FT	NO	Group of Tree
In circling area and at AD	BUILDING	224330.7N 0754847.6E	1867 FT	NO	Hangar
In circling area and at AD	TREE	224329.2N 0754851.9E	1919 FT	NO	Group of Tree
In circling area and at AD	TREE	224331.7N 0754851.3E	1885 FT	NO	Group of Tree
In circling area and at AD	TREE	224331.1N 0754857.1E	1906 FT	NO	Group of Tree
In circling area and at AD	TREE	224332.9N 0754902.0E	1935 FT	NO	Group of Tree
In circling area and at AD	TREE	224335.3N 0754903.8E	1915 FT	NO	Group of Tree
In circling area and at AD	OTHER	224350.7N 0754858.7E	1898 FT	NO	Cell Phone Mast on Building
In circling area and at AD	OTHER	224334.1N 0754829.2E	1861 FT	LGTD	Obstacle Light on Windsock
In circling area and at AD	ANTENNA	224339.8N 0754834.3E	1897 FT	NO	Antenna on Old Terminal Building
In circling area and at AD	TREE	224341.5N 0754835.9E	1907 FT	NO	Group of Tree
In circling area and at AD	TREE	224339.3N 0754838.3E	1879 FT	NO	Group of Tree
In circling area and at AD	POLE	224339.4N 0754838.5E	1869 FT	NO	Light Post
In circling area and at AD	FENCE	224339.2N 0754838.6E	1854 FT	NO	Airport Boundary Wall with Fencing on Top
In circling area and at AD	TREE	224340.4N 0754838.8E	1891 FT	NO	Group of Tree

In Approach/Take-off/Circling Area and at AD					
1	**2**	**3**	**4**	**5**	**6**
RWY/Area affected	Obstacle type	Coordinates	Elevation (EGM-08)	Marking/LGT	Remarks
In circling area and at AD	POLE	224339.5N 0754840.8E	1849 FT	NO	Light Post
In circling area and at AD	FENCE	224339.7N 0754841.1E	1850 FT	NO	Airport Boundary Wall
In circling area and at AD	BUILDING	224330.8N 0754850.9E	1873 FT	NO	Building
In circling area and at AD	TREE	224329.7N 0754852.9E	1908 FT	NO	Group of Tree
In circling area and at AD	OTHER	224331.7N 0754848.8E	1852 FT	NO	Group of Tree
In circling area and at AD	POLE	224338.4N 0754835.0E	1873 FT	NO	CCTV Pole
In circling area and at AD	OTHER	224340.9N 0754836.4E	1901 FT	NO	Mast
In circling area and at AD	TREE	224316.8N 0754742.8E	1907 FT	NO	Group of Tree
In circling area and at AD	ANTENNA	224333.5N 0754813.8E	1934 FT	NO	Antenna on ATC Building (FMVUF)
In circling area and at AD	OTHER	224333.5N 0754813.8E	1942 FT	NO	Arrester on ATC Building
In circling area and at AD	OTHER	224333.7N 0754813.8E	1929 FT	NO	Beacon
In circling area and at AD	TREE	224301.2N 0754745.6E	1911 FT	NO	Group of Tree
In circling area and at AD	ANTENNA	224333.5N 0754813.7E	1938 FT	NO	ADBS ANTENNA ON ATC
In circling area and at AD	ANTENNA	224333.7N 0754814.0E	1937 FT	NO	ADBS ANTENNA ON ATC
In circling area and at AD	OTHER	224355.0N 0754621.5E	2018 FT	NO	Cell Phone Mast
In circling area and at AD	OTHER	223844.2N 0754915.2E	2657 FT	NO	Mast
In circling area and at AD	OTHER	223559.8N 0755107.4E	2508 FT	NO	Hill TOP
In circling area and at AD	OTHER	224420.0N 0754730.8E	2006 FT	NO	Cell Phone Mast
In circling area and at AD	OTHER	224427.7N 0754736.1E	2051 FT	NO	Cell Phone Mast
In circling area and at AD	OTHER	224202.3N 0755243.2E	2423 FT	NO	TV Tower
In circling area and at AD	BUILDING	223845.6N 0755519.1E	2611 FT	NO	Building on Hill (Hill Top=782.4 M.)
In circling area and at AD	BUILDING	224011.0N 0755551.4E	2502 FT	NO	Temple on Hill (Hill Top=758.4 M.)
In circling area and at AD	OTHER	224426.5N 0754724.3E	2011 FT	NO	Cell Phone Mast

VAID AD 2.11 METEOROLOGICAL INFORMATION PROVIDED

1	Name of the associated meteorological office	Indore

2	Hours of service and, where applicable, the designation of the responsible meteorological office outside these hours	H24
3	Office responsible for preparation of TAFs and periods of validity and interval of issuance of the forecasts	Bhopal 9 and 24HR
4	Availability of the trend forecast for the aerodrome and interval of issuance	NIL
5	Information on how briefing and/or consultation is provided	On request within ATS HRS
6	Types of flight documentation supplied and language(s) used in flight documentation	Tabular Form English
7	Charts and other information displayed or available for briefing or consultation	Nil
8	Supplementary equipment available for providing information on meteorological conditions, e.g. weather radar and receiver for satellite images;	Nil
9	The air traffic services unit(s) provided with meteorological information	VAID Indore ATC and ACS
10	Additional information, e.g. concerning any limitation of service.	Documents provided as requested.

VAID AD 2.12 RUNWAY PHYSICAL CHARACTERISTICS

Designations	TRUE Bearings	Dimensions of RWY (M)	Strength of pavement (PCN) and associated data) and surface of runway and associated stopways	Geographical coordinates for threshold and runway end
1	2	3	4	5
07	65.06 DEG	2754 x 45 M	82/F/C/W/T Asphalt	THR: 224256.13N 0754713.04E RWY END: 224333.88N 0754840.54E
25	245.06 DEG	2754 x 45 M	82/F/C/W/T Asphalt	THR: 224333.88N 0754840.54E RWY END: 224256.13N 0754713.04E

THR elevation and highest elevation of TDZ of precision APP RWY	Slope of runway and associated stopway	Dimensions of stopway (M)	Dimensions of clearway (M)	Dimensions of strips (M)
6	7	8	9	10
THR: 1838.0FT TDZ: 1853.0FT	0.71%	NIL	NIL	2874 x 280 M
THR: 1839.0FT TDZ: 1847.0FT	0.71%	NIL	NIL	2874 x 280 M

Dimensions of runway end safety areas	Location and description of arresting system (if any)	Existence of an obstacle-free zone	Remarks.
11	12	13	14
90M x 90M		---	1. RWY PCN: From beginning of RWY 07 to 1707m: 82/F/C/W/T, From 1707m of RWY 07 to 2287m: 64/F/C/W/T From 2287m of RWY 07 to 2754m: 78/F/C/W/T 2. RWY Slope: From RWY 25 to RWY 07: 0.71% (Long), -1.5% (Trans.) 3. Vertical Datum: EGM08
90M x 90M		---	1. RWY PCN: From beginning of RWY 25 to 467m: 78/F/C/W/T From 467m of RWY 25 to 1047m: 64/F/C/W/T From 1047m of RWY to 2754m: 82/F/C/W/T 2. RWY Slope: From RWY 25 to RWY 07: 0.71% (Long), -1.5% (Trans.) 3. Vertical Datum: EGM08

VAID AD 2.13 DECLARED DISTANCES

RWY Designator	Take-off run available TORA (M)	Take-off distance available TODA (M)	Accelerate distance available ASDA (M)	Landing distance available LDA (M)	Remarks (including runway entry or start point where alternative reduced declared distances have been declared)
1	2	3	4	5	6
07	2754	2754	2754	2754	
25	2754	2754	2754	2754	

VAID AD 2.14 APPROACH AND RUNWAY LIGHTING

Runway Designator	Type, length and intensity of approach lighting system	Runway threshold lights, colour and wing bars	Type of visual slope indicator system	Length of runway touchdown zone lights
1	2	3	4	5
07	SALS 420 M LIH	Green	PAPI LEFT/3.00 DEG MEHT (50.62)	
25	SALS 420 M LIH	Green	PAPI LEFT/3.00 DEG MEHT (49.82)	

Length, spacing, colour and intensity of runway centre line lights	Length, spacing, colour and intensity of runway edge lights	Colour of runway end lights and wing bars	Length and colour of stopway lights	Remarks
6	7	8	9	10
	2754 M 60 M White LIH	Red		(i) Cross bar: 300M from Threshold. (ii) Distance of PAPI from THR 07: 278.7M (iii) Type of SALS fittings: Elevated spherical. (iv) RWY LGT AVBL with 2 ALT circuits
	2754 M 60 M White LIH	Red		i. Cross Bar: 300M from Threshold. ii. Distance of PAPI from THR 25: 298M iii. RWY LGT AVBL with 2 ALT circuits.

VAID AD 2.15 OTHER LIGHTING, SECONDARY POWER SUPPLY

1	Location, characteristics and hours of operation of aerodrome beacon/identification beacon (if any)	ABN	At Tower Building, FLG W&G EV2SEC. As ATS HR.
		IBN	Nil
2	Location and lighting (if any) of anemometer/ landing direction indicator;	LDI	Available
		Anemometer	North of ATC.Lighted
3	Taxiway edge and taxiway centre line lights;	Edge	All TWY
		Centre Line	NIL
4	Secondary power supply including switch-over time;	Secondary Power supply to all lighting at AD. Switch-over time: RWY Light: 01 Sec. For Other lights: 15 Sec.	
5	Remarks	NIL	

VAID AD 2.16 HELICOPTER LANDING AREA

1	Geographical coordinates of the geometric centre of touchdown and lift-off (TLOF) or of each threshold of final approach and take-off (FATO) area	Not Established
2	TLOF and/or FATO area elevation:	Not Established
3	TLOF and FATO area dimensions to the nearest metre or foot, surface type, bearing strength and marking;	Not Established
4	True bearings of FATO;	Not Established
5	Declared distances available	Not Established
6	Approach and FATO lighting;	Not Established
7	Remarks	Not Established

VAID AD 2.17 AIR TRAFFIC SERVICE AIRSPACE

1	Airspace designation, geographical coordinates and lateral limits	CTR: Circular area centered on 224324N 0754820E within a 11NM radius.

2	Vertical limits	FL 75
3	Airspace classification	D
4	Call sign and language(s) of the air traffic services unit providing service;	Indore Tower / Indore Approach, English
5	Transition altitude	5000 FT
6	Hours of applicability	HO
7	Remarks	NIL

VAID AD 2.18 AIR TRAFFIC SERVICES COMMUNICATION FACILITIES

Service Designation	Call sign	Channel(s)	SATVOICE Number(s), if available
1	**2**	**3**	**4**
APP	Indore Approach	118.500 MHZ	
APP	Indore Approach	120.625 MHZ	
TWR	Indore Tower	118.500 MHZ	
TWR	Indore Tower	122.800 MHZ	
ATIS	Indore Information	127.600 MHZ	
ALRS	Emergency Frequency	121.500 MHZ	

Logon address, as appropriate	Hours of operation	Remarks
5	**6**	**7**
	0600 - 1200	Backup Frequency
	0600 - 1200	Main Frequency
	As ATS	Alternate Frequency
	As ATS	NIL
	As ATS	NIL
	As ATS	NIL

VAID AD 2.19 RADIO NAVIGATION AND LANDING AIDS

Type of aids, magnetic variation and type of supported operation for ILS/ MLS, basic GNSS, SBAS and GBAS, and for VOR/ILS/MLS station used for technical lineup of the aid	Identification	Frequency(ies), Channel number(s), Service provider, and reference path identifier(s) (RPI), as appropriate	Hours of operation, as appropriate;
1	**2**	**3**	**4**
LOC 25 CAT I	IIDR	110.900 MHz	HO
GP 25		330.800 MHz	HO
DME ILS 25	IIDR	CH46X	HO
DVOR/DME	IID	116.700 MHz CH114X	H24

Geographical coordinates of the position of the transmitting antenna	Elevation of transmitting antenna of DME/ elevation of GBAS reference point	Service volume radius from the GBAS reference point	Remarks
5	**6**	**7**	**8**
224243.3N 0754643.4E			
224325.7N 0754831.7E			3 DEG
224325.6N 0754831.7E	1850 FT		1. Collocated with GP 25 2. Vertical Datum: EGM 08
224238.2N 0754646.2E	1854 FT		

VAID AD 2.20 LOCAL AERODROME REGULATIONS

1. PUSHBACK AND TAXI PROCEDURES:

a. Apron-A (Stand no. 1 to 5 and 12 to 16)

i. Aircraft will be powered in taxi to stands via taxilane D1 and pushed back on taxilane D1 either facing east or west with exception of aircraft on stand 1 to be pushed back facing North/West for Runway 25/07.

ii. Aircraft can enter/vacate apron via taxiway G-D/C to stands/Runway in case of Runway 25 (or vice versa in case of Runway 07) or as instructed.

iii. Simultaneous push back from adjacent stands shall not be permitted.

iv. Simultaneous pushback from any stand shall be allowed only with all necessary precautions subject to separation and taxi procedure.

v. Startup while pushing back shall not be allowed.

b. Apron-A (Stand no. 6 to 7)

i. Aircraft will be powered in taxi to stands via taxilane D1 and taxi out via C1-C for Runway 25/07.

ii. Aircraft can enter/vacate apron via taxiway G-D/C to stands/Runway in case of Runway 25 (or vice versa in case of Runway 07) or as instructed.

c. Apron-B (Stand no. 8 to 11)

i. Aircraft will be powered in taxi to stands via taxiway C-A and make right turn and taxi out via taxilane B1, taxiway B to holding point rwy25/07 or as required.

ii. Aircraft can enter/vacate apron via taxiway C-A/B1-B to stands/Runway in case of Runway 25/07 or as instructed.

d. Apron-C (Stand no. 17 to 26)

i. Aircraft will be powered in taxi to stands via taxilane H and pushed back on taxilane H either facing east or west for Runway 25/07.

ii. Aircraft can enter/vacate Apron via Taxiway G-H1-H/H-H3-G-C to stands/Runway in case of Runway 25 (or vice versa in case of Runway 07) or as instructed.

e. Taxi Procedures for Stand NR. 8A:

i. Lead in via TWY B to Bay 8A

ii. Lead out via TWY C to holding point.

iii. Bay No. 06 to 11 and 12 will be kept vacant.

iv. Vehicular movement on service road adjacent to the bay 6-11 will not be allowed during taxi in and taxi out of the aircraft.

v. No aircraft will be allowed beyond position abeam to aircraft strand no. 03 towards Taxiway C during taxi of B777-300ER.

2. No Aircraft shall take lock turn/ pivotal turn on the Runway to avoid pavement damage.

VAID AD 2.21 NOISE ABATEMENT PROCEDURES

NIL

VAID AD 2.22 FLIGHT PROCEDURES

RADIO COMMUNICATION FAILURE PROCEDURES

1. INTRODUCTION
Radio communication failure procedures are described in ICAO's PANS- ATM (DOC 4444), Manual of Air Traffic Services Part-I and DGCA CAR Section 9, Series C, Part 1.

2. GENERAL:
2.1 Radio communication failure may occur due to:
a) Airborne Transmitter and/or Receiver Failure
b) Ground station Transmitter and/or Receiver Failure.
2.2 As soon as it is known to ATC that two-way communication has failed, the action shall be taken to ascertain whether the aircraft is able to receive transmissions from the air traffic control unit by requesting it to execute a specified manoeuvre or to transmit if possible, a specified signal in order to indicate acknowledgement.
2.3 All Transponder equipped aircraft experiencing Radio Communication Failure shall set transponder to Mode A/C code 7600 as soon as practicable.
(Note: This requirement of setting transponder to Mode A/C code 7600 in no way imposes any restriction on the pilot's decision to set transponder to Mode A/C code 7500 or 7700, whenever required).
2.4 Immediately after the detection of RCF, the aircraft shall attempt to establish communications with the appropriate air traffic control unit using all other available means. (Indore Tower- 122.8 MHz Main and 118.5 MHz Standby/ Indore Approach 120.625MHz / Bhopal Tower 118.05 MHz (adjacent unit)/ Nagpur control/ Airline's channel/ Emergency 121.5Mhz/ suitable HF frequency)
2.5 In addition, the aircraft shall keep watch for any instructions that may be issued by visual signals directed to aircraft from ground.
2.6 The pilot shall make blind transmission to ATC of all necessary reports and actions taken by the aircraft, e.g. descent, turn, joining hold, leaving for approach, FAF etc., irrespective of whether partial/complete RCF has been established or not.
2.7 Action shall be taken by Indore ATC to reach aircraft, which were under his control, via all available means, which may include Manpack VHF Set, relay through other aircrafts, through airlines' channel (company frequency or satphone, mobile/ cell phone, or pager on board), adjacent ATS unit etc. Action shall be taken to ascertain whether the aircraft is able to receive transmissions from the air traffic control unit by requesting it to execute specified manoeuvre which can be observed either visually (if the aircraft is visible to ATC) or Nagpur RADAR display (through Nagpur ACC). Further actions, as described hereunder, may be followed, as and when necessary.
2.8 If the aircraft can be observed from a control tower, ATC shall determine if the aircraft receiver is functioning by:
i) instructing the pilot to manoeuvre the aircraft in such a manner as to alternately raise and lower the wings in a rocking motion;
ii) if observed from a control tower by night, by instructing the pilot to flash the landing and navigation lights twice.
2.9 Aircraft experiencing radio communication failure shall be provided all required information necessary for the safe and efficient conduct of flight and landing clearance without expecting acknowledgment.
2.10 After landing at Indore Airport, Aircraft shall lookout for follow me jeep on nearest taxiway holding point and after sighting the Follow me Jeep, Aircraft shall follow the Follow Me Jeep for parking to the allotted bay. Upon sighting the marshaller, aircraft shall stop following "Follow me Jeep" and shall follow marshaller for parking.
2.11 When Indore ATC becomes aware of the RCF of the aircraft, the controller concerned shall accord priority for the RCF aircraft to land.
2.12 If the aircraft re-establishes communication or has landed the ATC unit shall inform all concerned units/ aerodromes along the route as per the flight plan including the alternate aerodrome.

3. ASSIGNED RUNWAY AND ITS AVAILABILITY FOR RCF AIRCRAFT
3.1 In case of an arriving aircraft experiencing RCF, when Runway for landing has already been advised to the aircraft by ATC, such runway shall be considered as the assigned runway. If an arriving aircraft has not been advised of any runway, Runway 25 shall be considered as assigned runway for such arrival.
3.2 In case of departures from Indore returning on account of RCF, the departure runway of such aircraft shall be considered as assigned runway for landing.
3.3 If Radio communication failure occurs after the final/interception turn, the aircraft may continue its approach to land on such Runway.
3.4 Runway lights and Approach lights in 'SWITCHED ON' position shall indicate the availability of such Runway for aircraft experiencing RCF.
3.5 In strong tail wind conditions for assigned Runway, aircraft experiencing RCF will carry out a missed approach on assigned runway and after following complete missed approach for such approach, aircraft will carry out either visual or Instrument approach procedure published for the opposite runway.

4. PROCEDURES FOR ARRIVALS
4.1 In case Radio Communication failure takes place after establishing final approach track,aircraft may continue the approach and land subject to visually sighting the runway or GO AROUND and carry out the missed approach procedure and join the VOR (116.7 MHz) IID Holding procedure climbing to and maintaining 4000 feet.
4.2 Except when descent clearance has already been received from ATC and acknowledged, pilot shall continue on ATS route cleared to IID maintaining filed flight plan level or level cleared by adjacent Area control unit (Nagpur ACC) and do not commence descent before 30 miles VOR (116.7 MHz) IID.
4.3 For aircraft whose flight plan route is UPMAV-IID and experiencing RCF shall follow UPMAV-MONPI-IID due VAD8.
4.4 After crossing 30 miles, the pilot shall descend to FL 080 to join the published hold over VOR (116.7 MHz) IID for the runway as mentioned in para 3 above.

4.5 Commence descent to 4000 feet in published Hold over VOR (116.7 MHz) IID at or as close as possible to, Expected Approach Time (EAT) last received and acknowledged; or if no Expected approach time (EAT) has been received and acknowledged, at or as close as possible to, Estimated time of arrival (ETA) resulting from the current flight plan.
4.6 Leave VOR (116.7 MHz) IID and carry out published ILS/VOR procedure for runway as mentioned in para 3.
4.7 Land, if possible, within 30 minutes after the estimated time of arrival (ETA) or the last acknowledged expected approach Time (EAT), whichever is later.

5. PROCEDURES FOR DEPARTURE

5.1 DEPARTURE INTENDING TO CONTINUE TO DESTINATION

5.1.1Any departing aircraft experiencing RCF and intending to continue to its filed Flight plan destination shall:
i)Continue ATS route as per filed flight plan, climbing to/maintaining cleared and acknowledged flight level, or minimum flight altitude if higher, for a period of 20 minutes following the aircraft's failure to report its position over compulsory reporting point and thereafter adjust level and speed in accordance with the filed flight plan to destination.
ii)When the aircraft is given clearance for offset from flight plan route without a specified limit, re-join the current flight plan route after passing 20 Mile from VOR (116.7 MHz) IID but not later than the next significant point, taking into consideration the applicable minimum flight altitude.

5.2 DEPARTURE INTENDING TO LAND BACK AT INDORE AIRPORT

5.2.1Any departing aircraft experiencing RCF after departure and intending to land back at Indore Airport, shall:
i)Maintain the last assigned level, or minimum flight altitude if higher, for a period of 10 minutes on the flight plan route or on offset radial as cleared in ATC clearance.
ii)After 10 minutes turn towards VOR (116.7 MHz) IID via the same flight plan route or radial as per departure clearance. On Reaching VOR (116.7 MHz) IID join hold as published.
iii)If required, jettison fuel, before joining hold IID taking all necessary precautions then join hold over VOR (116.7 MHz) IID.
iv)Commence descent in the hold to 4000 feet. Leave VOR (116.7 MHz) IID and carry out the published ILS/VOR Procedure for the runway as mentioned in para 3 above.

6. PROCEDURES FOR VFR TRAFFIC

6.1In case of a VFR flight experiencing RCF and does not intend to land at Indore airport:
i)It shall continue to fly in VMC, land at the nearest suitable aerodrome /helipad, and report its arrival by the most expeditious means to the Indore ATC.
6.2In case of a VFR flight experiencing RCF and intending to land at Indore airport:
i)Proceed according to the current flight plan route in VMC and maintain the altitude/level last assigned and acknowledged.
ii)Proceed between R330-R340 20D-25D or R130-R140 20D-25D of the Indore airfield subject to the arrival route and descent to 4000 ft AMSL.
iii)Maintaining 4000 ft AMSL proceed towards Indore airport passing 10 D descent to circuit altitude to join the traffic circuit (at Downwind leg) for the last acknowledged Runway or the Runway as per para 3 above.
iv) Carry out a complete standard aerodrome traffic circuit and land on the last acknowledged Runway or the Runway as per para 3.

7 VARIOUS SIGNALS USED BY ATCO DURING COMMUNICATION FAILURE

The various signals used by the ATCOs during communication failure are as follows.	**Aircraft in Flight**	**Aircraft on the ground**
Steady green	Cleared to land	Cleared for take-off
Steady red	Give way to other aircraft, continue circling	Stop
A series of green flashes	Return for landing* (*Clearances to land and to taxi will be given in due course.)	Cleared to taxi
Series of red flashes	Aerodrome is unsafe, do not land	Taxi clear of landing area in use
Series of white flashes	Land at this aerodrome and proceed to the apron*	Return to starting point on the aerodrome
Red pyrotechnic	Notwithstanding any previous instructions, do not land for the time being	
Flashing runway or taxiway lights	Vacate the runway and observe the tower for light signal	

VAID AD 2.23 ADDITIONAL INFORMATION

1. Installation of illuminated national flag on 30.5m high monumental flag pole.
   Coordinate of flag pole: 224340.9N0754812.6E Height of mast: 591.50M AMSL
2. Prior coordination required for parking stands.
3. Intermediate dumbbell is not suitable for operations.
4. Apron Edge, Vehicular Lane, Wing Tip Clearance marking, Equipment Limit Line / safety Clearance line and parking stand marking available.
5. Apron Flood Lights & edge lights available.
6. New extended Turnpad having PCN 61 F/C/W/T, RWY 07/25 and fillets of TWY B are suitable for B777-300ER.
7. Intersection Departure Distances (TORA) for RWY 07/25:

RWY	TAXIWAY	TORA (M)
25	**B**	**2511**
	C	**2396**
	D	**2129**
07	**F**	**1538**

8. Runway Turn Pads, capable of handling B777-300 ER type of aircraft, provided at both ends of Runway for Special Operations with prior permission.

LOW VISIBILITY PROCEDURES

1. BACKGROUND

1.1 Until the latest amendment dated 28.10.2022 of DGCA Civil Aviation Requirements (CAR) section 8, Series 'C', Part-I on All-Weather Operations, Low visibility procedures were required at aerodromes for the purpose of ensuring safe operations during Categories II and III approaches and/or low visibility take-offs (LVTO).

1.2 However, in latest amendment to CAR (issue Oct 2022), para 5.3, following provision regarding Low visibility procedures is added. "An operator shall not conduct take-off with RVR/visibility less than standard Category I conditions of 550m RVR/800 m visibility unless low visibility procedures are enforced".

1.3 This provision necessitated the need for low visibility procedures for accommodating/permitting departures in Visibility/ RVR less than 800M/550M even at such airports where there are no CAT II and CAT III operations.

1.4 As per provisions of Aerodrome Design and Operations CAR section 8, Series 'C', Part-I on All-Weather Operations and ICAO DOC 9365 take-off can be permitted until RVR not less than 400M. Further, as per Aerodrome Design and operations CAR para

9.8.7, Surface Movement Radar (SMR) need to be provided at an aerodrome intended for use in Runway Visual Range conditions less than a value of 350M. 1.5 Accordingly, Low visibility Procedures have been developed for Devi Ahilya Bai Holkar Airport, Indore to accommodate/permit departures in Visibility/RVR less than 800M/550M. As Indore Airport has Runway edge lights and Runway center line markings whereas Runway Centre line Lights and SMR are not available at Indore Airport, these procedures will be applicable for take-off from RWY 07 in VIS/RVR below 800M/550M but not less than 400M RVR.

2. DEFINITIONS

2.1 Low Visibility Procedures (LVP): Specific procedures applied at an aerodrome for the purpose of ensuring safe operations during Categories II and III approaches and/or low visibility take-offs.

Note: as per para 5.3 of CAR on All Weather Operations, an operator shall not conduct Take-off with RVR/Visibility less than standard CAT-I conditions of 550m RVR/800m Visibility unless low visibility procedures are enforced.

2.2 Manoeuvring Area: That part of an aerodrome to be used for the take-off, landing and taxiing of aircraft, excluding aprons.

2.3 Runway Visual Range: The range over which the pilot of an aircraft on the centreline of a runway can see the runway surface markings or the lights delineating the runway or identifying its centreline.

2.4 Aerodrome Operating Minima: The limits of usability of an aerodrome for:

a) take-off, expressed in terms of runway visual range and/or visibility and, if necessary, cloud conditions.

b) landing in 2D instrument approach operations, expressed in terms of visibility and/or runway visual range, minimum descent altitude/height (MDA/H) and, if necessary, cloud conditions; and

c) landing in 3D instrument approach operations, expressed in terms of visibility and/or runway visual range and decision altitude/height (DA/H) appropriate to the type and/or category of the operation.

2.5 Visibility: Visibility for aeronautical purposes is the greater of

a) The greatest distance at which a black object of suitable dimensions, situated near the ground, can be seen and recognized when observed against a bright background;

b) The greatest distance at which lights in the vicinity of 1,000 candelas can be seen and identified against an unlit background.

Note 1: The two distances have different values in the air of a given extinction coefficient, and the latter b) varies with the background illumination. The former a) is represented by the meteorological optical range (MOR).

Note 2: The definition applies to the observations of visibility in local routine and special reports, to the observations of prevailing and minimum visibility reported in METAR and SPECI, and to the observations of ground visibility.

3. ABBREVIATIONS

ADC: Aerodrome Control

ARFF: Airport Rescue and Fire Fighting Services

ATC: Air Traffic Control ATM: Air Traffic Management CFT: Crash Fire Tender

ATIS: Automatic Terminal Information Service

DG: Diesel Generating Set

LVP: Low Visibility Procedures

MET: Meteorology

RWY: Runway

RVR: Runway Visual Range SP: Safeguarding Procedures TDZ: Touchdown Zone

TWR SUP: Tower Supervisor

TWY: Taxiway

WSO: Watch Supervisory Officer

4. GENERAL

4.1 The Low Visibility Procedure (LVP) incorporates safeguarding measures to mitigate runway incursions and defines operational restrictions to ensure safe Airside Operations considering the available Aerodrome facilities.

5. MINIMUM REQUIREMENTS

5.1 The following Aeronautical Ground lights and RVR equipment shall be serviceable to the required standard to support Low Visibility Procedures.

a) Runway edge lights,

b) Runway end lights,

c) Real time TDZ RVR*.

d) Stand by Power supply to maintain switch over time of 1 Second for Runway Edge Lights and Runway End Lights. This requirement can be met with the help of DG Set and/or UPS.

Note: * Real time TDZ RVR is available only for RWY07, hence LVP is applicable for RWY07

5.2 RVR/Visibility for Take-off (Commercial Transport Aeroplanes) is as per Table 4, below:

Take-off RVR/Visibility	
Facilities	RVR/VIS1 Cat A, B, C & D
Adequate Visual reference2 (Day only)	500m
Runway edge lights or Runway Centre line markings3	400 m
Runway edge lights and Runway Centre line markings3	300 m
Runway edge lights and Runway Centre line lights	200 m*

Runway edge lights and Runway Centre line lights and relevant RVR information4	150 m*
High intensity Runway edge lights and Runway Centre line lights (spacing 15 m or less) and relevant RVR information4	125 m*
High intensity Runway edge lights and Runway Centre line lights (spacing 15 m or less), approved lateral guidance system and relevant RVR information4	75 m*
**Operation Below 200 m Subject to availability of End RVR*	

Table 4 (RVR/Visibility for Take-off (Commercial Transport Aero planes)

Note-1: The TDZ RVR/VIS may be assessed by the pilot subject to Pilot fulfilling conditions set out in para 14, 15 & 16 of DGCA CAR Section 8 Series C Part –I Annexure- 2.

Note-1a: Pilot assessment of TDZ RVR is to be made only when the MID & ROLL OUT zone RVR are reported, and both these are not less than 200 m. (DGCA CAR Section 8 Series C Part –I Annexure 2 Para 17).

Note1b: An operator shall not conduct take-off with RVR/visibility less than standard Category I conditions of 550m RVR/ 800 m visibility unless low visibility procedures are enforced. (DGCA CAR Section 8 Series C, Part –I Para 5.3).

Note1c: Below 200 m all three RVR are required. The governing RVR shall be the lowest of the reported RVRs. (DGCA CAR Section 8 Series C Part –I Table 10: RVR/Visibility for take-off).

Note-2: Adequate Visual Reference means, that a pilot is able to continuously identify the take-off surface and maintain directional control.

Note-3: For night operations at least, Runway edge lights or centre line lights and Runway end lights are available

Note-4: The required RVR must be achieved for all relevant RVR reporting points (touchdown, mid-point and stop-end/ rollout). The governing RVR shall be the lowest of the reported RVRs.

Note-5: An operator shall not conduct low visibility take-offs in less than 400m RVR unless approved by DGCA.

Note-6: An operator shall not conduct take-off with visibility / RVR less than Category-I conditions unless low visibility procedures are enforced.

5.3 Unserviceability of Aeronautical Ground Lights/ Equipment before Implementation of Low Visibility Procedures will not be implemented when any of the light/equipment mentioned in para 4 above is un-serviceable or is not maintained as per the required standard.

Aeronautical Ground Lighting Facility	**Un-serviceability**	**Restrictions**
Runway Edge light	More than 15% of all lights are unserviceable	LVP operations will be suspended
	Any two consecutive lights or more are unserviceable	

Runway End lights	More than 15% of all lights are unserviceable LVP operations will be suspended	LVP operations will be suspended
	Any two consecutive lights or more are unserviceable	
Standby Generators/ UPS	Any of the generator/UPS is unserviceable	LVP operations will be suspended

5.4 Unserviceability of Aeronautical Ground Lights/ Equipment after Implementation of LVP When any of the light/ equipment mentioned in para 4 above becomes unserviceable or fails to meet the required standard during periods of LVP, TWR shall advise the aircraft accordingly and LVP shall be suspended and information to this effect shall be included in ATIS broadcast.

6. SAFEGUARDING PROCEDURES

Safeguarding Procedures (SP) are instructions for relevant airport departments to prepare ground services and facilities for low visibility operations in order that when LVP are implemented all safeguarding procedures are complete. Duty Officer Tower/Tower Supervisor will initiate and co-coordinate with all the concerned agencies for completion of safeguarding procedures before implementation of Low Visibility Procedures.

S. No	Safeguarding Process Steps	Detailed Activity steps	Responsibility
6.1	Condition for safeguarding procedure	a) The Visibility/ RVR is 1200m or less and visibility/RVR is forecast to deteriorate to 800m or less; and/or b) The cloud ceiling is less than 400ft and forecast to fall to 200ft or less.	MET/ ATC

6.2	**Safeguarding Procedure**	Safeguarding Procedures are the necessary actions to prepare the airport for Low Visibility Procedures. They include: a) Carry out Runway, Taxiway, Road Holding, emergency access road and Apron inspection to ensure serviceability of the visual aids and Ground Lights. b) Stop all maintenance works on the manoeuvring area and vacate all men, Material and equipment from the manoeuvring area. c) Termination of all work in progress in the localizer and glide path sensitive area. d) Removal of all equipment/material from localizer and glide path sensitive area. e) Restrictions on the movement of vehicles on the manoeuvring area and aprons. Limit number of vehicles on the manoeuvring area to bare minimum. To meet any inescapable operational needs, vehicle may be escorted by Follow Me under intimation to ATC. f) During LVP operations the fire approach road is reserved for positioning of CFT, Whereas at RWY Approach Road from beginning of RWY25 and RWY07, trained manpower (02 manpower ateach location) with manual lighting system will be deployed to prevent entry of any vehicle or person on the RWY. g) Ensuring availability of secondary power supply for change over, with switchover time of maximum 1 second for RWY Edge, RWY End and Threshold lights supported by UPS.	a) OPS/ ATC/ ARFF b) OPS c) CNS d) CNS e) ATC/ OPS/ Engg-Elect f) ATC/ OPS/ Engg-Elect g) Engg-Elect

		h) DATCO will co -coordinate with all the concerned agencies for implementation of Low Visibility Procedures. i) Airside Manager will inspect Movement area, and In-charge Powerhouse will inspect AGL System and Associated Roads with all the concerned section as per Check List **Note-1**: RWY Edge, Threshold lights and RWY End lights may continue to operate on main power supply during safeguarding Procedures. Whenever, LVP is to be implemented the RWY Edge, Threshold lights and RWY End lights shall be put on Standby Power Supply (DG set or UPS). This operation needs to be completed before LVP is implemented **Note-2:** As UPS is available at Indore Airport, Indore is capable of maintaining the required AGL system with one second of Switchover time, the main supply can continue to be the primary source of supply, and the Generator Supply can be kept as Standby Power supply. In case of UPS is unserviceable, Generator supply shall be the primary source of powersupply and Main power supply shall act as standby power supply.	h) DATCO i) OPS/ Engg Elect

6.3	Implementation of Safeguarding Procedure	a) When meteorological conditions meet the criteria for initiation of SP as stipulated in Sl. No. 6.1, the duty officer tower will inform Airside Manager, In-Charge Powerhouse Electrical, Engg-Civil, ARFF and MT. b) Positioning of one CFT each at the two predetermined positions one at TWY F and one at fire approach road NOTE: Action to be taken by various agencies is attached as Annexure-1. DATCO shall insure before implementation of SP check list must be completed. When all the concerned agencies have completed their necessary actions, they shall report to DUTY OFFICER TOWER (ATC) that their Safeguarding Procedure (SP) is completed, and the airport is safeguarded for LVP operations.	a) DATCO/ OPS/ Engg Civil/ Engg Elect/ ARFF/ MT b) ARFF

Note: As UPS is available at Indore Airport and is capable of maintaining the required AGL system (refer table under para 4.1) with one second of Switch Over time with Main Supply, the main supply can continue to be primary supply, and the Generator Supply can be kept as Standby Power supply. In case of UPS is unserviceable, Generator supply will become primary source of power supply and Main power supply shall act as standby power supply.

The appropriate Aeronautical ground lights must have been inspected during the hour preceding implementation of LVP, and thereafter once every two-hour period as mentioned below in para 6 (o). These lighting inspections should be accorded priority and, if necessary, aircraft operations may be delayed

7. LOW VISIBILITY PROCEDURES

S.No	**Safeguarding Process Steps**	**Detailed Activity steps**	**Responsibility**

7.1	Condition for Low Visibility Procedures	Low Visibility Procedures shall be implemented when – a) Visibility is less than 800 m; and/or Cloud ceiling is less than 200 ft.; AND b)Safeguarding Procedures (SP) have been completed, and the airport is safeguarded.	**DATCO**
7.2	Low Visibility Procedures (LVP)	a) Low Visibility Procedures are the actions to ensure the safe operation of aircraft during periods of reduced visibility or low cloud base. b) LVP shall only be implemented when Safeguarding Procedures (SP) has been completed and the airport is configured for low visibility operations. *Note-1: Though LVP is implemented when RVR is less than 800m, ILS CAT I operation will continue till Visibility /RVR is not less than 550m.* *Note-2: LVP procedures will be applicable for take-off in VIS/RVR below 800M/550M but not less than 400M RVR.* *Note: Duty Officer Tower shall stop LVP operations whenever RVR falls below 400M*	**DATCO**
7.3	Implementation of LVP	When meteorological conditions meet the criteria for LVP as stipulated in Sl. No 7.1, the Duty Officer Tower (ATC) will implement Low Visibility Procedure and following action shall be taken	

		a) ATC shall declare LVP in force, and intimate Airside Manager and ARFF.	a) DATCO
		b) The following should be included in ATIS. "LOW VISIBILITY PROCEDURES IN FORCE".	b) DATCO
		c) Positioning of one CFT each at the two predetermined positions one at TWY F and one at fire approach road.	c) ARFF
		d) TOWER-A on behalf of DATCO shall inform the concerned stake holders (ARFF, Airside Manager, MET, Engg-Civil, Engg. -Elect, MT and all Airlines/GHA) for enforcement of LVP.	d) OPS
		e) All maintenance works on apron shall be stopped. However, any maintenance work of urgent nature may be carried out under strict monitoring of Follow Me in coordination with ATC.	e) OPS
		f) All stake holder shall advice their staff that only operationally critical vehicles are permitted during LVP, additional vehicular movement shall be positively approved form ATC Tower.	f) OPS
		g) MT In-Charge shall in coordination with Airside Manger and ATC, to implement 'Mandatory Follow Me' service for all aircraft on apron, if the visibility conditions so demand.	g) ATC/ OPS
		h) No towing of aircraft shall be permitted during LVP. However, in case of urgent requirement, towing may be permitted under mandatory 'Follow Me' guidance.	h) ATC

		i) High Power Engine Ground Run (HPEGR) will not be permitted during LVP. If any HPEGR is already in progress, aircraft will be advised to stop engine run and proceed to allocated stand.	i) ATC
		j) If RVR equipment is unserviceable LVP will be withdrawn.	j) MET/ATC
		k) Suspend operations if RVR drops below 400 m.	k) ATC
		l) Additional Manpower deployment by MET if required.	l) MET
		m) TWR shall permit departures only from the beginning of the Runway 07.	m) DATCO
		n) Airside Manger shall be responsible for carrying out following actions: - Carry out inspection of manoeuvring and movement areas as part of Safeguarding Procedures. - Strictly restrict/regulate vehicular traffic on the manoeuvring area. - To ensure that all works within the manoeuvring area has been stopped.	n) OPS
		o) Ensure that Runway lights are inspected every 2 hours after implementation of LVP during its continuance.	o) Engg-Elect/ DATCO
		p) In-Charge Engg -Electrical or his/her representative will ensure that all AGL lights will be inspected logged in the attached format and reported to DATCO before every departure during LVP.	p) Engg-Elect/ DATCO
		q) In-Charge Engg-Electrical or his/her representative will ensure compliance to DGCA CAR section 4 series B part IV para 10.5.10. & 10.5.12 before every departure during LVP.	q) Engg-Elect/ DATCO

8. TERMINATION OF LOW VISIBILITY PROCEDURES

8.1 When Visibility/RVR improves to 800M/550 M or more and cloud ceiling is 200 feet or higher and trend is for improvement, Tower Supervisor/Duty Officer Tower would terminate operations of LVP. He may obtain advice from Duty Met. Officer regarding improvement in weather conditions before the termination of LVP. Tower Supervisor/Duty Officer shall inform ARFF/In-charge electrical-Engg. regarding the termination of LVP operations.

8.2 On cancelling of LVP, following message shall be included in two subsequent ATIS broadcasts. “LOW VISIBILITY PROCEDURES CANCELLED”.

8.3 If SP are implemented and LVP are not subsequently implemented and the visibility/RVR improves and is more than 1200 m and/or the cloud ceiling is 400ft or higher and both are forecast to remain above the required SP criteria, Tower Supervisor/Duty Officer Tower may cancel SP.

9. ACTIONS BY OTHER AGENCIES (AIRLINES, REFUELLING COMPANIES, CATERING AGENCIES, ETC.)

9.1 All agencies operating in the operational area shall ensure that minimum number of their vehicles, as are absolutely essential for aircraft operations, operate in the operational area. The drivers of these vehicles should keep a look out for taxing aircraft and other vehicles to prevent incident/ accidents.

9.2 All the vehicles must have their obstruction/ anti-collision lights “ON” during operation of low visibility procedures.

9.3 Follow all instructions/sign boards provided on vehicular movement area/ service roads.

9.4 No vehicle/equipment/personnel shall enter in and around the vicinity of the runways or taxi-tracks except with prior permission of aerodrome control tower.

VAID AD 2.24 CHARTS RELATED TO AN AERODROME

1. Aerodrome Chart
2. Aircraft Parking/ Docking Chart - Main Apron
3. Aircraft Parking/ Docking Chart - New Apron
4. Aerodrome Obstacle Chart Type-A (Operating Limitations) RWY 07/25 (03 October 2024)
5. Aerodrome Obstacle Chart Type - B (03 October 2024)
6. ILS (Z) Procedure RWY 25
7. VOR Procedure RWY 07(27 NOV 2025)
8. VOR Procedure RWY 25(9 JULY 2026)
9. RNP Y Procedure RWY 07
10. Coding Table - RNP Y Procedure RWY 07
11. RNP Y Procedure RWY 25(9 JULY 2026)
12. Coding Table - RNP Y Procedure RWY 25

VAID AD 2.25 VISUAL SEGMENT SURFACE (VSS) PENETRATION

Procedure	Procedure Minima	VSS Penetration
1	**2**	**3**