




PRODUCT 7680
PN 108845001x
NAME 108845001 BEARING TO CARRIAGE

PURPOSE: The purpose of this document is to provide instructions for assembling the printer's 108845001 Assembly.

RESPONSIBILITY: It is the responsibility of Pertech Management to maintain this documentation.

TOOLS: Fixture #51347

DRAWING and BOM PNs: 108845-001X



1. Raise the press arm.
2. Place 108845x Carriage over the mandrel.
3. Place 106815x bearing over the same mandrel.
4. Rotate the press arm to bring the press in contact with the bearing.
5. Align the bearing and the carriage.
6. Proceed to press bearing into the carriage until flush.
7. Remove any plastic shavings.