RTC Header QA Card

 $Individual\ RTC\ Header\ Inspection$

Board Number: 22	Technician: Krish flate
Checklist:	
Header orientation correct	
Placed in correct direction which faces inward towards the PCB. The PCB should sit on the	5 0
Soldered RTC header securely	
Header sits flush; joint fully connects pin and	pad
Even solder amount and shape	
Concave, shiny finish; no cold joints or solder	bridges
□ Visual inspection complete	
Check for solder bridges or incomplete joints	
Continuity test passed	
Place one multimeter probe on a pin and the ot Repeat this across all pairs of adjacent pins.	her on the adjacent pin to ensure no shorts.
Final Status: Passed	
Date: 05/04/2015	
Notes: Battery Still needs to be put to check	e full functionality.