RTC Header QA Card

 $Individual\ RTC\ Header\ Inspection$

Board Number: 24	Technician:	Krijeh Hate
Checklist:		
	should sit on the smaller header pins.	and the battery faces
Soldered RTC header secur	rely	
Header sits flush; joint fully c	connects pin and pad	
Even solder amount and sha	ape	
Concave, shiny finish; no cold	l joints or solder bridges	
□ Visual inspection complete		
Check for solder bridges or in	$a complete\ joints$	
☐ Continuity test passed		
Place one multimeter probe or Repeat this across all pairs of	n a pin and the other on the adjacent pin f adjacent pins.	to ensure no shorts.
Final Status: Passed - N	Needs Rework	
Date: 05/04/2028		
Notes: Buttery Still needs to be	e put to check full functionality	•