## RTC Header QA Card

 $Individual\ RTC\ Header\ Inspection$ 

| Board Number:   |
|---|
| Checklist:  |
| Header orientation correct  |
| Placed in correct direction which faces inward to the SD card module and the battery face towards the PCB. The PCB should sit on the smaller header pins. |
| Soldered RTC header securely  |
| Header sits flush; joint fully connects pin and pad   |
| Even solder amount and shape  |
| Concave, shiny finish; no cold joints or solder bridges   |
| □ Visual inspection complete  |
| Check for solder bridges or incomplete joints   |
| Continuity test passed  |
| Place one multimeter probe on a pin and the other on the adjacent pin to ensure no shorts Repeat this across all pairs of adjacent pins.                  |
| Final Status: Passed   Needs Rework   |
| Date: 05/04/2018  |
| Notes:<br>Battery Still needs to be put to check full functionality.  |