RTC Header QA Card

 $Individual\ RTC\ Header\ Inspection$

Board Number:	<u> </u>	Technician:	Krijeh Hate
Checklist:			
Header orientation corre	ect		
Placed in correct direction towards the PCB. The PC	· ·		and the battery faces
Soldered RTC header se	ecurely		
Header sits flush; joint fu	ly connects pin and pad	!	
Even solder amount and	l shape		
Concave, shiny finish; no	cold joints or solder bri	dges	
□ Visual inspection compl	ete		
Check for solder bridges o	r incomplete joints		
☐ Continuity test passed			
Place one multimeter prob Repeat this across all pair	-	on the adjacent pin	to ensure no shorts.
Final Status: Passed	□ Needs Rework		
Date: 05/04/2025			
Notes: Battery Still needs t	6e put to check	full functionality	r