RTC Header QA Card

 $Individual\ RTC\ Header\ Inspection$

Board Number:	To	echnician: Krijth ff	ate
Checklist:			
	ct		
	which faces inward to the SD of B should sit on the smaller hea		ttery faces
Soldered RTC header see	curely		
Header sits flush; joint full	y connects pin and pad		
Even solder amount and	shape		
Concave, shiny finish; no o	cold joints or solder bridges		
☐ Visual inspection completion.	ete		
Check for solder bridges or	$incomplete\ joints$		
☐ Continuity test passed			
Place one multimeter probe Repeat this across all pairs	on a pin and the other on the of adjacent pins.	adjacent pin to ensure	no shorts.
Final Status: Passed	Needs Rework		
Date: 05/05/2005			
Notes: Buttery Still needs to	be put to check full fur	nctionality.	