## RTC Header QA Card

 $Individual\ RTC\ Header\ Inspection$ 

Board Number: Technician: Krijth #	rte
Checklist:	
Header orientation correct	
Placed in correct direction which faces inward to the SD card module and the bat towards the PCB. The PCB should sit on the smaller header pins.	tery faces
Soldered RTC header securely	
Header sits flush; joint fully connects pin and pad	
Even solder amount and shape	
Concave, shiny finish; no cold joints or solder bridges	
□ Visual inspection complete	
Check for solder bridges or incomplete joints	
Continuity test passed	
Place one multimeter probe on a pin and the other on the adjacent pin to ensure Repeat this across all pairs of adjacent pins.	$no\ shorts.$
Final Status: Passed    Needs Rework	
Date: 05/04/2025	
Notes: Battery Still needs to be put to check full functionality.	