RTC Header QA Card

 $Individual\ RTC\ Header\ Inspection$

Board Number:	Technician: Krijen Hate
Checklist:	
Header orientation correct	
Placed in correct direction which faces inwards the PCB. The PCB should sit on the	rd to the SD card module and the battery faces se smaller header pins.
Soldered RTC header securely	
Header sits flush; joint fully connects pin an	ed pad
Even solder amount and shape	
Concave, shiny finish; no cold joints or sold	er bridges
□ Visual inspection complete	
Check for solder bridges or incomplete joint	S
Continuity test passed	
Place one multimeter probe on a pin and the Repeat this across all pairs of adjacent pins.	other on the adjacent pin to ensure no shorts.
Final Status: Passed	
Date: 05/04/2005	
Notes: Battery Still needs to be put to ch	ede ful functionality.