RTC Header QA Card

 $Individual\ RTC\ Header\ Inspection$

Board Number:	12	Technician:	Krijish Hate
Checklist:			
	tion correct		
	·	nward to the SD card module in the smaller header pins.	and the battery faces
Soldered RTC	header securely		
Header sits flush;	joint fully connects pi	n and pad	
☐ Even solder am	nount and shape		
Concave, shiny fi	nish; no cold joints or	solder bridges	
☐ Visual inspection ☐ Visu	on complete		
Check for solder	bridges or incomplete j	oints	
☐ Continuity test	passed		
	eter probe on a pin and s all pairs of adjacent p	the other on the adjacent pin ins.	to ensure no shorts.
Final Status: Pass	sed Needs Rewo	ork	
Date: 05/04/2025	-		
Notes: Battery Still	needs to be put to	check ful functionality	c