RTC Header QA Card

 $Individual\ RTC\ Header\ Inspection$

Board Number:	10	Technician: Krijth Hate
Checklist:		
	tion correct	
	•	s inward to the SD card module and the battery faces to on the smaller header pins.
Soldered RTC	header securely	
Header sits flush;	joint fully connects	pin and pad
☐ Even solder am	nount and shape	
Concave, shiny fi	nish; no cold joints	or solder bridges
☐ Visual inspection ☐ Visu	on complete	
Check for solder	bridges or incomplet	e joints
☐ Continuity test	passed	
	eter probe on a pin of all pairs of adjacen	and the other on the adjacent pin to ensure no shorts. at pins.
Final Status: Pass	sed 🗆 Needs Re	ework
Date: 05/04/2025		
Notes: Battery Still	needs to be put	to check full functionality.