

Startup support, sensor timing investigation and customer handover notes.

C-0001-P-002 · Remote Controls Support Retainer · Demo · 2026-08-18 · Alex Rivera

needs_changes

This report needs changes before it can be approved.

Update the fields below and submit it again. The owner and admin team can see exactly what changed.

Modify report

Changes are versioned and notify the owner/admin review group.

v3

Autosave is ready

Shift

Set the field date and the shift context for this source record.

Work date **Required**

18/08/2026



Site / shift

Body shop · first shift

Work performed

Record the work completed during this shift.

Shift summary **Required**

Startup support, sensor timing investigation and customer handover notes.

Tasks completed **Required**

Cleared timing faults and documented affected devices.

Issues / decisions

Capture problems, corrective action, customer decisions, and blockers.

Problems found

Two prox sensors showed inconsistent transition timing.

Corrective actions

Adjusted debounce parameters within the approved range.

Client decisions**Open items**

Monitor through afternoon production.

Downtime minutes

0

Standby reason

Blockers

Next steps

Leave the handover context needed for the next shift and review.

Next-day plan

Close issue after trend review.

Customer contact

Safety-related

☐

Cancel

Save changes and notify reviewers

Report summary

PROJECT

C-0001-P-002

Remote Controls Support Retainer · Demo

AUTHOR

Alex Rivera

worker@demo.jaautomation.local

SAFETY

No safety flag

Recorded with the source

VERSION

3

2026-08-22T20:06:42.575Z

Change history

Immutable audit trail for this source record.

4 events

report.report modified

Alex Rivera · 2026-08-22 20:06:42

Changed: summary, standbyReason, customerContact

report.daily.update

Alex Rivera · 2026-08-22 20:06:42

Changed: summary, standbyReason, customerContact

daily report.submit

Alex Rivera · 2026-08-22 20:06:42

{ "baseVersion": 1 }

daily report.create

Alex Rivera · 2026-08-22 20:06:42

{ "projectId": "01a02b15-2a6a-759b-9f4e-9d697250d7fa", "workDate": "2026-08-18" }

Owner controls

Deleting removes this draft source record and records the action in the audit trail. Finalized reports cannot be deleted.

Delete report