

Line 4 Main Conveyor

C-0001-P-001 · Body Shop Line 4 Controls Upgrade · Demo · 2026-09-22 · Alex Rivera

Approved

Modify report

Changes are versioned and notify the owner/admin review group.

v3

Autosave is available for draft reports and reports needing changes

Equipment

Identify the plant, line, station, and automation equipment involved.

System name **Required**

Line 4 Main Conveyor

Plant / site

Detroit Assembly Campus · Demo

Area / line

Body Shop / Line 4

Station / machine

Transfer Zone TZ-240

System type

Conveyor controls

PLC platform

Rockwell Automation

Controller

ControlLogix 5580

HMI / SCADA

FactoryTalk View SE

Network protocol

EtherNet/IP

Software version

Studio 5000 v35

Change

Describe the technical change and its production impact.

Program reference

L4_MAIN_DEMO_2026-08-11

Problem / symptom Required

Diagnosis / root cause Required

Change performed Required

Corrected the sequence race between robot-cell-clear confirmation and conveyor zone release.
Added a bounded wait state, diagnostic alarm and reset path.

Production impact

Removed intermittent startup hold without bypassing interlocks.

Validation / risk

Record validation performed, results, open risk, and rollback information.

Validation

Dry-cycle test, forced-fault recovery test and three automatic production cycles.

Validation result

All tests passed. No unresolved sequence faults.

Open risk / issue

Monitor input timing after planned sensor replacement.

Rollback plan

Restore prior routine revision from the registered pre-change backup.

Safety

Flag changes that require safety-impact review.

Safety impact

☐

Cancel

Save changes and notify reviewers

Report summary

PROJECT

C-0001-P-001

Body Shop Line 4 Controls Upgrade · Demo

WORK PERFORMED BY

Alex Rivera

worker@demo.jaautomation.test

REPORT CREATED BY

Alex Rivera

worker@demo.jaautomation.test

REVIEWED BY

Daniel Brooks

pm@demo.jaautomation.test

SAFETY

No safety flag

Recorded with the source

VERSION

3

2026-09-22T14:17:49.282Z

Change history

Immutable audit trail for this source record.

3 events

Technical report approved
Daniel Brooks · 2026-09-22 14:17:49

`{"reason":null,"safetyRelated":false}`

Technical report submitted for review

Alex Rivera · 2026-09-22 14:17:49

`{"baseVersion":1}`

Technical report created

Alex Rivera · 2026-09-22 14:17:49

`{"projectId":"01a0c97a-e32b-73bf-bb6b-05e39c4ab508","reportDate":"2026-08-11","safetyRelated":false}`