

EXAMPLE-P-001 · EXAMPLE — Packaging Cell
Commissioning · Sep 9, 2026

Operational record

Project EXAMPLE-P-001 · EXAMPLE — Packaging Cell Commissioning	Work performed by Marina Costa
Report created by Marina Costa	Client Example Manufacturing Ltd
Date Sep 9, 2026	System EXAMPLE — Packaging Cell PLC
Site EXAMPLE Manufacturing Site	Area / line EXAMPLE Packaging Line 1
Station / machine EXAMPLE Case Packer	Status Approved
Safety-related No	

Technical records

System type PLC and safety controller	PLC platform EXAMPLE controller — training data
Controller EXAMPLE-CPU-001	HMI / SCADA EXAMPLE-HMI-001
Network protocol Industrial Ethernet — EXAMPLE	Software version EXAMPLE v1.0

Program reference

**EXAMPLE_P001_REV_02_NOT_FOR_US
E**

Change summary

Problem / symptom

EXAMPLE photoeye chatter caused an intermittent carton-present alarm.

Diagnosis / root cause

EXAMPLE input debounce was shorter than the simulated sensor transition.

Change performed

EXAMPLE debounce changed from 40 ms to 80 ms.

Production impact

No production impact; fictional test mode only.

Validation

EXAMPLE — ten consecutive simulated cartons passed.

Validation result

Pass for documentation example only.

Open risk

None; this is synthetic and must not be used for field work.

Rollback plan

**Restore
EXAMPLE_P001_REV_01_NOT_FOR_US
E.**

Technical changes

DATE	DETAIL	CHANGE SUMMARY	STATUS
Sep 9, 2026	EXAMPLE photoeye input	Debounce 40 ms → 80 ms	Approved