



Technical report

C-0050-P-20261005 · BBS · Ejemplo de manual · Oct 19, 2026

OPERATIONAL RECORD

Project C-0050-P-20261005 · BBS · Ejemplo de manual	Work performed by BBS ROLE LAB External Technician
Worker email bbs-role-lab-external@example.test	Report created by BBS ROLE LAB External Technician
Creator email bbs-role-lab-external@example.test	Reviewed by BBS ROLE LAB Project Manager
Reviewer email bbs-role-lab-manager@example.test	Client BBS DEMO - Manual
Date Oct 19, 2026	System SYNTHETIC ET06 documentation bench
Site BBS readiness lab	Area / line —
Station / machine —	Status Approved
Safety-related No	

TECHNICAL RECORDS

System type —	PLC platform —
-------------------------------------	--------------------------------------

Controller

—

HMI / SCADA

—

Network protocol

—

Software version

—

Program reference

ET06-DOC-20261019

CHANGE SUMMARY

Problem / symptom

Fictional diagram revision label missing.

Diagnosis / root cause

Training note did not name diagram revision.

Change performed

Added fictional revision label. No equipment or PLC changed.

Production impact

None; documentation exercise only.

Validation

Compared training before and after revision labels.

Validation result

Fictional label consistent.

Open risk

No live control change authorized.

Rollback plan

—