



Technical report

C-0050-P-20261005 · BBS · Ejemplo de manual · Oct 16, 2026

OPERATIONAL RECORD

Project

C-0050-P-20261005 · BBS · Ejemplo de manual

Work performed by

BBS ROLE LAB Supplier Coordinator

Worker email

bbs-role-lab-coordinator@example.test

Report created by

BBS ROLE LAB Supplier Coordinator

Creator email

bbs-role-lab-coordinator@example.test

Reviewed by

BBS ROLE LAB Project Manager

Reviewer email

bbs-role-lab-manager@example.test

Client

BBS DEMO - Manual

Date

Oct 16, 2026

System

SYNTHETIC SC05 training documentation bench

Site

BBS readiness lab

Area / line

Documentation only

Station / machine

Fictional training station

Status

Approved

Safety-related

No

TECHNICAL RECORDS

System type

Offline narrative exercise

PLC platform

No live PLC connected

Controller

Fictional controller

HMI / SCADA

Not connected

Network protocol

Offline

Software version

Training reference v1

Program reference

SC05-DOC-20261016

CHANGE SUMMARY

Problem / symptom

Fictional handover lacked a revision reference.

Diagnosis / root cause

Training-only document reference omitted.

Change performed

Added revision reference to synthetic notes; no machine change.

Production impact

None. No live equipment, software upload or dispatch.

Validation

Compared fictional before/after text and revision label.

Validation result

Synthetic documentation reference now matches.

Open risk

Training exercise only; technical lead must authorize any real work.

Rollback plan

—