



Daily report

CP020 · BBS Mexico · Aug 5, 2026

Operational record

Project

CP020 · BBS Mexico

Client

IMPC Gmbh

Date

Aug 5, 2026

Worker

Gabriel Santos

Status

Approved

Safety-related

Yes

Site / shift

**Plant 1 · First Shift (07:00
- 17:00)**

Downtime minutes

0

Standby reason

**None · Normal continuous
operation**

Summary

Commissioned Allen Bradley ControlLogix safety zones and validated Siemens S7-1500 interlocks for Stations 10 to 14. Supervised trial production run with 0 safety incidents.

Tasks completed

Safety circuit checkout, servo axis tuning, HMI alarm messaging verified

Problems found

Photoelectric sensor bracket on station 12 was misaligned

Corrective actions

Re-aligned bracket and tightened mounting bolts; retested trigger window