HSE ORIENTATION

DRIVERS, BULK LIQUID CPU, VENDORS



INTRODUCTION

Welcome to McAsphalt! Please start your orientation with this short video.

Introducing McAsphalt Industries Limited

HEALTH, SAFETY, ENVIRONMENT, QUALITY POLICY



The McAsphalt HSEQ Policy is intended to reflect how we as a company manage our exposure to risk in the workplace.



Our Policy demonstrates the attitude and Leadership Commitment towards HSEQ with the steps, arrangements, and systems the company has in place to ensure compliance with all requirements including HSEQ and Legal.



McAsphalt ensures that all employees are made aware of our HSEQ Policy, which is publicly available, gets reviewed during the onboarding process and during returning employee orientations.



The Policy is reviewed annually, or when deemed necessary by Senior Leadership. Once the review in complete, the Policy will be re-approved by the President of McAsphalt, then distributed and made available through the appropriate channels.

- McAsphalt utilizes a combination of Health, Safety, Environmental and Quality Management Systems relating to the business unit needs while acknowledging and meeting all applicable regulatory and legislative requirements.
- McAsphalt cultivates risk-based thinking and knowledge sharing which emphasizes our actionable commitment towards continual improvement while strengthening our corporate culture of excellence.
- The Policy's update and release will be in accordance with or as prescribed by the applicable management system.

OUR GUIDING PRINCIPALS INCLUDE:



- Leadership
- Accountability
- Compliance
- Conservation
- Prevention
- Customer Focus and
- Continual Improvement

This is complimented by our Company Values of Sharing, Caring and Daring:

LIVING GOAL ZERO!



WORK SAFE – HOME SAFE

At McAsphalt, employee safety & wellbeing is at the core of everything we do.

We follow our Living Goal Zero Program to guide us to success in achieving Goal Zero. By embedding our Lifesaving Icons and everyday Behaviours in all our systems at work, we provide a common framework towards ensuring a safe working environment for everyone.

We encourage all visitors & contractors to report any Unsafe Acts or Conditions to the Responsible Manager or HSE Department for further investigation.

The program consists of 8 Core and 5 Supplementary Lifesaving Icons. These rules require that we all remain constantly vigilant about what we do and how that affects our wellbeing as well as those around us, thus maintaining a resilient culture of shared responsibility and a Zero Tolerance mindset.

These rules are shared and applied across all Colas Business Units around the world to ensure sustainability.

By adopting all Lifesaving Behaviours, we mitigate the risk of Serious Injuries and Fatalities (SIF)

Please watch the **Living Goal Zero** video and refer to more information below.

CORE ICONS



HAZARD CONTROL

Identify, evaluate, and control hazards before starting work.

A suitable plan must be in place that controls potential hazards in the workplace and the required controls must be communicated to each member of the workforce. Potential hazards and controls must be reviewed each day or for each new task to identify new or unforeseen hazards and amended controls must be agreed and authorized.



FALL PREVENTION

Protect yourself from falls.

Avoid working at height or use collective protection such as barriers or guardrails where possible. Work within a protective environment such as scaffold, man-lift or elevated platform or use fall protection equipment when working at heights. Always use three points of contact when accessing equipment, vehicles, and ladders. Fall hazards include elevated work, getting into or out of vehicles, working near exposed edges or around voids or fragile surfaces.



ROAD SAFETY

Drive and operate equipment safely.

This includes being qualified and authorized to drive a company vehicle on the highway, operating equipment on site, always wearing your seat belt, properly inspecting vehicles or equipment before use, obeying posted speed limits, and never driving or operating a vehicle or equipment while distracted. Road safety hazards include driving on the highway, on a work site and includes on-road and off-road vehicles.



ENERGY ISOLATION

Verify Zero Energy before work begins and use specified lock-out / tag-out equipment where required.

Hazardous energy includes equipment power sources such as electricity or fuels but also includes stored energy in the system such as electric potential, mechanical or kinetic energy, pressure, toxic materials, gases, chemicals, hot liquids, and gravity.



COMPETENCY

You must be adequately trained, experienced, and authorized to complete work tasks, or to operate equipment in the workplace.

Have a valid qualification, certification, or other authorization before you start the work task, or operate work equipment.



HEALTH HAZARDS

Protect yourself from health hazards.

These include exposure to materials, substances or environments that may cause life-altering injuries or conditions. Potential Health Hazards in our business can come from many sources, through inhalation, ingestion, contact, and from the environment. They can cause skin sensitizing/irritating, heat-related illness, and allergic reactions.



IMPAIRMENT

Never work or operate equipment while impaired.

Using alcohol or illegal drugs, or misusing legal drugs or other substances, will reduce your ability to do your job safely. A tired or fatigued worker may also be considered impaired.



LINE OF FIRE

Stay out of danger zones.

These include areas where there is a risk of being run over or backed over by a vehicle or mobile equipment, being struck by an object falling from height, ejected from a system or tool, or getting caught between an object and being crushed. Common activities where Line of Fire hazards are present include the moving/backing of vehicles and equipment, lifting or hoisting, tensioned lines, objects with potential to fall or roll, pressurized systems, electrical equipment, spring-loaded devices, and projectiles.

SUPPLEMENTARY ICONS



EXCAVATION

Before starting trenching and excavation work, ensure that authorization has taken place and that competent persons are in charge and responsible for operations.

Trenching and excavation may contain underground utility hazards, potential confined spaces, and have the potential for collapse of earth, walls and excavated materials.



CONFINED SPACES

Follow the confined space entry procedures before entering a confined space.

Confined spaces, such as silos, tankers, underground storage tanks, vaults, etc. may contain explosive gases, poisonous air, oxygen-deficient atmospheres, or other physical or environmental hazards. Spaces shall be permitted unless determined to not be required by the supervisor-in-charge. Authorized access will keep you safe.



SAFE LIFTING

Lifting activities must be planned, supervised, and carried out by competent people.

Lifting equipment and accessories must be certified and used in the manner for which they were designed. Hazards include failure or collapse of lifting equipment, loss of the load, which can fall on people nearby, or being trapped and crushed by parts of the lifting equipment or load.



OVERHEAD POWER LINES

Work activities must be planned to ensure equipment, objects or personnel do not enter the Minimum Approach Distance around any energized overhead line.

Hazards include electrocution or fire whenever the electricity finds a path to ground, touch potential of any object in contact with the line, or step potential where electricity is discharged in the ground. Electricity can jump a significant distance so direct contact with the line does not have to be made. In addition, lines can remain energized even when the power is turned off, so always treat any line as energized.



WORKING OVER WATER

Personal flotation devices should always be worn when there is a danger of falling into water.

When working near, or on water, wearing a personal flotation device (e.g., life jackets or buoyancy aids) protects you from drowning.

BACK IN / PARKING POLICY

BACK-IN PARKING ONLY signs are located at all McAsphalt locations, indicating the mandatory requirement to back-in when parking anywhere on the property. This is to be adhered to by employees, contractors, and visitors operating light vehicles.

Why do we back in? The simple answer is **“Safety”**.


- **Psychological,** how employees park when they arrive at work can affect their behaviour throughout the workday. It naturally triggers thoughts of why it is necessary, and anything that gets us to think about safe behaviour is a good thing.

- **Physical,** back in parking gives the driver a smaller field of vision and requires more concentration. As such, it is safer to do this at the start of your shift, when you are most alert. Also, in case of an emergency a degree of panic arises very quickly. If the need to evacuate arises, it is much quicker and safer to get into your vehicle and drive forward and out.



SIGN IN / SIGN OUT POLICY

- Any time you are entering or leaving a McAsphalt location, you must **sign in** and **sign out** at reception or the scale house. The reception or scale house must always be your first and last point of contact, no matter the purpose of your visit.
- For McAsphalt employees working on site, it is important you notify your supervisor or host when leaving the property, even if it is only for a brief period.



MCA **OPERATIONS** FCD.451.013 REV.1


Employee,Visitor, Contractor Sign-In-Out

Date	Name (Print)	Company	Contact Number	Time-In	Time-Out

- Once signed in, you must meet with your McAsphalt host in person.
- No visitor is allowed to wander the premises unaccompanied.
- If in doubt, consult the nearest / first employee you encounter.

DRIVERS ARRIVING ON SITE

- First and foremost, all drivers and / or retail customers must report to the scale house or office upon arrival.
- You must provide the bill of lading, which will be reviewed for last contents contained and actions required, if any, before loading / unloading begins.
- For example, rinsing requirements for loading a cationic emulsion when an anionic emulsion was the last contents contained.
- Verify if the product is regulated under the transportation of dangerous goods (TDG Act). If so, you will need the proper placards and have them securely displayed on each side and end of the means of containment. If unsure, ask a McAsphalt representative for assistance.



BILL OF LADING / CONNAISSEMENT

COPY

McASPHALT

Page: 1
Date: 6/5/2019

MCASPHALT INDUSTRIES LIMITED
22423 TWP 552, STURGEON INDUSTRIAL PARK
STURGEON COUNTY,AB,
780-912-9915

Ticket No: 439-1008913
Time In: 6:00:00 PM
Time Out: 7:02:00 PM

24 HOUR NUMBER - CANUTEC (613) 996-6666

Sold To: C00679
RUBYDALE ASPHALT WORKS (2006) LT
724 EAST LAKE ROAD
AIRDRIE, AB T4A 2J5

Ship To:
RUBYDALE ASPHALT WORKS (2006) LTD
Sundre

Method: CARRIER
MCASPHALT LOGISTICS INC.
Truck BoL: 2879
Truck No.: T543-06 631/632
Lic. No.: WALTER
Placards: 0
Last Contents:
52-34



WORKPLACE HARASSMENT, DISCRIMINATION & VIOLENCE

The workplace harassment program applies to all managers, supervisors, temporary employees, students, and subcontractors of McAsphalt Industries Ltd, affiliated companies, employees, and along with contractors or others performing work on behalf of McAsphalt.

McAsphalt is committed to providing and maintaining a harassment-free work environment in which all workers are treated with respect and dignity. In pursuit of this goal, McAsphalt does not condone and will not tolerate acts of harassment and/or violence against or by any employee. As such, this policy prohibits physical or verbal threats – with or without the use of weapons – intimidation, or violence and discrimination in the workplace.

Everyone has the right to equal treatment without discrimination or harassment, in the areas covered by the *Human Rights Code*. Workplace discrimination grounds include but are not limited to:

- Race, Ethnic origin, Place of origin, Citizenship,
- Disability, Age, Marital status, Family status
- Colour, Ancestry, Creed (religion)
- Sex, Sexual orientation
- Gender, Gender identity, Gender expression
- Receipt of social assistance
- Record of offenses

DRUG & ALCOHOL POLICY

- All employees, contractors, carriers, and brokers are expected to be fit for duty and in a condition to carry out their assignments and responsibilities. Those occupying safety sensitive positions will be subject to specific testing procedures.
- The consumption, use, manufacture, dispensation, sale, possession, distribution, promotion, provision, purchase, transportation, concealment, transfer or storage of unauthorized, prohibited, illegal or controlled substances and/or substance-related paraphernalia while performing McAsphalt work, on McAsphalt assignment or on McAsphalt premises (including McAsphalt owned or leased vehicles), is strictly prohibited.
- An employee, contractor, carrier, or broker whose off-duty involvement with unauthorized, prohibited, illegal or controlled substances becomes known to McAsphalt may be considered to be in violation of our policy.
- All employees, contractors, carriers, and brokers doing work with or for McAsphalt, whether it be handling and / or transporting product or doing any safety sensitive work, may be required to undergo or provide proof of a drug and alcohol screen that is consistent with the intent and implications of our policy.



PERSONAL PROTECTIVE EQUIPMENT (PPE)

Everyone entering a McAsphalt site must wear or have on their person our minimum PPE as follows:



- Hard Hat
- Safety Glasses
- Clothing covering all limbs
- High Visibility / Reflective Vest or Jacket
- Protective Gloves specific to hazard
- Safety Boots, minimum 6 inch

- Specialized PPE must be worn as required by the activity / hazard. i.e. fall arrest, gas monitors, respirators, PFD, etc.
- Burn Cards to be on your person at all times.
- Heat Resistant sleeves to protect wrists and forearms, Fire Resistant Coveralls and Face Shields to be used for loading / unloading activities, and other tasks involving hot liquid substances as deemed necessary by hazard assessment.
- Wearing of prescribed PPE is mandatory. Failure to comply will lead to your refusal to enter our working area. It is for your own safety as well as of others around you.



**All 3rd Parties and Contractors need to provide their own PPE.*
***PPE to be put on at sign in or scale, whichever comes first.*
****All equipment needs to be CSA Approved.*


EMERGENCY SAFETY EQUIPMENT

All McAsphalt locations are equipped with the following:

- A list of staff trained in First-Aid, CPR, and AED
- First-Aid Kits
- AED's
- Fire Extinguishers
- Emergency Eyewash / Shower Stations
- Evacuation Routes
- Burn Kits

**If exposed to molten asphalt, completely submerge in cold water and do not attempt to remove. Seek medical attention!*

All the above are identified on the Emergency Response site plan or HSE board. Please review with the site representative.



McASPHALT

mcasphalt.com
ISO 9001/14001/45001

Suggested Treatment For Molten Asphalt Cement Burns

Completely submerge area in ice water.
DO NOT apply ice directly to affected area.
DO NOT ATTEMPT TO REMOVE THE ASPHALT CEMENT with products containing solvents or ammonia.

Natural separation will occur in about 48-72 hours. If necessary for early removal, soak bandage in mineral oil and place over affected areas for 2 to 3 hours.

McAsphalt Industries Limited
www.mcasphalt.com

First Aid For Molten Asphalt Cement Burns

Completely submerge affected area is ice cold tap water, or place affected area under running water. DO NOT DELAY.

Minor Asphalt Cement Burns - at first opportunity get victim to physician.

Serious Asphalt Cement Burns - as soon as possible get victim to hospital, clinic or physician's office,
Includes: Injury to the head, face or extremities; Injury when large amounts of asphalt cements are involved; Evidence of nausea or faintness.

Treatment for Shock:

1. Keep victim lying down and quiet.
2. Covered with a blanket or something similar to keep body temperature at normal 98F (37C).
3. Keep victim's head lower than feet to promote blood pressure to head and chest.

DO NOT ATTEMPT TO REMOVE THE ASPHALT CEMENT

McASPHALT

EMERGENCY PREPAREDNESS

IN THE EVENT OF A FIRE OR EMERGENCY:


- 1. In the event a fire is discovered that is beyond control or you hear an alarm, ensure your safety, then check the area for others.
- 2. Leave the area and close doors behind you. Do not open any unnecessary doors on your way to the exit.
- 3. Activate alarm.
- 4. Call in the Alarm (911)
- 5. Meet in the designated area (Muster Point) for a headcount to ensure all persons have evacuated.
- 6. Secure the area for fire department and emergency vehicle access.
- 7. Remain at a safe distance to provide information to emergency personnel and ensure that all personnel are accounted for.



If at a customer location separate from McAsphalt, all drivers will follow the customers emergency response site plan.

FIRE PREVENTION

- Good housekeeping is essential in the prevention of fires.
- Fires can start anywhere and at any time. Therefore, it is important to know which fire extinguisher to use, where it is located, and how to use it.
- Always keep fire extinguishers visible, free from obstacles, and easy to retrieve.
- Fire extinguishers must be properly maintained, marked, inspected, and certified for the job.



UNWANTED EVENTS

- It is extremely important to report all Unsafe Acts and Condition, Incidents and Near-Misses to the Responsible Manager, or the nearest McAsphalt employee immediately.

- Anonymous Good-Catch and Near-Miss reporting is available through our Digital HSE Platform, by scanning the QR Code with any mobile device fitted with a camara. For more details, speak to the Responsible Manager.

- Good-Catch and Near-Miss reporting is encouraged as a proactive measure. Information and guideline is displayed around all work areas.

- All employee are permitted to stop any Unsafe Acts and Conditions, violations in Policy or Procedure or any breach in Legal Requirements.



SAFE JOB PROCEDURES

FALL PROTECTION

It is the policy of McAsphalt to protect its employees to the greatest extent possible as well as comply with the Occupational Health and Safety Code (OH&S).

- The OH&S code states that “An employer must ensure that workers use a fall protection device at a temporary or permanent work area if:
  - A worker may fall 3 meters or more.
  - There is a possibility of injury if a worker falls less than 3 meters.
- Climbing up to open a hatch or open a valve places an employee in a situation where they may fall more than 3 meters.
- McAsphalt employees must use fall protection devices supplied at the refineries, facilities, shops, and wash bays. Employees must be properly trained and certified in the use of personal fall protection devices prior to using them.
- Always use three points of contact when accessing equipment, vehicles, and ladders. Fall hazards include elevated work, getting into or out of vehicles, working near exposed edges or around voids or fragile surfaces.
- If you are unclear on fall protection, make sure to ask your manager or supervisor.






LOADING PROCEDURE

- Orders are placed at the scale house with the scale operator.
- If loading liquid bulk, a tare weight must be recorded by the scale operator before leaving the scale.
- If the product requested is a Dangerous Good, a valid TDG licence/certificate must be presented to the scale operator.
- Once your order has been placed, proceed to the loading area as directed by the scale operator.
- Maintain a safe responsible speed of 10 Km/h maximum while on McAsphalt property, unless otherwise posted.
- Ensure you have all the required PPE on, and your vehicle engine is off during the loading process.
- While loading liquid bulk, the vessel must be grounded with a grounding cable. The vessel must not be situated in the same enclosed space where the driver is located. i.e. in the back seats of a van.
- Absolutely no cell phones while in the loading zone.
- Intrinsically safe flashlights only.
- Under no circumstances should you start or stop any pumps. A McAsphalt Operator will instruct you when to open/close the butterfly valve on the wand.









LOADING PROCEDURE

If the product loaded is deemed a dangerous good as per TDG Regulations, placards must be present on the trailer(s) at all times. All drivers / carriers transporting dangerous goods products must strictly adhere to all TDG rules and regulations.

1. Prior to entering loading facility, ensure that all valves on the trailer(s) are closed, and the unit is ready to load.
2. Complete required paperwork prior to entering the loading facility.
3. Arrive at location and contact customer if required. Ensure all site-specific rules are adhered to.
4. When approaching the scale, bring your unit to a complete stop. Ensure the scale is free of traffic, align the unit properly, and proceed straight onto the scale at a slow speed. Driver will show the operator their paperwork to ensure compatibility and volume of product. Once the scale in process is completed, follow directions to designated loading area.
5. All mandatory PPE must be donned BEFORE entering the PPE area.
6. Proceed to the designated loading area when clear to do so. *** Loaders always have the right of way. ***
7. Driver aligns unit at the loading area with operator (spotter) guidance if necessary. Watch out for any rack that may have been left in a downward position as damage to both your unit and the rack are possible.
8. Driver turns off engine and applies the air brakes. All personal electronics must be kept inside the cab of the unit during the loading process. The drivers must follow site specific protocols related to their units' keys.
9. Driver performs a circle check.
   - Ensure the unit is properly grounded,
   - Ensure all valves on the unit are closed,
   - Verify all caps are secured.
10. Driver/Operator proceeds to the top of the loading rack and;
    - Lowers walkway/fall protection slowly,
    - Opens hatch and ensures no visible moisture, product, or foreign objects are inside trailer,
    - Positions loading arm above crows nest,
    - Disconnects drip pail,
    - Lowers arm into hatch (90o),
    - Secures loading arm,
    - Positions vapor recovery (if applicable),
    - Ensures meters are reset to zero and ready to start loading (If applicable),
    - Verifies valves are in the open position.
11. Driver and operator communicate that loading procedure is ready to commence.
12. If applicable, driver will maintain compression of dead mans switch.
13. Check for leaks while loading.
14. Double check meter is reading properly, and product is flowing.
    - Visual and sound checks must be completed at 3,000 / 6,000 / 9,000 KG.

McASPHALT

LOADING PROCEDURE (CONTINUED)

*** If any boiling is detected (cracking/popping sounds) stop loading and report immediately for further instructions. ***

- Maintain visual monitoring, with heightened attention when reaching 2,000 KG, ensuring full focus until the load is complete before finishing each trailer.

15. Loading is complete when the required quantity has been reached.

16. Driver/Operator proceeds to the top of the loading rack and;
    - Communicates/verifies that the pump has stopped,
    - Verifies valves are in the closed position,
    - Returns vapor recovery (if applicable),
    - Re-attaches drip pail to loading arm, and returns loading arm back to original position,
    - Closes and secures trailer hatch,
    - Raises walkway/fall protection slowly into upright position.

17. Proceed down from loading rack.

18. Driver performs a circle check.
    - Disconnect grounding cable from unit,
    - Check for visible and audible leaks,
    - Ensure all valves on the unit are closed,
    - Verify all caps are secured,
    - Verify again that loading rack is in the up-right position.

***If loading a Super-B / B-Train combination, repeat steps 7 to 18 for the pup trailer. ***

19. Pull away slowly from the loading rack and proceed to the scale.

20. When approaching the scale, bring your unit to a complete stop. Ensure the scale is free of traffic, align the unit properly, and proceed straight onto the scale at a slow speed.

21. Driver confirms all applicable fields are complete and accurate on the bill of lading. Prior to leaving scales for your destination make sure that you have all the proper paperwork for your load.

22. Driver inserts the new bill of lading into the last contained tube.

23. When safe to do so, slowly leave the scale and proceed to destination.

McASPHALT

UNLOADING PROCEDURE

1. Arrive at location and contact customer if required. Ensure all site-specific rules are adhered to.
2. If a scale is present; when approaching, bring your vehicle to a complete stop. Ensure the scale is free of traffic, align the unit properly, and proceed straight onto the scale at a slow speed. Once the scale in process is completed, follow directions to unloading area.
3. Driver will show the operator the bill of lading to ensure the correct product has been transported, the correct location to unload has been confirmed and written on the drivers copy of the bill of lading. The correct amount for safe delivery has been approved and the temperature is sufficient.

   *** Drivers will request that the operator initial the bill of lading next to the agreed location. ***

   *** Certain tasks listed in Step 3 may not be finalized until arrival at the unloading area. ***
4. All mandatory PPE must be donned BEFORE entering the PPE area.
5. Proceed to the designated unloading area when clear to do so.

   *** Loaders always have the right of way. ***
6. Driver aligns unit at the unloading site with operator (spotter) guidance if necessary.
7. Driver turns off engine and applies the air brakes. All personal electronics must be kept inside the cab of the unit during the unloading process.

   *** If pump is required for unload, please follow pumping procedure. ***
8. Driver performs a circle check.
   a) If required, ensure the unit is properly grounded.
   b) Ensure all valves on the unit are closed.
   c) Ensure catch basin/pail is positioned under the unload spout of the trailer (where the hose meets the dog leg).
   d) Verify all caps are secured.
   e) Confirm suspension is dropped.
   f) Verify the trailer that is being unloaded is properly vented by ensuring the top hatch is in an open position.
9. Remove cap from the unloading pipe on the trailer.

   *** Be cautious while removing the cap as product maybe present inside the plumbing ***
10. Driver and operator ensure the hose is in good condition and the hose has been properly attached/secured.
11. Driver and operator communicate that unloading procedure is ready to commence.
12. With the customers pump running, confirm proper suction by either visual, or auditory means.
13. After confirming suction, the driver will open the internal valve, then gradually open the external valve while monitoring for leaks and listening for air.
14. If there is no product flow, please refer to troubleshooting guide.
15. Driver will remain by the dog leg and valve until continuous product flow is established and no leaks are observed.
16. Driver must remain in view of the unload at all times and will verify product continues to flow properly by visually inspecting the unload at 5-, 20-, and 40-minute intervals until the unload has been visually confirmed to be complete.

    *** Obstructions and leaks may develop during unloading, potentially slowing, or interrupting product transfer.***

McASPHALT

UNLOADING PROCEDURE (CONTINUED)

17. Once the trailer is empty, continue to pump for at least a minute. Some sites don't allow for sufficient drainage, so extend pumping as needed to prevent product from solidifying and causing issues with future loads.

18. The driver should first close the internal valve before introducing air to purge the hose. This can be done using either a bleeder valve or the cam lock ear (open the opposite ear to your body position). Once the hose is empty;
    - If using the bleeder valve, close and cap it.
    - using the cam lock ear method, open the other cam ear, remove the hose slowly, and cap it when done.

19. Driver performs a circle check.
    a) Return grounding cable back to original location.
    b) Ensure all valves on the unit are closed.
    c) Ensure catch basin/pail is cleaned and returned to original location.
    d) Verify all caps are secured.
    e) Ensure product hose is returned to its original location.
    f) Confirm suspension is raised on your unit.
    g) Communicate with customer that it is safe to proceed.

    ***** If unloading a Super-B / B-Train combination, repeat steps 6 to 19 for the lead trailer. *****

20. Driver to ensure all necessary paperwork is completed, including:
    a) Time arrived.
    b) Time started.
    c) Time finished.
    d) Time departed.
    e) Customer signature.
    f) Tank delivered into.

21. "Residue Last Contained".
    a) Cross out the weights on the bill of lading.
    b) Clearly write "Residue Last Contained".
    c) Insert the updated bill of lading into the last contained tube.

22. If a scale is present; when approaching, bring your vehicle to a complete stop. Ensure the scale is free of traffic, align the unit properly, and proceed straight onto the scale at a slow speed. Declare to the scale that your unit is empty and capture the tare weight.

    *** Should a heel of 400kg or greater be left in the trailer, it must be reported immediately. ***

23. When safe to do so, slowly leave the scale and proceed to destination.

If the product unloaded was deemed a dangerous good as per TDG Regulations, placards must remain on the trailer(s). **All drivers/carriers transporting dangerous goods products must strictly adhere to all TDG rules and regulations.**

McASPHALT

LAST CONTAINED

THE IMPORTANCE OF LAST CONTAINED


- **Incompatibility:**
  - Asphalt and water/humidity can create a violent reaction. Asphalt boil overs have the potential to cause severe burns.
  - Anionic and cationic emulsion have different PH levels. The two are not compatible with each other.

- **Quality**
  - Mixing different products in small quantities may affect the properties of one of the products and will result in making the finished product off spec.

- **Compliance**
  - If applicable, drivers must ensure that the load is identified by the appropriate placards (TDG) and when unloaded, have the bill of lading of the last contained inside the document tube of the trailer.

Always have the residue last contained BOL in the document tube, no matter the product.

RESIDUE LAST CONTAINED



Shipment Origin: NANTICOKE TERM 06S5 METERED AT: CONCESSION RD # 3, NANTICOKE ONT N0A 1L0

Product Summary / Sommaire du produit

Dangerous Goods Description / Désignation des Marchandises Dangereuses	Gross	Net
NONE ASPHALT NOT REGULATED PG .	42040 KG	42040 KG
Totals:	42040 KG	42040 KG
		42040 KG

Check Residue - Last Contained

Product Detail / Détail du produit

ID	Name / Nom	Gross	Net	Temp	Density	Preset	Trailer Comp	Comp Empty
105052	Paving Asphalt PG 58-28	~~42040~~	~~42040~~	15.0	1020.3			
Totals:	~~Paving Asphalt PG 58-28~~	42040	~~42040~~					

Tare Weight / Gross Weight in KG 20360 / 62400

Residue Last Contained

MAR. 26/25 OSHAwise

ID	Product Message
105052	PRODUCT LAST CONTAINED 58-28 . TRUCK NO. 2145 5526 . IF ANTI-FOAM ADDITIVE USED, HOW MUCH — . THIS TRANSPORT VEHICLE HAS BEEN INSPECTED FOR AND IS ACCEPTABLE FOR TRANSPORTING THE ABOVE ASPHALT CEMENT PRODUCT.

IN - 6:00 AM
ST - 6:15 AM
OUT - 6:45 AM

TANK 21B

COMPATIBILITY CHART

LAST PRODUCT	PRODUCT TO BE LOADED			
	Asphalt Cement	Cutback Asphalt	Cationic Emulsion	Anionic Emulsion
Asphalt Cement	OK to Load ✓	OK to Load ✓	Empty to no Measurable Quantity** ✗	Empty to no Measurable Quantity** ✗
Cutback Asphalt	Empty* ✓	OK to Load ✓	Empty to no Measurable Quantity** ✗	Empty to no Measurable Quantity** ✗
Cationic Emulsion	Empty* ✓	Empty to no Measurable Quantity** ✗	OK to Load ✓	Empty to no Measurable Quantity** ✗
Anionic Emulsion	Empty* ✓	Empty to no Measurable Quantity** ✗	Empty to no Measurable Quantity** ✗	OK to Load ✓
Crude Petroleum	Empty* ✓	Empty to no Measurable Quantity** ✗	Empty to no Measurable Quantity** ✗	Empty to no Measurable Quantity** ✗
Any product not listed above	Tanks must be cleaned ✗	Tanks must be cleaned ✗	Tanks must be cleaned ✗	Tanks must be cleaned ✗

* = “Empty” means drained/dried out of all previous contents
** = “Empty to no Measurable Quantity” means less then 0.5% of capacity (ie. 25,000 litre tank x 0.005 = 125 Litres)

BURN AWARENESS





HOW TO DEAL WITH BURNS

Completely submerge affected area in ice water.
DO NOT APPLY ICE DIRECTLY TO AFFECTED AREAS.

DO NOT ATTEMPT TO REMOVE THE ASPHALT CEMENT
With products containing solvent or ammonia.

Natural separation will occur in 48 – 72 hours.

If necessary for early removal, soak bandages in mineral oil and place over affected area for 2 to 3 hours.









McASPHALT

GOAL ZERO OBJECTIF ZERO

Please watch this video for more information

Burn Prevention Video

HANDLING SPILLS, FIRES & OTHER EMERGENCIES

Drivers will need to be prepared for a product spill or fire should they occur. In order to deal with these, the driver must follow the proper procedures.

- Ensure the safety of yourself and others.
- Notify authorities, if applicable (Fire, Police, Ambulance).
- Secure the area if authorities have not yet arrived at the scene (if necessary).
- Contact your loader / operator. They will help assist you through the proper steps/procedures to take.
- Contain the leak/fire if safe to do so.
- Remain at the scene to provide assistance to the first responders (Fire, Police, Ambulance).
- Inform authorities of the response expected from McAsphalt.
- Understand the role of the emergency responders.
- If the media is at the scene, you are not required/permitted to speak with them, instead forward their inquiries to your manager/supervisor.



H2S AWARENESS

What is H2S ?

- H2S (hydrogen sulfide) is a hazardous gas often present in the vapour space of tanks, trucks, rail cars, and barge compartments containing liquid asphalt and may be present on our site.
- H2S gas is flammable and colourless. At low concentration it mimics the smell of rotten eggs. At high concentration it becomes odourless.
- **Warning Properties**
- Exposure to low concentrations of H2S may cause irritation to eyes, nose or throat. It may also cause difficulty in breathing for some asthmatics. Brief exposure to very high concentrations of H2S can cause a loss of consciousness and possibly death.
- Hazards controls are in place on our sites and if additional measures are required, they will be mentioned to you at the site-specific orientation.

ENVIRONMENT MANAGEMENT

- McAsphalt has implemented an Environmental Management system focusing on pollution prevention, compliance with all environmental guidelines, standards and regulations, and continual improvement of our environmental performance through regular review and evaluation of our facilities and departments Impacts and Aspects.

- This review will include both direct and indirect aspects where all identified processes and areas will be evaluated. This will include all new processes, products, activities and services.

- McAsphalt will include activities that have positive environmental impact, that reduce the impact of our activities to bolster acceptability including recycling practices, low carbon initiatives and conservation of natural resources and biodiversity.

HAZARDOUS WASTE

- All hazardous waste generated at a worksite, unused hazardous chemicals and related materials including those contaminated must be properly labeled, removed, transported and disposed of in accordance with applicable Environmental Legal Requirements.

- Discharge into drains, sinks or sewers is strictly prohibited on work location sites.

- Spills and other releases or impacts to the environment must be reported immediately to the Responsible Manager.

- Any clean up required in the event of accidental Environmental discharge will be coordinated by the Responsible Manager and will most likely include action to be taken by the contractor responsible for the discharge, or at their expense.





Thank you for reviewing our Drivers, Bulk Liquid CPU & Vendors. Please follow the link below to complete our online quiz and validate your registration.



Orientation Quiz