



CNC3-3018MAX

Part A: Assembly instructions


V.1.0


## STEP1. Base Assemble






Step2. Table Assemble







## Completed:




## Step3.Right






Step5. Left



Step6. Sipndle



## Step7. Control board

