
BANDWAAGEN



OOSIERWAAGEN

KUKLink 2.1

Manual English



A product of the company:

KUKLA Waagenfabrik GmbH & Co. KG

Stefan-Fadinger-Str. 1-11

4840 Vöcklabruck

Austria

Author:

Schaumberger Andreas

Place, date:

Vöcklabruck, am 04. Oktober 2006

Gegründet 1932

BANOWAAGEN



OOSIERWAAGEN

INDEX

START OF THE PROGRAM		PAGE 4
Menu File		PAGE 4
OPEN LIST		
SAVE LIST		
• Print		
• CLOSE LIST		
• EXIT		
MENU COM-PORT		PAGE 5
OPEN PORT		
 ADJUSTMENTS 		
MENU LANGUAGE/SPRACHE		PAGE 5
MENU PARAMETERS		PAGE 6
CHANGE OF PARAMETERS WITHOU	UT USING	
MENU PARAMETER		PAGE 7
SPECIAL CHARACTERISTICS OF PAI	RAMETER NO. 115, PARAMETER NO. 430	
AND PARAMETER No. 431	·	PAGE 7
PUSH BUTTONS AND CHECKBOX		PAGE 8
• RECEIVE PARAMETERS		
• TRANSMIT PARAMETERS		
OLD PARAMETER		
• CANCEL		

INSTALLATION OF KUKLINK 2.0

To install KUKLink 2.0 put the CD into your CD-drive. The installation starts automatically. If the installation does not start automatically, open the CD and execute manually the File Setup.exe.

Follow now the instructions on the screen.

START OF THE PROGRAM

For starting double-click the KUKLink 2.0 on your desktop or select KUKLink 2.0 in StartMenu. As standard now a window for selecting the language appears. Select the language requested and confirm with OK. KUKLink 2.0 now is correctly started.

MENU DATEI

• OPEN LIST

The menu point "Open list" - depending on whether "Old Parameter" is marked or not - offers 2 different functions.

"Old Parameter" marked:

In this mode you can open and work on traditional parameter expressions (*.pa3, *.pa4, *.pa5). The standard window for opening files is displayed. Select a traditional parameter expression and confirm with OK. This option is concerned with beneath (>> PUSH BUTTONS AND CHECKBOX)

"Old Parameter" not marked:

When implementing the menu Open list the standard pop-up window to open appears. The type of a parameter-list is *.pal.

SAVE LIST

After selection of menu point 'Save list' a pop-up window appears in which you can put in the name, under which the list shall be saved. You confirm your input with 'OK'.

PRINT

The standard pop-up window to print appears.

• CLOSE LIST

The list currently opened is closed.

EXIT

The program is left.

MENU COM-PORT

OPEN PORT


Opens the COM-Port with the Baudrate selected under 'Adjustments'.

After the first start the Settings selected are saved. After that the program start, the Port, can immediately be opened.

Attention: The Port selected must not be used by any other application, otherwise unexpected errors might occur.

• ADJUSTMENTS

Following Ports can be selected:



Following Baudrates can be selected:



MENU LANGUAGE/SPRACHE

Often it is necessary to print a parameter list in several languages. In this menu it is possible to adjust the language of the parameter list. The available languages are German, English, French, Italian and Spanish. Lists always are loaded in the language adjusted at that time.

MENU PARAMETER ...

This menu point can only be selected at opened list. Upon actuation following window appears:


KUKlink 2.0			
	ialdosierung Kontrollwaagenfunktion		
Waagendaten E/A - Analog E/A - Di	gital Dosierdaten/Zuteiler Grenzwerte		
Bedienungssprache Deutsch	Nennleistung 15000 kg/h		
● RBW / WB	Nennfrequenz 100 Hz		
C DDW	Nenngeschwindigkeit 		
Anzeigeeinheit	Zählerimpuls		
C XXX.x kg/h	C XXX.x kg Impulslänge		
C XXXX kg/h	⊙ XXXX kg 50 ms		
⊙ XX.xx t/h	C XX.xx t Zählsperre		
C XXX.x t/h	O XXX.x t =2%		
C XXXX t/h	C XXXX t		
Bandlänge 10000 mm	Tarierart		
g3 - Länge	MITTELWERT		
10 mm	C ABSOLUTWERT		
Prüfgewicht 11500			
ОК	Abbrechen		

Therein the most important parameters are comprised which this way can be changed quickly and simply. Please, note that the parameters cannot exceed/undercut certain limits. Please, find more details thereto in the parameter lists.

The parameters can also be directly changed in the list view. (\rightarrow Change of Parameters without using of Menu Parameter ...)

CHANGE OF PARAMETERS WITHOUT USING OF MENU PARAMETER ...

To edit the values of an opened list, double-click the line requested.




Now put in the value requested and confirm with 'OK'.

Attention: Please, note that your change is not effective if the selected value is outside the admissible range.

SPECIAL CHARACTERISTICS OF PARAMETER NO. 115, No. 430 AND No. 431

These parameters are represented by a Hex-number. The hexadecimal system is based - contrary to the decimal system - on 16 different figures (0-9 and A-F). By a click on the corresponding line a window appears in which the detailed apportionment of this value is displayed.

Thereto an example of parameter No. 115 with the value &H800C



PUSH BUTTONS AND CHECKBOX

• RECEIVE PARAMETERS

The Push button "Receive parameters" - depending on whether "Old Parameter" is marked or not - offers 2 different functions.

Attention: In order to be able to receive data both at the DWC and at the program the same Port-settings have to be adjusted. The scale computer must not be in picture mode.

"Old Parameter" marked:

In this mode you can receive traditional parameter expressions. For representing them a new window appears. This option is concerned with beneath (\rightarrow PUSH BUTTONS AND CHECKBOX).

"Old Parameter" not marked:

A parameter list is received. This may - depending on the Baudrate - take some time.

In case of inappropriate cables transmission errors may occur. Please, note the beam in the description field. If it does not move any more and nevertheless no new list appears, press the Cancel-button and try once more. If the error continues to exist, replace the transmission cable. It is not recommended to actuate the Cancelbutton during the data transfer.

No data can be received from a DWC4.


• TRANSMIT PARAMETERS

In order to transmit data press 'Transmit parameters'. The data transfer may take some time. It is not possible to transmit data to a DWC4.

Attention: In order to be able to transmit data both at the DWC and at the program the same Port-settings have to be adjusted. The scale computer must be in parameterizing mode.

• OLD PARAMETER

The Checkbox Old Parameter governs whether you work with the traditional parameter expression or with the new parameter list. The previous instructions - unless otherwise noted - relate to the parameter list. After opening/downloading of a parameter expression following window appears:



You can print and save this list as usual.

This function is the only one which can open resp. process data from a DWC4.

It is not possible to transmit a traditional parameter list to the DWC!

• CANCEL

This Button is active only if data are received. This Button shuts down the Port-connection and, thus, terminates the data transfer.

Please, absolutely note: It is not recommendable to actuate the Cancel-Button during the data transfer. Only use this Push button, if due to the beam in the description field an end of the data transfer can be recognized.