# Casting - GATE

## Kulasekaran

February 14, 2023

# Contents

1	Met	al Casting
	1.1	Introduction to Casting
		1.1.1 Advantages
		1.1.2 Disadvantages
	1.2	Pattern
		1.2.1 Shrinkage allowance (+ve)
		1.2.2 Draft or Taper allowance (+ve)
		1.2.3 Machining allowance (+ve)
		1.2.5 Machining anowance (+ve)
		1.2.4 Shake or Rapping allowance (-ve)
		1.2.5 Distortion or Camber allowance (+ve)
	1.3	Terms
		1.3.1 Flask
		1.3.2 Core
		1.3.3 Pouring Basin
		1.3.4 Sprue
		1.3.5 Choke
		1.3.6 Runner
		1.3.7 Difference between Sprue and Runner
		1.3.8 Gate
		1.3.9 Chaplet
		1.3.10 Chills
		1.3.11 Riser
		1.3.12 Vents
	1.4	Types of Pattern
	1.5	Properties of Moulding sand
	1.6	Core design
	1.7	Types of sand
	1.8	Additives used in moulding sand
	1.9	Types of Moulding methods
	1.10	Gating system
	1.11	Top Gate
	1.12	Bottom Gate
	1.13	Parting Line Gate
	1.14	Step Gate
	1.15	Solidification Time
	1.16	Types of Solidification
	1.17	Purpose of Riser
	1.18	Classification of Casting Techniques
	1.19	Permanent moulds
	1.20	Casting Defects
	1.21	Cupola
	1.22	Non-Destructive Testing
	1.23	Visual Inspection
	1.24	Hammer Test
		Radiography
	1.26	Liquid Penetrant test
		Ultrasonic Inspection

## Chapter 1

## Metal Casting

## 1.1 Introduction to Casting

- Casting Creating objects by melting metal, pouring it into a cavity that has the shape of that desired object and after solidification of metal, the object is obtained.
- Expendable mould Mould is broken after each object is cast
- Permanent mould Mould is reused for several cast

## 1.1.1 Advantages

- Less expensive
- Both brittle and ductile objects can be cast
- Easier to produce intricate shapes

## 1.1.2 Disadvantages

- Dimensional accuracy and Surface finish is very less
- Gas defects can form
- More labour intensive process
- Non-uniform mechanical properties of cast objects due to Non-uniform cooling

### 1.2 Pattern

• It is the replica of the desire object with slight modifications like core and allowances

### 1.2.1 Shrinkage allowance (+ve)

- $-T_P$  = Pouring Temperature;  $T_f$  = Freezing temperature;  $T_a$  = Ambient Temperature  $(T_P > T_f > T_a)$
- Liquid Shrinkage Metal cools from  $T_P$  to  $T_f$
- Solidification Shrinkage Cooling during Phase transition at constant temp
- Solid Shrinkage Metal cools from  $T_f$  to  $T_a$
- Liquid and Solidification Shrinkage can be compensated with Riser
- Solid shrinkage requires shrinkage allowance

## 1.2.2 Draft or Taper allowance (+ve)

- For easy removal of pattern from sand mould without damaging the mould
- $-x = htan \theta$  (Around 0.5 to 2°)

## 1.2.3 Machining allowance (+ve)

Since casting products have poor surface finish, machining is required for cast objects. This reduces the
object's dimensions. So, the casting dimension of the object must be more than actual required dimension
of the object.


## 1.2.4 Shake or Rapping allowance (-ve)

- When Pattern is tried to be taken out of the mould, due to shaking, it increases the mould cavity. So, if the cavity dimension was given slightly less compared to the original product dimension, then the shaking itself will bring the cavity to the required dimension


## 1.2.5 Distortion or Camber allowance (+ve)

 V-shape, U-shape and flat object with very less thickness can distort. To avoid distortion, allowance is provided opposite to the direction of distortion

## 1.3 Terms



#### 1.3.1 Flask



#### 1.3.2 Core

• If the desired object has a **hollow cavity**, then to cast such object, that hollow cavity sized object is placed in the sand mould, so that the molten metal can't fill that space.

## 1.3.3 Pouring Basin

• Funnel shaped cavity at the top of the mould into which the molten metal is poured

#### 1.3.4 Sprue

• The passage through which the molten metal from the Pouring basin reaches the mould cavity

#### Choke 1.3.5

- Regulates flow rate of molten metal and hence prevents defects
- Can be created by using core or creating a tapered section in gating system

#### 1.3.6 Runner

• The passage way in the parting plane. Parting plane is the plane between the top and bottom part of the mould

#### Difference between Sprue and Runner


- Sprue is the main and largest channel and is located at a top point.
- Runner distributes the molten metal to every gates

#### 1.3.8 Gate

• Entry point of the mould cavity

#### 1.3.9Chaplet

• Used to support core objects and keep them fixed



#### 1.3.10 Chills

• metalling objects placed inside to increase cooling rate

#### 1.3.11 Riser

- Acts as a reservoir
- When there is reduction in volume of metal in the cavity due to contraction, the molten metal in riser can fill

#### 1.3.12 Vents

• Vents are small holes provided for the escape of gases or trapped air pockets and hence preventing gas defects

#### Types of Pattern 1.4

#### 1.4.1 Solid or Single piece pattern

#### Split piece pattern 1.4.2

1.4.3 Loose piece pattern

1.4.4	Gated Pattern
1.4.5	Match Plate pattern
1.4.6	Cope and Drag pattern
1.4.7	Sweep pattern
1.4.8	Follow board pattern
1.4.9	Skeleton pattern
1.5	Properties of Moulding sand
1.6	Core design
1.7	Types of sand
1.8	Additives used in moulding sand
1.9	Types of Moulding methods
1.10	Gating system

1.11	Top Gate
1.12	Bottom Gate
1.13	Parting Line Gate
1.14	Step Gate
1.15	Solidification Time
1.16	Types of Solidification
1.17	Purpose of Riser
1.18	Classification of Casting Techniques
1.19	Permanent moulds
1.20	Casting Defects

1.21	Cupola	
•		
1.22	Non-Destructive Testing	
1.23	Visual Inspection	
1.24	Hammer Test	
1.25	Radiography	
1.26	Liquid Penetrant test	
1.27	Ultrasonic Inspection	