PLANNING AND CHANGES

	Issues in PB_A_1.1.1, changes require in PB_A_1.2-
	1. Buttons should be connected to RTC GPIODONE
	2. AHT sensor should be placed away from MCU so that we can get the exact and accurate temperature readingDONE
-	3. Need to recheck battery charging section, as it's not working for dead battery, we cannot charge the dead battery and provide system load at the same time with current circuitDONE
	3.1) Also, Add battery on off logic (as used in tracker device)DONE
	4. D2 LED ss recheckDONE
	5. Charging current change to 200mA (R35 should be 4.7K) DONE
	6. 100k pull down at gate of Q10DONE
	7. BOTTLE_SWITCH should be multiplexed with ESP_TX (need to check on hardware first, need to be confirm by vipin sir)DONE
	8. if 7 point is confirmed then we'll use a separate pin for charge ctrlDONE
	9. Power of SW32 and SW33 should be changed, take power from Q4,5,6,7 insteadDONE
-	10. gate pull up should be 100k instead of 10k of P-channel mosfetDONE
	11. need to add coin cell as backup for RTC ckt using diodeMS621FE-FL11E added with BAT54KFILM
	12. U11 should provide power instead of Ground, and U8 should provide groundDONE
	13. Check Boot pin from EL-400 DONE
	14. PCB thickness should be confirmed by 3D Designer or Client 1.2mm
	15. New Gerber of TG01 should be given by VIP sir DONE
	16. Recheck Buzzer's footprintPin distance reduced as per datasheet.
-	17. Add silkscreen for Speaker and Battery connDONE
	18. Add polarity for LCD LEDDONE
	29-06-2024-
	Issues in PB_A_1.3-
	1. Cannot use common SDAA signal for RTC and Accelero. Separate signal SDAA HT used.

21-12-2024-


Changes in PB_1.3.2-


- 1. Value of LED PWR resistors (R79-R85) and RGB LED changed from 2.2k o 470R.
- 2. LEDs LED1- LED28 changed to Blue, PN- SMLD12BN1WT86.
- 3. Hall sensor (SW1-SW28) changed to KTH1601.
- 4. Buzzer connected on pin 48 and GAIN_SLOT connected on ESP_RX.
- 5. Board shape changed completely as per new design.
- 6. PN of crystal changed to XTAL206-32.768K-9P-2020-CI.
- 7. Need to place crystal on the bottom side.
- 8. Made changes in Audio ckt.
- 9. Footprint of LCD updated for backlight.
- 10. AHT20 to the center of the PCB- Need to check.
- 11. PN of RGB LED changed to 19-337/R6GHBHC-A01/2T.
- 12. SCLL connected on ESP_TX.

PB_A_1.3.2				
Size A3	FCSM No.	DWG No.		Rev
Scale	1		Sheet 0 O	T. 4


С


BATTERY SECTION






CHARGING







BATT 1



BUZZER





ACCELERO




TEMP SENSOR









LED MAGNETIC SWITCH C PB_A_1.3.2 D Sheet 3 OF 3