STARVISH MECHATRONICS Service Report No: SVSR0202-18 3/491,3rd cross, Bharathi Nagar, Arasanatty, Hosur - 635126 Report Date: 08/03/2018 starvishmechatronics@gmail.com **SERVICE REPORT Customer Name & Address:** M/C Type **HMC** Hyundai Wia HS6300 **Avtec Limited** M/C Name Punapalli, Punapalli Village, Mathagondapalli Post, Nil M/C Serial No. Hosur - 635114 **Fanuc** Controller Name Chargeable(Yes/no) Yes Contact Person: Ramakrishnan.P **Service Date** Time in Time out Travel time Designation: Engineer 13,17,18-02-2018 9.00 a.m. 8.00 p.m. 20 min 22,23,24,25,26,27, Contact No: 9080980158 9.00 a.m. 8.00 p.m. 20 min 28-02-2018 Service Charge: Rs.10500/day + GST@18% **Nature of Complaint:** Abnormal noise in Spindle gear box while gear shifting. **Details of Service Performed:** Removed gear box and found bearing abnormality for main transmission and drive end bearing. Replaced spindle gearbox bearing. Replaced high speed spindle back support bearing. All other alignments done as per MTB's procedure. ATC alignment done and Tool change has been checked. Checked Spindle in high and low RPM.

Customer's Remarks:

Service Engineer's Remarks:

Customer's Signature

Machine handed over for production.

Prem, Starwin, Krishna

Service Engineer's Name & Signature