## CIS 351 Sample ADD4 Problem Solutions

Tue  $2^{\rm nd}$  Sept, 2025

## ADD4: Recognize Overflow

Given an 4-bit adder, complete the table below to show the carry out and overflow for each pair of inputs.

	A		В	$C_{out}$	Overflow
0	(0000)	0	(0000)	0	0
-1	(1111)	-1	(1111)	1	0
5	(0101)	6	(0110)	0	1