


Tektronix TDS 2001C — SPI Clock Waveform



Time Interval Error (TIE Track) — P2P Jitter: 66.15 ns

