

Ganga Bridge Pier 2: 5.2mm structural crack detected by lead auditor.