

Recommendation Report

Summary

Recommendations are rule-based and derived from observed hotspots, recurring causes, closure rates, and resilience scores.

Recommendation Report

Recommendations

priority	area	trigger	
recommendation			
High	Non-corridor	Hotspot 0 has 7176 incidents and 8.2% closure rate.	Increase monitoring near Non-corridor / HAL Old Airport for recurring vehicle_breakdown incidents.
Medium	Mysore Road	Hotspot 22 has 10 incidents and 40.0% closure rate.	Increase monitoring near Mysore Road / Kengeri for recurring others incidents.
Medium	Mysore Road	Hotspot 25 has 13 incidents and 30.8% closure rate.	Increase monitoring near Mysore Road / Kengeri for recurring vehicle_breakdown incidents.
Medium	Hennur Main Road	Hotspot 27 has 12 incidents and 0.0% closure rate.	Increase monitoring near Hennur Main Road / Hennuru for recurring vehicle_breakdown incidents.
Medium	Bellary Road 2	Hotspot 23 has 12 incidents and 0.0% closure rate.	Increase monitoring near Bellary Road 2 / Chikkajala for recurring vehicle_breakdown incidents.
Medium	ORR West 1	Hotspot 4 has 49 incidents and 0.0% closure rate.	Increase monitoring near ORR West 1 / Banashankari for recurring vehicle_breakdown incidents.
Medium	Bellary Road 2	Hotspot 19 has 14 incidents and 0.0% closure rate.	Increase monitoring near Bellary Road 2 / Chikkajala for recurring vehicle_breakdown incidents.
Medium	Non-corridor	Hotspot 8 has 67 incidents and 14.9% closure rate.	Increase monitoring near Non-corridor / Hennuru for recurring construction incidents.
Medium	Non-corridor	227 pothole-related incidents recorded.	Schedule road-condition inspection and maintenance review for this corridor.
Medium	Hosur Road	60 pothole-related incidents recorded.	Schedule road-condition inspection and maintenance review for this corridor.
Medium	Bannerghata Road	45 pothole-related incidents recorded.	Schedule road-condition inspection and maintenance review for this corridor.
Medium	IRR(Thanisandra road)	37 pothole-related incidents recorded.	Schedule road-condition inspection and maintenance review for this corridor.
Medium	ORR East 1	26 pothole-related incidents recorded.	Schedule road-condition inspection and maintenance review for this corridor.
Medium	Non-corridor	Low resilience score: 53.2/100.	Prioritize this area for patrol planning, recurring cause review, and incident response readiness.
Medium	Mysore Road	Low resilience score: 58.0/100.	Prioritize this area for patrol planning, recurring cause review, and incident response readiness.
Medium	Bellary Road 1	Low resilience score: 60.7/100.	Prioritize this area for patrol planning, recurring cause review, and incident response readiness.
Medium	IRR(Thanisandra road)	Low resilience score: 61.9/100.	Prioritize this area for patrol planning, recurring cause review, and incident response readiness.
Medium	Bannerghata Road	Low resilience score: 62.3/100.	Prioritize this area for patrol planning, recurring cause review, and incident response readiness.
Medium	Non-corridor	Road closure rate is 12.1%.	Monitor closure-prone incidents and prepare diversion communication playbooks.
Medium	Varthur Road	Road closure rate is 11.7%.	Monitor closure-prone incidents and prepare diversion communication playbooks.