

Same recorded target values, nominal supported simulator plants, real airborne hardware
Support fixtures are not independently metrologically matched; steering hardware zero is defective


Steering MIT 50 Hz versus the previous fixed-base simulator replay



Steering MIT 200 Hz versus the previous fixed-base simulator replay



Rear C0 50 Hz versus the previous fixed-base simulator replay



Rear C0 200 Hz versus the previous fixed-base simulator replay

