
Steering initialization defect: F1 starts at code 65535 / +3 rad, while A3 lies above +3 rad
No curve has been shifted to make tracking look better
Steering MIT 50 Hz | initial range clipping
min 2.5817 | max 3.1761
Native motor position (rad)
Time from replay start (s)
Native A3 count × 2π/16384
Native F1 position
F0 upper encoding endpoint +3 rad
Steering MIT 200 Hz | initial range clipping
min 2.5819 | max 3.2137
Native motor position (rad)
Time from replay start (s)
Native A3 count × 2π/16384
Native F1 position
F0 upper encoding endpoint +3 rad
min 0.17248 | max 0.17895
Coordinate discrepancy (rad)
Time from replay start (s)
A3-relative − F1-relative
Initial A3 minus F1: 0.176107 rad (10.09°)
min 0.21119 | max 0.21601
Coordinate discrepancy (rad)
Time from replay start (s)
A3-relative − F1-relative
Initial A3 minus F1: 0.213690 rad (12.24°)
Timing abort ~5.373 s