


MIT actuation check: measured current supports the requested P control







*Model alignment =1 ms selected with repeat 2, not measured firmware delay; raw current times unchanged. Current-derived torque is not independent shaft torque.