

$$W_{xc} \rightarrow R^D \times R^H \qquad W_{hc} \rightarrow R^H \times R^H$$

$$i_{t} = \sigma (W_{xi}x_{t} + W_{hi}h_{t-1} + W_{ci}c_{t-1} + b_{i})$$

$$f_{t} = \sigma (W_{xf}x_{t} + W_{hf}h_{t-1} + W_{cf}c_{t-1} + b_{f})$$

$$c_{t} = f_{t}c_{t-1} + i_{t} \tanh (W_{xc}x_{t} + W_{hc}h_{t-1} + b_{c})$$

$$o_{t} = \sigma (W_{xo}x_{t} + W_{ho}h_{t-1} + W_{co}c_{t} + b_{o})$$

$$h_{t} = o_{t} \tanh(c_{t})$$

$$egin{aligned} egin{aligned} egi$$

 $b_o \in \mathbb{R}^B imes \mathbb{R}^H$