
Design_and_Manufacturing_Workflow

April 9, 2021

1 1 Paper Mockup

The paper mock up is identical to the solidworks design seen after. It uses the same measurements as the dynamics II assignments, and is made of cardboard (frame) and cardstock (leg and links). To hold everything together, tape can be used, but the final device would use glue as it would provide a cleaner connection.






Folded:




Flattened:


2 2 Solidworks Model

The solidworks model seen here is a 3D version of our design. The folded states depicts both the assembled and exploded view for clarity. The flattened state represents the unfolded assembly in a way that can be used for manufacturing later. The system itself consists of 3 main parts, the sarrus linkages (x2), the frame, and the leg. Holes in the device are for the motor cable to move through, and flaps are used to adhere joints to one another.



Folded:






Flattened:

3 3 DXF file

The dxf file directly from solidworks (the method of retrieving the yaml file, then getting the dxf) had issues that left every joint. To troubleshoot, we attempted to add more verticies, and even manually adding them in the program draft sight, both to no avail. Eventually, we found a different program called libreCAD that functions similarly to draft sight. This allowed us to finally obtain the proper dxf file needed, with both body (red) and joint (blue) layers.



4 4 Jupyter Notebook

```
[66]: import foldable robotics
      from foldable robotics.layer import Layer
      from foldable_robotics.laminate import Laminate
      import shapely.geometry as sg
      foldable_robotics.resolution=4
[67]: import foldable_robotics
      import foldable_robotics.dxf
      import numpy
      import shapely.geometry as sg
      from foldable robotics.layer import Layer
      from foldable_robotics.laminate import Laminate
      import foldable_robotics.manufacturing
      import foldable_robotics.parts.castellated_hinge1
      import idealab_tools.plot_tris
      from math import pi, sin, cos, tan
      import idealab_tools.text_to_polygons
      foldable_robotics.display_height=200
      foldable_robotics.line_width=.5
      from foldable_robotics.layer import Layer
      from foldable_robotics.laminate import Laminate
      import foldable_robotics
      import foldable_robotics.dxf
      import foldable_robotics.manufacturing
      import foldable robotics.parts.castellated hinge1
```

```
foldable_robotics.display_height=200
      foldable_robotics.line_width=.5
      #import workflow_support as ws
      import os
      import foldable_robotics.solidworks_support
[68]: def get_bodies(filename, layername, num_layers):
          body = foldable robotics.dxf.read lwpolylines(filename,layer=layername,
       \rightarrowarc_approx = 10)
          bodies = [Layer(sg.Polygon(item)) for item in body]
          body = bodies.pop(0)
          for item in bodies:
              body ^= item
          body = body.to_laminate(num_layers)
          return body
[69]: def get_hinge_lines(filename, layername):
          hinge_lines1 = foldable_robotics.dxf.read_lines(filename,layer=layername)
          hinge_lines2 = foldable_robotics.dxf.
       →read_lwpolylines(filename,layer=layername)
          hinge_lines3 = []
          for points in hinge_lines2:
              hinge_lines3.append(points[:2])
          hinge_lines = hinge_lines1 +hinge_lines3
          return hinge_lines
[70]: def hinge_lines_to_hinges(hinge_lines,hinge):
          lam = Layer().to_laminate(len(hinge))
          all_hinges = []
          for p3,p4 in hinge_lines:
              all_hinges.append(hinge.map_line_stretch((0,0),(1,0),p3,p4))
          all_hinges = lam.unary_union(*all_hinges)
          return all_hinges
[71]: def get_cuts(filename, layername, thickness, num_layers):
          cut_lines = foldable robotics.dxf.read lines(filename,layer=layername)
          cut_lines += foldable_robotics.dxf.
       →read_lwpolylines(filename,layer=layername, arc_approx = 10)
          cuts = []
          for item in cut_lines:
              cuts.append(Layer(sg.LineString(item)))
          cuts = Layer().unary_union(*cuts)
          cuts<<=thickness/2
          cuts = cuts.to_laminate(num_layers)
```

```
return cuts
[72]: def get_holes(filename, layername,num_layers):
          holes = foldable robotics.dxf.read circles(filename,layer='holes')
          holes2 = []
          for center, radius in holes:
              holes2.append(sg.Point(*center).buffer(radius))
          holes layer = Layer(*holes2)
          holes_lam = holes_layer.to_laminate(num_layers)
          return holes lam
[73]: def hinge_width_calculator(desired_degrees,thickness):
          theta = (180-desired_degrees)*pi/180
          w=thickness/tan(theta)
          return w
[74]: def polys_to_layer(l1):
          11 = [sg.Polygon(item) for item in 11]
          l11 = Layer(l1.pop(0))
          for item in 11:
              111 ^= Layer(item)
          return 111
[75]: def output_pdf(filename,design2,x,y,layers_separate = True):
          design2 = design2.translate(x,y)
          design2=design2.scale(1/25.4,1/25.4)
          design2=design2.scale(foldable_robotics.pdf.ppi,foldable_robotics.pdf.ppi)
          if isinstance(design2,Laminate):
              if not layers_separate:
                  p=foldable_robotics.pdf.Page(filename+'.pdf')
                  for d in design2:
                   d = design2[0]
          #
                      for item in d.exteriors()+d.interiors():
                          p.draw_poly(item)
                  p.close()
              else:
                  for ii,d in enumerate(design2):
                      p=foldable_robotics.pdf.Page(filename+'{0:03f}.pdf'.format(ii))
                      for item in d.exteriors()+d.interiors():
                          p.draw_poly(item)
                      p.close()
          elif isinstance(design2,Layer):
              p=foldable_robotics.pdf.Page(filename+'.pdf')
              for item in design2.exteriors()+design2.interiors():
                  p.draw_poly(item)
```


```
p.close()
[76]: def build_layer_numbers(num_layers, text_size = None, prop=None):
          text_size = text_size or 1
          prop = prop or {'family':'Arial','size':text_size}
          layer_ids = []
          for ii in range(num layers):
              1 = idealab_tools.text_to_polygons.text_to_polygons('Layer_
       → '+str(ii),prop=prop)
              layer_ids.append(1)
          layer_ids = [polys_to_layer(item) for item in layer_ids]
          layer_id = Laminate(*layer_ids)
          return layer_id
[77]: def_
       -build_web(design2,keepout,support_width,jig_diameter,jig_hole_spacing,is_adhesive):
          num_layers = len(design2)
          layer_id = build_layer_numbers(num_layers,text_size=jig_diameter)
          design_outer = foldable robotics.manufacturing.unary_union(design2)
          bb1= (design_outer<<jig_hole_spacing/2).bounding_box()</pre>
          (x1,y1),p2 = bb1.bounding_box_coords()
          w,h = bb1.get_dimensions()
          w2 = round(w/jig_hole_spacing)*jig_hole_spacing
          h2 = round(h/jig_hole_spacing)*jig_hole_spacing
          points = []
          points.append(sg.Point(x1,y1))
          points.append(sg.Point(x1+w2,y1))
          points.append(sg.Point(x1,y1+h2))
          points.append(sg.Point(x1+w2,y1+h2))
          layer_id = layer_id.translate(x1+jig_diameter,y1-jig_diameter/2)
          placement_holes2 = Layer(*points)
          placement_holes2<<=(jig_diameter/2)</pre>
          sheet = (placement_holes2<<10).bounding_box()</pre>
          placement holes2=placement holes2.to laminate(num layers)
          sheet=sheet.to_laminate(num_layers)
          removable_scrap =
       →calculate removable scrap(design2, sheet, support width, is adhesive)
          web = (removable_scrap-placement_holes2)-layer_id
```

```
return web, sheet
[78]: def calculate removable scrap(design, sheet, width, is_adhesive):
          '''this computes all removable scrap given a sheet, a design, and a_{\sqcup}
       ⇔clearance width'''
          all_scrap = sheet-design
          ru = foldable_robotics.manufacturing.not_removable_up(design,is_adhesive)
          rd = foldable_robotics.manufacturing.not_removable_down(design,is_adhesive)
          removable_scrap_up = all_scrap-(ru<<width)</pre>
          removable_scrap_down = all_scrap-(rd<<width)</pre>
          removable_scrap = removable_scrap_up|removable_scrap_down
          return removable_scrap
[79]: | #user_path = os.path.abspath(os.path.expanduser('~')) user_path
[80]: | folder = 'C:/Users/Jonathan/Documents/Jupyter/Design and Manufacturing Workflow/
                                 #folder with yaml file
      input_filename = folder+'TESTFlatSystemPart - Sheet1_Drawing View1.yaml'
                       #All flattened assemblies
      #input_filename = folder+'SarrusLinkage - Sheet1_Drawing View1.yaml'
                    #Only sarrus linkage
      output_file_name = 'design.dxf'
      New_output_file_name = 'designJoints.dxf'
[81]: round_digits = 2
      prescale=1000
      jig_diameter = 5
      support_width = 1
      kerf = .05
      jig_hole_spacing=20
      is adhesive1 = [False]
      is_adhesive = [False,True,False,True,False]
      arc_approx = 10
[82]: foldable_robotics.solidworks_support.
       process(input_filename,output_file_name,prescale,round_digits)
[82]: (<foldable_robotics.layer.Layer at 0x194a0ac8640>,
       <foldable_robotics.layer.Layer at 0x194a0ac89a0>,
       [<foldable_robotics.solidworks_support.Component at 0x194a03aa040>])
```

5 1 Layer manufacturing design approach


Generating a perforated hinge for the single layer design:

```
[83]: radius = .01
      num_perforations = 5
      num_segments = num_perforations*2+1
      num_points = num_segments+1
      a=numpy.r_[0:1:num_points*1j]
      lines = []
      for ii in range(int(len(a)/2)-1):
          p1 = sg.Point(a[2*ii+1]+radius,0)
          p2 = sg.Point(a[2*ii+2]-radius,0)
          lines.append(sg.LineString((p1,p2)))
      hinge = Layer(*lines)
      hinge<<=radius
      hinge = Laminate(hinge)
      w=hinge_width_calculator(150,1.1)
      hinge = hinge.scale(1,w)
      hinge.plot()
```




```
[84]: NUMLAYERS = len(hinge)
NUMLAYERS
[84]: 1
```

[85]: hinge.plot()




Creating the main body of the design from the imported DXF. New_output_file_name is the modified design.dxf file.

```
[86]: body = get_bodies(New_output_file_name, 'body', NUMLAYERS)
body = foldable_robotics.manufacturing.cleanup(body,.01)
body.plot()
```



Plots the perforated hinges at each joint line from the joint layer:

```
[87]: joint_lines= get_hinge_lines(New_output_file_name,'joints')
    joints = hinge_lines_to_hinges(joint_lines,hinge)
    joints = foldable_robotics.manufacturing.cleanup(joints,.001)
    joints.plot()
```




```
[88]: cuts = get_cuts(New_output_file_name,'cuts',.02,NUMLAYERS)
#cuts.plot()
```


```
[89]: holes = get_holes(output_file_name, 'holes', NUMLAYERS)
#holes.plot()
```

Generate holes at vertices to prevent collision:


```
[90]: hole,dummy = foldable_robotics.manufacturing.calc_hole(joint_lines,w)
hole = hole.to_laminate(NUMLAYERS)
hole<<=.2
hole.plot()</pre>
```




How the end result will look:





Generating the keepout. In the single layer case, it is essentially equivalent to design2.




Web and sheet generation:









Since it is one layer, only a first/single pass in needed.



Generating support:




Merging the web, design2 and support into the supported design:




Plotting the material that will be cut and then the final cut itself:

```
[98]: #cut_line = keepout << kerf
cut_material = (keepout << kerf) - keepout
cut_material.plot()</pre>
```




```
[99]: final_cut = sheet - keepout
final_cut = final_cut[0]
final_cut.plot()
```





Plotting the material that will remain after the cut:


```
[100]: remaining_material = supported_design-cut_material
remaining_material.plot()
#make dxf here
```





Plots of each separate piece resulting from the cuts:
































```
[102]: d3=design2>>1
    for item in remaining_parts:
        if not (item&d3).is_null():
            break
    check = (item^design2)
    print(check.is_null())
```

False

Exporting 1-layer DXF:


```
[105]: #if check.is_null():
    # supported_design.export_dxf('first_pass')
    # final_cut.export_dxf('second_pass')

#supported_design.export_dxf('first_pass')
final_cut.export_dxf('Single_Layer_Cut')
```

6 5 Layer robot design approach

Generate 5 layer castellated hinge:


```
[106]: hinge = foldable_robotics.parts.castellated_hinge1.generate()
w=hinge_width_calculator(150,1.1)
hinge = hinge.scale(1,w)
hinge.plot()
```



```
[107]: NUMLAYERS = len(hinge)
NUMLAYERS


[107]: 5

[108]: body = get_bodies(New_output_file_name, 'body', NUMLAYERS)
body = foldable_robotics.manufacturing.cleanup(body,.01)
body.plot()
```



mapping the hinge design to each joint in your joints layer of the dxf

```
[109]: joint_lines= get_hinge_lines(New_output_file_name, 'joints')
    joints = hinge_lines_to_hinges(joint_lines, hinge)
    joints = foldable_robotics.manufacturing.cleanup(joints,.02)
    joints.plot()
```




```
[110]: cuts = get_cuts(New_output_file_name,'cuts',.02,NUMLAYERS)
#cuts.plot()
```

```
[111]: holes = get_holes(output_file_name, 'holes', NUMLAYERS)
#holes.plot()
```

holes computed for any vertices


```
[112]: hole,dummy = foldable_robotics.manufacturing.calc_hole(joint_lines,w)
hole = hole.to_laminate(NUMLAYERS)
hole<<=.2
hole.plot()</pre>
```




7 5 Layer manufacturing design approach

Subtracting hole, cut, and joint geometries from the body, resulting in the intended design:

```
[113]: design2 = body- hole - joints - cuts - holes
design2.plot()
```



[114]: keepout = foldable_robotics.manufacturing.keepout_laser(design2)
keepout.plot()





Web design

[115]: web, sheet=build_web(design2, keepout, support_width, jig_diameter, jig_hole_spacing, is_adhesive) web.plot()




[116]: sheet.plot()







Support design




[119]: #Calculate the web by using only the material which can be cut, minus a gapudetermined by the support width. Is that the only material you can use? supported_design = web|design2|support supported_design.plot()



```
[120]: #cut_line = keepout << kerf
cut_material = (keepout << kerf) - keepout
cut_material.plot()</pre>
```




```
[121]: final_cut = sheet - keepout
final_cut = final_cut[0]
final_cut.plot()
```





Full cutsheet


[122]: remaining_material = supported_design-cut_material
 remaining_material.plot()
 #make dxf here





Connection check







































































































































```
[124]: d3=design2>>1
    for item in remaining_parts:
        if not (item&d3).is_null():
            break
    check = (item^design2)
    print(check.is_null())
```


False

```
[59]: w,h = supported_design.get_dimensions()
p0,p1 = supported_design.bounding_box_coords()

rigid_layer = supported_design[0] | (supported_design[-1].translate(w+10,0))
rigid_layer.plot()
```



```
[60]: 14 = supported_design[3].scale(-1,1)
p2,p3 = 14.bounding_box_coords()
14 = 14.translate(p0[0]-p2[0]+10+w,p0[1]-p2[1])
adhesive_layer = supported_design[1] | 14
adhesive_layer.plot()
```



```
[61]: first_pass = Laminate(rigid_layer,adhesive_layer,supported_design[2])
    if check.is_null():
        first_pass.export_dxf('first_pass')
        final_cut.export_dxf('final_cut')


[62]: check.is_null()

[62]: False
    Exporting 5-layer DXFs:


[132]: rigid_layer.export_dxf('rigid_layer')
    adhesive_layer.export_dxf('adhesive_layer')
    final_cut.export_dxf('final_cut')
```

8 5 Final DXF files


Single layer DXF:




5-layer adhesive DXF:



5-layer rigid DXF:



5-layer final cut DXF:



[]: