

STANDARD OPERATING PROCEDURE
ELI LILLY AND COMPANY
North American Logistics Operations

Material Movement between Building 151 and the Plainfield Distribution Center

USD-SOP-Mtl Mvt btw 151 and PDC-001

SUPERSEDES	001-005187
PURPOSE	To establish the process for transferring approved finished and semi-finished product between Building 151 and the Plainfield Distribution Center (PDC).
AREAS INVOLVED	North American Logistics Operations (NALO) - Plainfield, NALO Quality Assurance, and Delivery Services
AREAS AFFECTED	Indy Device Assembly and Packaging
APPROVALS	Approval of this procedure requires the signature of: Management, NALO Operations (Plainfield) Management, Delivery Services Management, NALO Quality Assurance
*REFERENCES	Global Records Retention Schedule USD-SOP-Facility State Licensing-039 USD-SOP-Quarantine of Finished Products-001 USD-SOP-Segregation Process and Scrapped Mtl Processing-001 USD-SOP-Product Recpt at PDC-134 Lilly Quality System (LQS) Glossary
REASONS FOR REVISION	All revisions are marked with an (*): To remove reference to GBIP-00596, WM Receiving Production. • Rationale: It is not used in NALO.

DEFINITIONS

Controlled Room Temperature – See the LQS Glossary

Chill Room (e.g., Refrigerator) – A cold place in which the temperature is maintained thermostatically between 2° and 8° C (36° and 46° F).

**RULES &
RESTRICTIONS
FOR MOVEMENT
OF MATERIAL**

1. Materials must be moved on temperature-controlled trucks with refrigeration unit on trailer setpoint at 42 degrees Fahrenheit continuous mode for all product. A setpoint of 70 degrees Fahrenheit may be used for loads containing CRT products only.
 2. Material must be placed on pallets that have a designation indicating they have been heat treated in accordance with ISPM 15 (International Standards for Phytosanitary Measures No. 15) requirements for pallet treatment ("HT" for heat treatment) and secured for shipping (banding, shrink wrap) prior to moving material to appropriate staging area.
 3. Vault material must be capped and strapped, or stretch wrapped (w/opaque wrap) and must bear no external markings identifying the contents as Special Security Substances.
 4. Miscellaneous items may be shipped on the same truck with the approved finished drug product providing :
 - Space is available on the truck
 - The item being transported has a completed Physical Transfer Form attached
 - The item being transported does not pose a risk to the rest of the load.
-

**MATERIAL
ARRIVAL AT PDC**

Note: All steps are performed by PDC personnel unless noted otherwise.

Note: Driver contacts Dispatcher if truck is staged at PDC prior to seal being broken and Dispatcher provides tracking number and notifies monitoring firm of staging.

Step	Action
1	Upon arrival, verify the Seal Number on the Bill of Lading matches the truck seal. Verify that the seal is intact. If it is not intact, notify NALO Quality Assurance.
2	Driver contacts Dispatcher upon the seal being broken upon arrival.
3	Dispatcher contacts monitoring firm and notifies them of trip completion.
4	PDC personnel and/or Delivery Services personnel unload the material at PDC dock.
5	Visually examine each pallet and contents of partial cases to ensure that product, containers, labeling are not suspected of being damaged, adulterated, misbranded, counterfeited, contraband, or otherwise unfit for distribution. • If there is evidence of adulteration, misbranding, counterfeiting or suspicion of counterfeiting, notify NALO QA immediately. NALO QA will immediately impound the product in accordance with USD-SOP-Quarantine of Finished Products-001 and perform notifications as required by USD-SOP-Facility State Licensing-039. • If product is damaged or the sealed outer and/or secondary containers have been opened or used, but there is no adulteration, misbranding, counterfeiting or suspicion of counterfeiting, notify NALO QA. The product may either be scrapped immediately per USD-SOP-Segregation Process and Scrapped Mtl Processing-001 or impounded per USD-SOP-Quarantine of Finished Products-001.
*6	Perform receipt processing in accordance with USD-SOP-Product Recpt at PDC-134.
7	After receipt processing is complete, turn over contents of Distribution Receipt and/or packlist to NALO QA.

**RETURNING MATERIAL TO
BUILDING 151 FROM PDC****Note:** All steps are performed by PDC personnel unless noted otherwise.

Step	Action
1	Identify the material, batch, and quantity to be returned.
2	Schedule a temperature-controlled truck through Delivery Services (317-276-7765).
3	Ensure refrigeration unit on trailer setpoint is 42 degrees Fahrenheit continuous mode for all product. A setpoint of 70 degrees Fahrenheit may be used for loads containing CRT products only.
4	Notify QA personnel to move the batch to Restricted Stock using SAP transaction MSC2N.
5	Use Transaction VLMOVE and the following Movement Types: • Movement type 303 for Domestic material or • Movement type 313 for Export material. Enter material, batch, source plant, and storage location. Note: If product that has not been PGR at PDC needs to be sent back to 151 due to a quality reason, ensure it is sent back on a Physical Transfer Form.
6	Click on the "Target Mat. Entry" tab. Enter the destination plant and destination storage type. Plants for domestic VLMOVES are, 0004, 0314, 0413 or 0350. If the material is Export, the plant is the same as the source plant. Hit "Enter". Enter the quantity to be shipped. Click on "Create Delivery" button. Note the delivery number. Go to VL03N and enter delivery number. Ensure the ship to address and quantities are correct. Wave, pick and pack the outbound delivery *in EWM. • For serialized products ○ Execute transaction *EWM RF Menu Management – Select Outbound ○ *EWM RF Pick and Pack by Warehouse Order. Note: Once the outbound is "goods issued", it will automatically create an inbound delivery for the receiving site.
7	Obtain an Information Shipment Envelope and ensure the following is recorded on the envelope: • Date • Time • Seal # • Outbound Delivery # • Refrigeration unit is set at XX degrees Fahrenheit (per above Step) • Initial/Date
8	PDC personnel and/or Delivery Services personnel load the material on the truck.
9	Attach Information Shipment Envelope to the last pallet in the truck. Complete the Bill of Lading.
10	Shut the door and attach the security seal.
11	Initiate load with the security firm monitoring the truck.
12	Post Goods Issue the deliveries that were loaded into the trailer.

Document Approval Signatures

Approved Date: 14 Jan 2025

Approval Verdict: Approve	Brandon Bowler (L004253@lilly.com) Approver 06-Jan-2025 17:54:44 GMT+0000
Approval Verdict: Approve	Kelly Taylor (RZ38640@lilly.com) Quality Approver 07-Jan-2025 18:39:20 GMT+0000
Approval Verdict: Approve	Cory Andrews (SIX0701@lilly.com) Approver 14-Jan-2025 15:42:01 GMT+0000
Reviewer / Approver Additional Details	N/A