

Global Quality Required Tool GSOP-104-1-TL-5		
Version Number	Intracompany Issues	Associated Procedure
2		GSOP-104-1
Superseded Document		Page 1 of 3
GSOP-104-1-TL-5, v1		

Purpose

This global required tool describes the process and management of Intracompany Issues (ICIs) within the Quality Incident module in the Global Deviation Database (GDD).

Scope

In Scope

Issues between sites which require an assessment to determine if a deviation is required to investigate the identified issues.

Out of Scope

Communication of market complaints or issues discovered during distribution of finished products or devices are out of scope. When the issue meets the definition of a deviation or impacts batches, the deviation process must be used. ICI is not to be used for investigation, batch impact management, root cause, or CAPA.

Table of Contents

1.0	Overview of the ICI Process.....	2
2.0	Create and Assign the ICI	2
3.0	Perform the ICI Assessments	3
	Revision History	3



Global Quality Required Tool GSOP-104-1-TL-5		
Version Number	Intracompany Issues	Associated Procedure
2		GSOP-104-1
Superseded Document		Page 2 of 3
GSOP-104-1-TL-5, v1		

1.0 Overview of the ICI Process

ICIs are assessments performed between sites/functions within the enterprise which allow for triaging to determine if the issue in question requires further investigation by means of a deviation record. The site/function personnel who identifies the ICI will create the ICI record and assign the representatives to the other site/area involved so that an assessment of the issue and appropriate next steps are performed.

If a deviation is identified, the deviation process will be followed to investigate and identify the root cause of the issue.

2.0 Create and Assign the ICI

Step	Activity	Related Information	Responsible
1	Create the ICI	Create the ICI record from the Organization Level 1 who discovered the issue in question. Include pictures or other attachments as needed to support the written description of the issue. Create an ICI record within one (1) working day of identifying the issue which requires assessment. ICI records are automatically given a two (2) calendar day due date from the date of creation to ensure that deviation initiation occurs in a timely manner when a deviation is required.	Initiator
2	Batch is Impacted	Condition: An ICI has already been created. No batch object exists on ICI, so to flag a potential deviation in SAP, the deviation module must be used. Complete the missing information in the ICI and send it for assessment. Send a request to the assessor to complete the assessment with a new deviation if required per section 3.0, Step 4.	Initiator
3	Identify Areas/ Sites Involved	Identify Triaging Organizational Level 1, which is the site/function that is responsible for conducting the ICI assessment. Include additional organizational levels of the triage site/area, as needed.	Initiator
4	Assign the ICI Team	Assign the Team members who will conduct the assessment (for example, triage) and determine if a deviation is required.	Initiator
5	Review the ICI Record	Review the record for completeness and accuracy. Provide updates to the record, as needed. Include pictures or other attachments as needed to support the written description of the issue.	Owner

Global Quality Required Tool GSOP-104-1-TL-5			
Version Number	Intracompany Issues	Associated Procedure	
2		GSOP-104-1	
Superseded Document		Page 3 of 3	
GSOP-104-1-TL-5, v1			

3.0 Perform the ICI Assessments

Step	Activity	Related Information	Responsible
1	Complete the ICI Assessment	Review the ICI record and provide the assessment outcome (decision), including rationale, for the issue to confirm if it meets the definition of a deviation. Select the option to reflect if a quality event is required or not.	Assessor
2	Request Additional Information	Condition: ICI Record is not complete or more information is required to perform the assessment Select that additional information is required for the record so that the record can be returned to the record Owner to complete or provide the information as requested.	Assessor
3	Complete the Assessment with no Quality Event Required	Condition: No quality event is required from the ICI assessment Confirm the completion of the assessment and that the issue does not meet the definition of a deviation. The record is returned to the Owner to review the outcome and to either send back to the assessor or close the record.	Assessor, Owner
4	Complete the Assessment with a Deviation Required	Condition: A deviation is required from the ICI assessment Confirm the completion of the assessment, that the issue meets the definition of a deviation, and that a deviation is required. Indicate if a deviation is already in progress to relate to the ICI record and relate the deviation to the ICI record. Where no deviation is in progress, a deviation is automatically created. The Owner is assigned as the Fact-Finder of the created deviation. Refer to global procedures GSOP-104-1, Record Creation and Fact Finding , and GSOP-104-1-TL-2, Multi-Track Deviations .	Assessor, Owner

Revision History

Version Number	Effective Date	List of Major Changes
2	Effective date viewable in eDMS.	Updated Section 2.0, Step 2, to clarify that when the situation has a possible impact to batch(es), the deviation process must be followed.
1	14-Jul-2025	First version of this global quality required tool.

Document Approval Signatures

Approved Date: 10 Nov 2025

Approval Verdict: Approve	Ciara Keohane (C206691@lilly.com) Quality Approver 04-Nov-2025 15:48:44 GMT+0000
Approval Verdict: Approve	Thomas Davey (L108497@lilly.com) Quality Approver 11-Nov-2025 00:22:37 GMT+0000
Reviewer / Approver Additional Details	N/A