ሦ master ▼

...

advisories / CVEs / CVE-2021-40150.txt

MrTuxracer Add CVE-2021-40150

At 1 contributor

```
83 lines (61 sloc) | 2.67 KB
                                                                                                                                                                               ...
      RCE Security Advisory
      https://www.rcesecurity.com
     1. ADVISORY INFORMATION
      -----
                      Reolink E1 Zoom Camera
     Product:
      Vendor URL:
                     https://reolink.com/product/e1-zoom/
                      Exposure of Sensitive Information to an Unauthorized Actor [CWE-200]
      Date found:
                      2021-08-26
 11
     Date published: 2022-06-01
      CVSSv3 Score: 5.3 (CVSS:3.0/AV:N/AC:L/PR:N/UI:N/S:U/C:L/I:N/A:N)
 12
                    CVE-2021-40150
     CVE:
 13
 14
      2. CREDITS
 17
      This vulnerability was discovered and researched by Julien Ahrens from
 18
 19
      RCE Security.
 20
 21
      3. VERSIONS AFFECTED
 23
 24
      Reolink E1 Zoom Camera 3.0.0.716 (latest) and below
 25
 26
 27
      4. INTRODUCTION
      Meet new generation of Reolink E1 series. Advanced features - 5MP Super HD
      & optical zoom are added into this compact camera. Plus two-way audio, remote
 31
      live view and more smart capacities help you connect with what you care. Be
 32
      closer to families and be away from worries.
 33
 34
      (from the vendor's homepage)
 36
 37
     5. VULNERABILITY DETAILS
 38
      The web server of the E1 Zoom camera through 3.0.0.716 discloses its configuration
 39
      via the /conf/ directory that is mapped to a publicly accessible path.
      An unauthenticated attacker can abuse this with network-level access to
 43
      the camera to download the entire NGINX/FastCGI configurations by querying, i.e.:
 44
      http://[CAM-IP1/conf/nginx.conf
 45
      http://[CAM-IP]/conf/fastcgi.conf
 46
 48
 49
 50
 51
      6. RISK
 52
      An unauthenticated attacker can download the webserver's configuration
      files which might lead to sensitive information disclosure.
 56
 57
     7. SOLUTION
 58
      -----
 59
      None.
 61
 62
     8. REPORT TIMELINE
 63
     2021-08-26: Discovery of the vulnerability
 64
      2021-08-26: Sent notification to Reolink via their support channel
 65
      2021-08-26: Response from vendor asking for vulnerability details
      2021-08-26: Sent all the vulnerability details
      2021-08-31: Vendor is still looking into the issue
 69
      2021-09-03: Vendor states that the issue will be fixed with the next firmware update by the end of September.
 70
      2021-10-01: Since no firmware has been released, we've sent another notification
      2021-10-02: Vendor states that the new firmware is delayed
 71
      2022-02-01: Since there is still fix, sent another notification
      2022-02-02: Vendor states that the firmware with the fix hasn't been released yet.
      2022-03-03: Since there is still fix, sent another notification
 75
      2022-03-12: Vendor states they're still working on the issue (internal update awaits testing)
 76
      2022-05-24: Since there is still fix, sent another notification
      2022-05-24: Vendor states that the update still hasn't been released yet.
     2022-06-01: Almost a year should be enough to fix this. Public disclosure.
```