


About Services Events Securit

# Galleon N15-6002-GPS Command Injection

неіт 20 Мау 2022



# TL;DR

Galleon Systems' GPS NTP time server had a command injection vulnerability in the firmware of their NTS GPS device which could allow total control of the device through the web management interface.

### The vulnerability – CVE-2022-27224

https://cve.mitre.org/cgi-bin/cvename.cgi?name=CVE-2022-27224

Device: Galleon NTS-6002-GPS

# Categories

Show all

See the other cool stuff we've been doing...

Hive Ransom ware is on the rise. How should you deal with it?

INTERNE T OF THINGS Effectin g positive change in the Internet SOCIAL ENGINEE RING
Social Enginee ring dos and don'ts

2022





About Services Events Securit



Moto E20 Readba ck Vulnera bility 19 OCT 2022 MS
Enterpr
ise app
manage
ment
service
RCE.
CVE202235841
13 OCT
2022

### Summary

A vulnerability was discovered in Galleon NTS-6002-GPS 4.14.103-Galleon-NTS-6002.V12 #4. A low privilege authenticated attacker can perform command injection as the root user, by supplying shell metacharacters to forms on the Network Tools section of the webmanagement interface. All three networking tools are affected (Ping, Traceroute, and DNS Lookup) and their respective input fields (ping\_address, trace\_address, nslookup\_address).

In the examples below, we are targeting one of the three vulnerable pages (in this case DNS Lookup). The vulnerable endpoint is "/tools/dolookup" and the parameter "nslookup\_address".

Example commands used to enumerate and perform command injection via the pages and injectable page parameters mentioned above ("buffer" is a chosen random input word expected by the application):

**SERVICES** 

Penetration Testing

Find out more »

Our People



+44


0500 +1 • 646 693

2501

#### About Services Events Securit

buffer&id&pwd&ls;

PENTEST PARTNERS
Security consulting and testing services



is über technical, but faceless relationships do nobody any good. **Meet the team** »

# Exploitation

The underlying system did not allow some characters to be passed, these can be worked around using shell facilities. We can avoid the use of spaces by using the IFS shell variable (Input Field Separator):

buffer&cat\${IFS}index.php








Forward slashes "/" were also not accepted. In bash these can be replicated by using variable substitution, such as \${HOME:0:1}. This extracts the first character for the HOME shell variables, which, as the variable is a full path, is equal to the "/" character. With these substitutions we can submit most shell commands, such as:

buffer&cat\${IFS}\${HOME:0:1}etc\${HO
ME:0:1}passwd

buffer&cat\${IFS}\${HOME:0:1}etc\${HO
ME:0:1}shadow

The final command injection string gets the local Un\*x system's password hash file. This is only accessible with "root" level privileges on the device, and therefore highlights another issue of the web management UI server being run via the "root" administrative account rather than a more sensible choice such as "www-var" or "apache".



#### Disclosure timeline

- Nov 21 Initial disclosure to Galleon Systems
- Jan 22 Acceptance of part of the vulnerability
- Jan 22 Vendor started the vulnerability registration (CVE ID request dropped by MITRE due to failure by Galleon to provide additional information)
- Mar 22 I disclosed the vulnerability to MITRE myself
- May 22 MITRE acknowledged the vulnerability CVE ID provided

### Background

I found the vulnerability almost accidentally while doing other work. Wanting a change of focus I explored the web admin UI looking for basic vulnerabilities. Much to my surprise I found this device to be vulnerable.

# Realistic impact

Command injection on a GPS powered NTP device could in theory be quite devastating. Once "root" level privileged command execution is gained on the device, an attacker could gain control over the network time which could interfere with the Kerberos authentication protocol. This would be compounded if no backup NTP source is available.



# Mitigations

At the time of writing the vendor was working on releasing a newer iteration of the device's software which would patch the identified security issues. However it has not yet been released, and to the best our knowledge the update has not been tested or verified.

- While waiting for a vendor software patch, these devices should be properly restricted with firewalls at a host and / or network level in a manner that would only allow for IT management devices to authenticate to the device.
- Further, ensure the device is making use of a suitably complex and unique password so that an attacker could not trivially guess the password to the device's web admin UI.
- Ensure that more than one high tier NTP source is used to provide time for the network.

### Disclosure challenges

The vendor attempted to deny that the webserver was running with "root" privileges. Here's what they said to us:



About Services Events Securit

Furthermore, as seen in the screenshots above, it was possible to retrieve the "/etc/shadow" hash file that is typically only accessible by the "root" account or an account with delegated "root" privileges (e.g SUID).

#### References

- https://github.com/swisskyrepo/PayloadsAllTheThin gs/tree/master/Command%20Injection
- https://cve.mitre.org/cgi-bin/cvename.cgi? name=CVE-2022-27224











Securit y Consut ing



Papa -PTP Advanc e Passwo rd Audito r

Get in touch Connect





Services About Events Securit

























Privacy Policy

Terms of Service

Company number: OC353362

VAT reg number: GB825526427

© 2022 Pen Test **Partners**