Products

[[| [next>] [<thread-prev] [thread-next>] [day] [month] [year] [list]

What's new

Services

Publications

Resources

Hash Suite - Windows password security audit tool. GUI, reports in PDF.

```
Date: Sun, 5 Jun 2022 21:10:06 +0200
From: Salvatore Bonaccorso <carnil@...ian.org>
To: oss-security@...ts.openwall.com
Cc: solar@...nwall.com
Subject: Re: Linux kernel: UAF, null-ptr-deref and double-free
vulnerabilities in nfcmrvl module
Hi,
On Sun, Jun 05, 2022 at 09:14:00PM +0800, duoming@....edu.cn wrote:
> Hello there,
> There are double-free, use-after-free(write, read), null-ptr-deref vulnerabilities
> in drivers/nfc/nfcmrvl of linux that allow attacker to crash linux kernel by simulating
> nfc device from user-space.
> =*=*=*=*=*=*=*= Bug Details =*=*=*=*=*=*=
> There are destructive operations such as nfcmrvl_fw_dnld_abort and
> gpio free in nfcmrvl nci unregister dev. The resources such as firmware,
> gpio and so on could be destructed while the upper layer functions such as
> nfcmrvl fw dnld start and nfcmrvl nci recv frame is executing, which leads
> to double-free, use-after-free and null-ptr-deref bugs.
> There are three situations that could lead to double-free bugs.
> The first situation is shown below:
     (Thread 1)
                                       (Thread 2)
> nfcmrvl_fw_dnld_start
                                  nfcmrvl nci unregister dev
  release firmware()
                                  nfcmrvl_fw_dnld_abort
   kfree(fw) //(1)
                                    fw dnld over
                                     release firmware
                                      kfree(fw) //(2)
> The second situation is shown below:
                                       (Thread 2)
    (Thread 1)
> nfcmrvl_fw_dnld_start
 mod timer
  (wait a time)
  fw_dnld_timeout
                                 nfcmrvl_nci_unregister_dev
                                  nfcmrvl_fw_dnld_abort
   fw dnld over
     release_firmware
                                   fw dnld over
                                     release firmware
      kfree(fw) //(1)
                                      kfree(fw) //(2)
> The third situation is shown below:
                                         (Thread 2)
        (Thread 1)
> nfcmrvl_nci_recv_frame
  if(..->fw download in progress) |
   nfcmrvl_fw_dnld_recv_frame
    queue_work
> fw dnld rx work
                                  | nfcmrvl_nci_unregister_dev
  fw dnld over
                                  | nfcmrvl_fw_dnld_abort
                                     fw dnld over
   release firmware
    kfree(fw) //(1)
                                      release firmware
                                       kfree(fw) //(2)
```

> The firmware struct is deallocated in position (1) and deallocated

```
> in position (2) again.
> What's more, there are also use-after-free and null-ptr-deref bugs
> in nfcmrvl fw dnld start.
> One of the use-after-free bugs about firmware is shown below:
    (Use Thread)
                                        (Free Thread )
> nfcmrvl fw dnld start
                                    nfcmrvl nci unregister dev
                                     nfcmrvl fw dnld abort
                                      fw dnld over
                                      release firmware
                                       kfree(fw) //(1)
   priv->fw dnld.fw->data;//(2)|
> One of the use-after-free bugs about gpio is shown below:
    (Use Thread)
                                         (Free Thread )
> nfcmrvl fw dnld start
                                    nfcmrvl nci unregister dev
                                     gpio free //(1)
   nfcmrvl_chip_reset
    gpio_set_value //(2)
> One of the null-ptr-deref bugs about firmware is shown below:
    (Use Thread)
                                        (Free Thread )
> nfcmrvl fw dnld start
                                    nfcmrvl_nci_unregister_dev
                                    nfcmrvl_fw_dnld_abort
                                      fw dnld over
                                       priv->fw dnld.fw = NULL;//(1)
   priv->fw dnld.fw->data;//(2)|
> If we deallocate firmware struct, gpio or set null to the members of priv->fw dnld
> in position(1), then, we dereference firmware, gpio or the members of priv->fw dnld
> in position(2), the UAF or NPD bugs will happen.
> =*=*=*=*=*=*=*= Bug Effects =*=*=*=*=*=*=
> We can successfully trigger the vulnerabilities to crash the linux kernel.
> (1) One of the backtraces caused by use-after-free(write) bug is shown below.
> [ 138.280382] BUG: KASAN: use-after-free in request firmware+0x52/0x690
 [ 138.280382] Write of size 8 at addr ffff88\overline{8}00c1148\overline{5}0 by task download/11174
 [ 138.280382] Call Trace:
[ 138.280382] <TASK>
> [ 138.280382] dump_stack_lv1+0x57/0x7d
> [ 138.280382] print report.cold+0x5e/0x5db
> [ 138.280382] ? request firmware+0x52/0x690
> [ 138.280382] kasan_report+0xbe/0x1c0
> [ 138.280382] ? _request_firmware+0x52/0x690
 [ 138.280382] _request_firmware+0x52/0x690
[ 138.280382] request_firmware+0x2d/0x50
> [ 138.280382] nfcmrvl fw dnld start+0x7a/0xb0
> [ 138.280382] nfc_fw_download+0x92/0xe0
> [ 138.280382] nfc genl fw download+0x10b/0x170
> [ 138.280382] ? nfc_genl_enable_se+0xa0/0xa0
 [ 138.280382] ? __kasan_slab_alloc+0x2c/0x80
[ 138.280382] ? __nla_parse+0x22/0x30
> [ 138.280382] ? genl_family_rcv_msg_attrs_parse.constprop.0+0xd3/0x130
> [ 138.280382] genl_family_rcv_msg_doit+0x17a/0x200
> [ 138.280382] ? genl_family_rcv_msg_attrs_parse.constprop.0+0x130/0x130
> [ 138.280382] ? mutex_lock_io_nested+0xb63/0xbd0
> [ 138.280382] ? security_capable+0x48/0x60
> [ 138.280382] genl_rcv_msg+0x18d/0x2c0
> [ 138.280382] ? genl_get_cmd+0x1b0/0x1b0
> [ 138.280382] ? rcu_read_lock_sched_held+0xd/0x70
> [ 138.280382] ? nfc_genl_enable_se+0xa0/0xa0
> [ 138.280382] ? rcu read lock sched held+0xd/0x70
> [ 138.280382] ? lock acquire+0xce/0x410
```

```
> [ 138.280382] netlink_rcv_skb+0xc4/0x1f0
> [ 138.280382] ? genl_get_cmd+0x1b0/0x1b0
> [ 138.280382] ? netlink_ack+0x4d0/0x4d0
> [ 138.280382] ? netlink deliver tap+0xf7/0x5a0
> [ 138.280382] genl_rcv+0x1f/0x30
> [ 138.280382] netlink unicast+0x2d8/0x420
> [ 138.280382] ? netlink_attachskb+0x430/0x430
> [ 138.280382] netlink_sendmsg+0x3a9/0x6e0
> [ 138.280382] ? netlink_unicast+0x420/0x420
> [ 138.280382] ? netlink_unicast+0x420/0x420
> [ 138.280382] sock_sendmsg+0x91/0xa0
                     __sys_sendto+0x168/0x200
> [ 138.280382]
> [ 138.280382] ? ia32 sys getpeername+0x40/0x40
> [ 138.280382] ? preempt_count_sub+0xf/0xb0
> [ 138.280382] ? fd_install+0xfb/0x340
> [ 138.280382]
> [ 138.280382]
                   ? __sys_socket+0xf0/0x160
? x64 sys clock nanosle
                        x64 sys clock nanosleep+0x195/0x220
> [ 138.280382] ? compat_sock_ioctl+0x410/0x410
> [ 138.280382]
                      _x64_sys_sendto+0x6f/0x80
> [ 138.280382] do syscall 64+0x3b/0x90
> [ 138.280382] entry_SYSCALL_64_after_hwframe+0x44/0xae
> [ 138.280382] RIP: 0033:0x7ff12ac0602c
> [ 138.280382] Code: 0a f8 ff ff 44 8b 4c 24 2c 4c 8b 44 24 20 89 c5 44 8b 54 2b > [ 138.280382] RSP: 002b:00007ff12aalee00 EFLAGS: 00000293 ORIG_RAX: 0000000000c
> [ 138.280382] RAX: fffffffffffffda RBX: 00000000000000 RCX: 00007ff12ac0602c
> [ 138.280382] RDX: 00000000000002c RSI: 000055eab88030b0 RDI: 000000000000000
> [ 138.280382] RBP: 0000000000000000 R08: 00007ff12aa1ee7c R09: 000000000000000
> [ 138.280382] R10: 000000000000000 R11: 000000000000293 R12: 00007ffca74ba00e
> [ 138.280382] R13: 00007ffca74ba00f R14: 00007ff12aalefc0 R15: 00007ff12aa1f700
> (2) One of the backtraces caused by use-after-free(read) bug is shown below.
> [
       65.835462] BUG: KASAN: use-after-free in nci fw download+0x26/0x60
> [
       65.840236] Read of size 8 at addr ffff88800c2f5008 by task download/160
> [
       65.845755] Call Trace:
      65.845755] <TASK>
65.845755] dump_stack_lvl+0x57/0x7d
65.845755] print_report.cold+0x5e/0x5db
> [
> [
     65.845755] ? nci fw download+0x26/0x60
> [
       65.845755] kasan report+0xbe/0x1c0
> [
> [ 65.856061] ? nfc driver failure+0x90/0xa0
> [ 65.856235] ? nci_fw_download+0x26/0x60
      65.856235] nci_fw_download+0x26/0x60
65.856235] nfc_fw_download+0x99/0xe0
65.856235] nfc_genl_fw_download+0x10b/0x170
>
 [
     65.861189] ? nfc_genl_enable_se+0xa0/0xa0
> [
      65.861189] ? __kasan_slab_alloc+0x2c/0x80
65.861189] ? __nla_parse+0x22/0x30
> [
> [
> [ 65.865988] ? genl_family_rcv_msg_attrs_parse.constprop.0+0xd3/0x130
      65.865988] genl_family_rcv_msg_doit+0x17a/0x200
65.865988] ? genl_family_rcv_msg_attrs_parse.constprop.0+0x130/0x130
  [
     65.870892] ? asm_spurious_interrupt+0x3/0x30
> [
     65.870892] ? security capable+0x48/0x60
> [
     65.870892] genl rcv msg+0x18d/0x2c0
> [
> [
       65.870892] ? genl_get_cmd+0x1b0/0x1b0
> [
       65.870892] ? rcu_read_lock_sched_held+0xd/0x70
                   ? nfc_genl_enable_se+0xa0/0xa0
? rcu_read_lock_sched_held+0xd/0x70
  Γ
       65.875946]
       65.875946]
       65.875946] ? lock_acquire+0xce/0x410
> [
       65.875946] netlink_rcv_skb+0xc4/0x1f0
> [
       65.880842] ? genl get cmd+0x1b0/0x1b0
> [
       65.881778] ? netlink_ack+0x4d0/0x4d0
> [
       65.881778] ? netlink_deliver_tap+0xf7/0x5a0
       65.881778] genl_rcv+0x1f/0x30
65.881778] netlink_unicast+0x2d8/0x420
> [
      65.885734] ? netlink attachskb+0x430/0x430
> [
> [
      65.887472] netlink sendmsg+0x3a9/0x6e0
       65.887472] ? netlink_unicast+0x420/0x420
> [
       65.887472] ? netlink_unicast+0x420/0x420
> [
      ___.wsg+ux91/0xa0

bb.891949] __sys_sendto+0x168/0x200

65.893134] ?__ia32_svs_co---
       65.887472] sock_sendmsg+0x91/0xa0
                        _ia32_sys_getpeername+0x40/0x40
> [
       65.893134] ? lockdep_hardirqs_on_prepare+0xe/0x220
> [
       65.893134] ?
                        schedule+0x5c5/0x1180
> [
       65.893134] ? io schedule timeout+0xb0/0xb0
```

```
> [
     65.897936] ? clockevents_program_event+0xd3/0x130
      65.897936] ? hrtimer_interrupt+0x332/0x350
      65.897936]
                    x64 sys sendto+0x6f/0x80
      65.897936] do syscall 64+0x3b/0x90
      65.897936] entry SYSCALL 64 after_hwframe+0x44/0xae
> [
      65.902930] RIP: 0033:0x7f96173ec02c
      65.902930] Code: 0a f8 ff ff 44 8b 4c 24 2c 4c 8b 44 24 20 89 c5 44 8b 54 24 28 48 8b 54 24 18 b8 2c
00 00 00 48 8b 74 24 10 8b 7c 24 08 0f 05 <48> 3d 00 fb
> [
      65.908959] RSP: 002b:00007f9617204df0 EFLAGS: 00000293 ORIG RAX: 00000000000002c
      65.908959] RAX: fffffffffffffda RBX: 0000000000000 RCX: 00007f96173ec02c
      65.908959] RDX: 00000000000000034 RSI: 0000556fa2a030b0 RDI: 000000000000000
> [
      65.908959] RBP: 0000000000000000 R08: 00007f9617204e6c R09: 00000000000000c
      > [ 65.916990] R13: 00007ffde78477ef R14: 00007f9617204fc0 R15: 00007f9617205700
> (3) One of the backtraces caused by double-free bug is shown below.
> [ 122.640457] BUG: KASAN: double-free or invalid-free in fw_dnld_over+0x28/0xf0
> [ 122.640457] Call Trace:
> [ 122.640457] <TASK>
> [ 122.640457] dump stack lvl+0x57/0x7d
> [ 122.640457] print_report.cold+0x5e/0x5db
    122.640457] ? fw_dnld_over+0x28/0xf0
122.640457] ? fw_dnld_over+0x28/0xf0
 [
> [ 1re22.640457] kasan_report_invalid_free+0x90/0x180
> [ 122.640457] ? refcount warn saturate+0x40/0x110
> [ 122.640457] ? fw dnld \overline{\text{over}} + 0x28/0xf0
_kasan_slab_free+0x152/0x170
> [ 122.640457] fw dnld over+0x28/0xf0
> [ 122.640457] nfcmrvl_nci_unregister_dev+0x61/0x70
> [ 122.640457] nci_uart_tty_close+0x87/0xd0
> [ 122.640457] tty ldisc kill+0x3e/0x80
> [ 122.640457] tty_ldisc_hangup+0x1b2/0x2c0
> [ 122.640457]
                   tty hangup.part.0+0x316/0x520
    122.640457] ___ccy_nangup.parc.070x5
122.640457] tty release+0x200/0x670
> [ 122.640457]
> [ 122.640457] __fput+0x110/0x410
> [ 122.640457] ? _raw_spin_unlock_irq+0x1f/0x40
> [ 122.640457] task work run+0x86/0xd0
> [ 122.640457] exit_to_user_mode_prepare+0x1aa/0x1b0
> [ 122.640457] syscall_exit_to_user_mode+0x19/0x50
> [ 122.640457] do_syscall_64+0x48/0x90
> [ 122.640457] entry_SYSCALL_64_after_hwframe+0x44/0xae
> [ 122.640457] RIP: 0033:0x7f68433f6beb
> [ 122.640457] Code: 0f 05 48 3d 00 f0 ff ff 77 45 c3 0f 1f 40 00 48 83 ec 18 84
> [ 122.640457] RSP: 002b:00007f684320fee0 EFLAGS: 00000293 ORIG RAX: 00000000003
> [ 122.640457] RAX: 000000000000000 RBX: 0000000000000 RCX: 00007f68433f6beb
> [ 122.640457] RDX: 000000000000000 RSI: 0000000000000 RDI: 00000000000000
    122.640457] RBP: 00007f684320ff00 R08: 00000000000000 R09: 00007f6843210700
     122.640457] R10: 000000000000000 R11: 00000000000293 R12: 00007ffd5d6f9fde
> [ 122.640457] R13: 00007ffd5d6f9fdf R14: 00007f684320ffc0 R15: 00007f6843210700
> (4) One of the backtraces caused by null-ptr-deref bug is shown below.
> [
      80.495478] BUG: KASAN: null-ptr-deref in nfcmrvl fw dnld start.cold+0x19/0x276
      80.498745] Read of size 8 at addr 00000000000000 by task download/161
      80.502308] Call Trace:
      80.502308] <TASK>
> [
      80.502308] dump_stack_lv1+0x57/0x7d
> [
      80.502308] kasan report+0xbe/0x1c0
> [
      80.502308] ? nfcmrvl_fw_dnld_start.cold+0x19/0x276
     80.502308] nfcmrvl_fw_dnld_start.cold+0x19/0x276
80.508210] ? nfc_fw_download+0x79/0xe0
80.508210] nfc_fw_download+0x99/0xe0
> [
> [
      80.508210] nfc genl_fw_download+0x10b/0x170
> [
> [
      80.508210] ? nfc genl enable se+0xa0/0xa0
      80.508210] ? __kasan_slab_alloc+0x2c/0x80
80.508210] ? __nla_parse+0x22/0x30
> [
> [
      80.508210]
                 ? genl_family_rcv_msg_attrs_parse.constprop.0+0xd3/0x130
                 genl family rcv msg doit+0x17a/0x200
      80.5082101
                  ? genl_family_rcv_msg_attrs_parse.constprop.0+0x130/0x130
      80.508210]
      80.513085] ? mutex_lock_io_nested+0xb43/0xbd0
> [
> [
      80.513085] ? security capable+0x48/0x60
      80.513085] genl rcv msg+0x18d/0x2c0
```

```
> [
      80.513085] ? genl_get_cmd+0x1b0/0x1b0
     80.513085] ? rcu_read_lock_sched_held+0xd/0x70
80.513085] ? nfc_genl_enable_se+0xa0/0xa0
80.513085] ? rcu_read_lock_sched_held+0xd/0x70
> [ 80.513085] ? lock acquire+0xce/0x410
> [ 80.513085] netlink rcv skb+0xc4/0x1f0
> [ 80.513085] ? genl_get_cmd+0x1b0/0x1b0
> [
     80.518420] ? netlink_ack+0x4d0/0x4d0
> [
      80.518420] ? netlink_deliver_tap+0xf7/0x5a0
     80.518420] genl_rcv+0x1f/0x30
80.518420] netlink_unicast+0x2d8/0x420
> [
> [
      80.518420] ? netlink attachskb+0x430/0x430
> [
      80.518420] netlink sendmsg+0x3a9/0x6e0
> [
> [
      80.518420] ? netlink_unicast+0x420/0x420
> [
      80.518420] ? netlink_unicast+0x420/0x420
 [
      80.518420] sock_sendmsg+0x91/0xa0
> [
      80.518420]
                   sys sendto+0x168/0x200
      80.523005] ?
> [
                     ia32 sys getpeername+0x40/0x40
      80.523005] ? preempt_count_sub+0xf/0xb0
> [
> [ 80.523005] ? fd install+0xfb/0x340
     80.523005] ? __sys_socket+0xf0/0x160
> [
> [
     80.523005] ? compat_sock_ioctl+0x410/0x410
      80.523005]
                   _x64_sys_sendto+0x6f/0x80
 [
     80.523005] __x64_sys_sendto+0x6f/0
80.523005] do_syscall_64+0x3b/0x90
> [
> [
     80.523005] entry SYSCALL 64 after hwframe+0x44/0xae
> [
      80.523005] RIP: 0033:0x7f30f54f402c
> [
     80.523005] Code: 0a f8 ff ff 44 8b 4c 24 2c 4c 8b 44 24 20 89 c5 44 8b 54 24 28 48 8b 54 24 18 b8 2b
      80.528021] RSP: 002b:00007f30f530cdf0 EFLAGS: 00000293 ORIG RAX: 00000000000002c
> [
> [
      80.528021] RAX: fffffffffffffda RBX: 0000000000000 RCX: 00007f30f54f402c
      80.528021] RDX: 0000000000000034 RSI: 00005571766030b0 RDI: 000000000000005
      80.533650] RBP: 0000000000000000 R08: 00007f30f530ce6c R09: 00000000000000
      ] <
      80.533650] R13: 00007ffd9c6c6cef R14: 00007f30f530cfc0 R15: 00007f30f530d700
> [
> =*=*=*=*=*=*=*= Bug Fix =*=*=*=*=*=*=
> The patch that have been applied to mainline Linux kernel is shown below.
> https://github.com/torvalds/linux/commit/d270453a0d9ec10bb8a802a142fb1b3601a83098
> =*=*=*=*=*=*=*= Timeline =*=*=*=*=*=*=*=
> 2022-05-01: commit d270453a0d9e accepted to mainline kernel
> 2022-06-05: send an email to secalert@...hat.com in order to request CVE number
> =*=*=*=*=*=*=*= Credit =*=*=*=*=*=*=
> Duoming Zhou <duoming@....edu.cn>
According to https://bugzilla.redhat.com/show bug.cgi?id=2086766 this
should be CVE-2022-1734.
Regards,
```

## Powered by blists - more mailing lists

Please check out the Open Source Software Security Wiki, which is counterpart to this mailing list.

Confused about mailing lists and their use? Read about mailing lists on Wikipedia and check out these guidelines on proper formatting of your messages.



Salvatore