tenda overflow vulnerability

```
vendor:Tenda
product:G1,G3
version:V15.11.0.17(9502)_CN(G1),
V15.11.0.17(9502)_CN(G3)
type:Buffer Overflow
author:Jinwen Zhou、Yifeng Li、Yongjie Zheng;
institution:potatso@scnu、feng@scnu、eifiz@scnu
```

Vulnerability description

We found a buffer overflow vulnerability in Tenda Technology Tenda's **G1 and G3** routers with firmware which was released recently, allows remote attackers to execute arbitrary code from a crafted GET request.

Buffer Overflow vulnerability

In **formDelPortMapping** function, the parameter **"portMappingIndex"** is directly **strcpy** to a local variable placed on the stack, which overrides the return address of the function, causing buffer overflow.

PoC

Buffer Overflow